

=====
*** Basic Information ***
=====

[Create date] 2017/10/11

[Program Name] Main

[Version] B13.1C

[PCB No.]

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Others

Exported to(language) GEN(all)

[Firmware No.] Y0AW5510A

[File Information]

File Name Y0AW5510A.exe

File Type Module for Service

Size 1.44 MB (1508040 byte)

Check Sum -8Bit Sum: 1858

 -16Bit Sum(Little Endian): 340C

 -16Bit Sum(Big Endian): 3C4C

[Availability of RFU] No

[Production reflection]

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

=====
*** Basic Information ***
=====

[Create date] 2017/10/11

[Program Name] Main

[Version] B13.1C

[PCB No.]

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Others

Exported to(language) GEN(all)

[Firmware No.] Y0AX5510A

[File Information]

File Name Y0AX5510A.exe

File Type Module for Service

Size 1.40 MB (1466147 byte)

Check Sum -8Bit Sum: 2CA3

 -16Bit Sum(Little Endian): 3E5A

 -16Bit Sum(Big Endian): 9149

[Availability of RFU] No

[Production reflection]

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

=====
*** Basic Information ***
=====

[Create date] 2018/10/26

[Program Name] Main

[Version] B14.2C

[PCB No.]

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Others

Exported to(language) GEN(all)

[Firmware No.] Y0AW5510B

[File Information]

File Name Y0AW5510B.exe

File Type Module for Service

Size 1.44 MB (1509590 byte)

Check Sum -8Bit Sum: B0E3

 -16Bit Sum(Little Endian): 1D5D

 -16Bit Sum(Big Endian): 7686

[Availability of RFU] No

[Production reflection]

=====
*** Note ***
=====

[Note]

1)Additional Model Information

None

2)Specification Change

Support Remote controller ID setup

3>Error Correction

None

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]
Rank C

Support Remote controller ID setup

[Modification history]

Version B13.1C
Symptom corrected:
- Seldom need press power button twice to turn on the projector.

Version B11.1C
1st release

=====
*** Basic Information ***
=====

[Create date] 2018/10/26

[Program Name] MCU

[Version] A50

[PCB No.]

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Others

Exported to(language) GEN(all)

[Firmware No.] Y0AW5512A

[File Information]

File Name Y0AW5512A.exe

File Type Module for Service

Size 0.19 MB (198273 byte)

Check Sum -8Bit Sum: CD13

-16Bit Sum(Little Endian): F7F5

-16Bit Sum(Big Endian): E81E

[Availability of RFU] No

[Production reflection]

=====
*** Note ***
=====

[Note]

1)Additional Model Information

None

2)Specification Change

Support Remote controller ID setup

3>Error Correction

None

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Basic Information ***
=====

[Create date] 2018/10/26

[Program Name] PIP

[Version] G60

[PCB No.]

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Others

Exported to(language) GEN(all)

[Firmware No.] Y0AW5513

[File Information]

File Name Y0AW5513.exe

File Type Module for Service

Size 0.62 MB (649171 byte)

Check Sum -8Bit Sum: 4A16

 -16Bit Sum(Little Endian): A3CE

 -16Bit Sum(Big Endian): BC48

[Availability of RFU] No

[Production reflection]

=====
*** Note ***
=====

[Note]

1)Additional Model Information

None

2)Specification Change

None

3)Error Correction

HDMI Output Range bug fixed

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***

=====
[Modifications made:]
Rank C

HDMI Output Range bug fixed

[Modification history]

=====
*** Modification History ***
=====

[Modifications made:]
Rank C

Support Remote controller ID setup

[Modification history]

Version A49
Bug fixed:
The EDID table can be modified by HDMI splitter in Standby mode.

=====
*** Basic Information ***
=====

[Create date] 2018/10/26

[Program Name] MCU Update

[Version] 1.4

[PCB No.]

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Others

Exported to(language) GEN(all)

[Firmware No.] Y0AW5522

[File Information]

File Name Y0AW5522.exe

File Type Module for Service

Size 0.72 MB (760071 byte)

Check Sum -8Bit Sum: 1517

 -16Bit Sum(Little Endian): B22E

 -16Bit Sum(Big Endian): 79E9

[Availability of RFU] No

[Production reflection]

=====
*** Note ***
=====

[Note]

ReadMe added

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]
Rank C

ReadMe added

[Modification history]

Version 1.4
Rank D

Initial release