

**Reissued: 27-Jan-16**

Model: <b>Altair-PJ1/ Altair-PJ2/Soleil-PJ2/Soleil-PJ2.5</b>	Date: 05-Feb-13	No.: RY024001c
--	-----------------	----------------

**RTB Reissue**

The items in ***bold italics*** have been corrected or added.

Subject: Release Note: FW Update		Prepared by: A. Iwaori	
From: VC Products Support Sec., Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware **FW Update Tool**.

Version	Program No.	Effective Date	Availability of RFU
1.3.0.0	Y0249101B	February 2015 production	Not available
1.1.0.0	Y0249101A	October 2013 production	Not available
1.0.0.0	Y0249101	Initial release	Not available

**Note: Definition of Availability of RFU via @Remote**
**"Available":** The firmware can be updated via RFU or SD card.

**"Not available":** The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
1.3.0.0	Additional Supported Model: Altair-PJ2 <b><i>Soleil-PJ2.5</i></b>
1.1.0.0	Additional Supported Model: Soleil-PJ2
1.0.0.0	This is a tool for updating the firmware for the main board on the following models only: Altair-PJ1  Important: This update tool can only be used on these models.

**Reissued: 12-Apr-16**

Model: <b>Soleil-PJ1a/Soleil-PJ1b/Soleil-PJ2/ Altair-PJ1/ Altair-PJ2/Soleil-PJ2.5</b>	Date: 19-Oct-12	No.: RY011003f
---	-----------------	----------------

**RTB Reissue**

The items in bold italics have been corrected.

Subject: Firmware Release Note: Backup Tool		Prepared by: A. Iwaori	
From: VC Products Support Sec., Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **Backup Tool**.

Version	Program No.	Effective Date	Availability of RFU
<b>1.7.0.0</b>	<b>Y0119100G</b>	-	<b>Not available</b>
1.6.0.0	Y0119100F	-	Not available
1.5.0.0	Y0119100E	-	Not available
1.4.0.0	Y0119100D	-	Not available
1.3.0.0	Y0119100C	-	Not available
1.2.0.0	Y0119100B	-	Not available
1.1.0.0	Y0119100A	-	Not available

**Note: Definition of Availability of RFU via @Remote**
**"Available":** The firmware can be updated via RFU or SD card.

**"Not available":** The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
<b>1.7.0.0</b>	<b>1) Additional Model Information</b> <b>None.</b>  <b>2) Specification Changes</b> <b>Able to obtain and display logs related to mercury bridge.</b>  <b>3) Error Corrections</b> <b>None.</b>
1.6.0.0	1) Additional Model Information The following projector is now supported: Soleil PJ2.5  2) Specification Changes None.  3) Error Corrections None.
1.5.0.0	Additional Model Information: - Altair PJ2 models have been added.  Specification Changes: The following functions have been added or changed for Altair PJ2:

**Reissued: 12-Apr-16**

Model: <b>Soleil-PJ1a/Soleil-PJ1b/Soleil-PJ2/ Altair-PJ1/ Altair-PJ2/Soleil-PJ2.5</b>		Date: 19-Oct-12	No.: RY011003f
Version	Modified Points or Symptom Corrected		
	<ul style="list-style-type: none"><li>- Added functionality for obtaining service status information (Service Status Tool).</li><li>- The tool automatically changes the projector's "Eco mode" settings to "Active stand-by mode" so that the tool can be executed without changing the setting in advance.</li></ul>		
1.4.0.0	Additional Supported Model: Soleil-PJ2		
1.3.0.0	Specification Change: Supports the Backup and Restore functions on the following versions of Altair-PJ1 firmware: Main: Ver. 1008220400 Network USB: Ver. 101300 ECO IO: Ver. 101400		
1.2.0.0	Additional Model Information: Support for the Altair-PJ1 was added.		
1.1.0.0	Initial release		

**Reissued: 27-Jan-16**

Model: <b>Soleil-PJ1a/ Soleil-PJ1b/ Soleil-PJ2/ Soleil-PJ2.5/Altair-PJ1/ Altair-PJ2</b>	Date: 21-Jul-12	No.: RY011004c
---	-----------------	----------------

**RTB Reissue**

The items in bold italics have been corrected or added.

Subject: Firmware Release Note: USB to UART Bridge Virtual COM Port driver		Prepared by: A. Iwaori	
From: VC Products Support Sec., Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Driver)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **USB to UART Bridge Virtual COM Port driver**.

Version	Program No.	Effective Date	Availability of RFU
1.0.0.0	Y0119102	-	Not available

**Note: Definition of Availability of RFU via @Remote**
**“Available”:** The firmware can be updated via RFU or SD card.

**“Not available”:** The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
1.0.0.0	<p><b><i>[Modifications made:]</i></b></p> <p><b><i>2015/02/02</i></b></p> <p><b><i>Additional support for Altair PJ2 has been included. No other changes have been made to the application.</i></b></p> <p><b><i>2016/01/20</i></b></p> <p><b><i>Additional support for Soleil PJ2.5 has been included. No other changes have been made to the application.</i></b></p> <p><b><i>---</i></b></p> <p>Initial Release</p>

Model: <b>Altair-PJ1/Altair-PJ2/Soleil-PJ1b/ Soleil-PJ2/Soleil-PJ2.5</b>	Date: 27-Jan-16	No.: RY011008
--	-----------------	---------------

Subject: Firmware Release Note: QuickPack		Prepared by: A. Iwaori	
From: VC Products Support Sec., Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **QuickPack**.

Version	Program No.	Effective Date	Availability of RFU
1001	PJSQPA_1001	-	Not available

**Note: Definition of Availability of RFU via @Remote**

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
1001	<p>1) Additional model information: Initial release.</p> <p>2) Specification changes: None.</p> <p>3) Error corrections: None.</p> <p>Remarks: QuickPack (Win. / Mac.) has been released via the following files.</p> <p>[Windows] QuickPack_WIN_V1000.zip Version: v1.0.0.0</p> <p>[Macintosh] QuickPack_MAC_V1102.zip Version: v1.1.0.2</p>