

Reissued: 12-Dec-14

Model: Altair-PJ1	Date: 22-Jan-13	No.: RY025001j
-------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been corrected or added.

Subject: Firmware Release Note: SYSTEM:XGA:ALT-1		Prepared by: T. Takahashi	
From: NA Support Sect, Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Other (Firmware)	<input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **SYSTEM:XGA:ALT-1**.

Note: This firmware correspond to Y025/Y028

Version	Program No.	Effective Date	Availability of RFU
<i>10142205-1017-1019</i>	<i>Y0255956N</i>	<i>December 2014 production</i>	<i>Not available</i>
10132205-1017-1019	Y0255956M	July 2014 production	Not available
10122205-1017-1019	Y0255956L	June 2014 production	Not available
10122205-1017-1018	Y0255956K	February 2014 production	Not available
10112205-1016-1017	Y0255956J	January 2014 production	Not available
10102205-1016-1017	Y0255956H	January 2014 production	Not available
10102205-1015-1016	Y0255956G	November 2013 production	Not available
10092205-1014-1015	Y0255956F	September 2013 production	Not available
10082204-1013-1014	Y0255956E	June 2013 production	Not available
10042203-1012-1012	Y0255956C	February 2013 production	Not available
10032202-1011-1010	Y0255956	Initial release	Not available

Note: Definition of Availability of RFU via @Remote

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
<i>10142205-1017-1019</i>	<p><i>1) Additional Model Information:</i> <i>N/A</i></p> <p><i>2) Specification Changes:</i> <i>N/A</i></p> <p><i>3) Error Corrections:</i> - <i>Automatic startup error when HDMI is connected.</i></p>
10132205-1017-1019	<p>Changes:</p> <p>1) New hardware support: None</p> <p>2) Specification changes: None</p> <p>3) Fixes:</p> <ul style="list-style-type: none"> - The display might be abnormal when the input is changed from "video" to "Network PC". - When the device is turned on, some previously set operations might not

Reissued: 12-Dec-14

Model: Altair-PJ1	Date: 22-Jan-13	No.: RY025001j
-------------------	-----------------	----------------

Version	Modified Points or Symptom Corrected
	be applied.
10122205-1017-1019	<p>Changes:</p> <ul style="list-style-type: none"> 1) New additional hardware: none 2) Specification changes: none 3) Fixes <ul style="list-style-type: none"> - If the device is turned on or in an energy-saving state for a long time, some operations might not be applied.
10122205-1017-1018	<ul style="list-style-type: none"> 1) Additional Model Information N/A 2) Specification Change N/A 3) Error Correction Improved the Interactive function.
10112205-1016-1017	<ul style="list-style-type: none"> 1) Additional Model Information N/A 2) Specification Change Improved picture quality when projecting over a network or from a USB drive. 3) Error Correction N/A
10102205-1016-1017	<ul style="list-style-type: none"> 1) Additional Model Information N/A 2) Specification Changes <ul style="list-style-type: none"> - Added the Quick Signage function. 3) Error Corrections <ul style="list-style-type: none"> - When projecting content from a USB drive, a black image is displayed for one second when Auto Demo starts. - System failure may occur when content is projected via DLNA and then switched to USB drive, and a thumbnail might appear and be inoperative. - A waiting screen appears when switching content that is being projected via DLNA.
10102205-1015-1016	<p>Error corrections:</p> <ul style="list-style-type: none"> - A network error occurs when the input signal is changed while a slideshow with a display effect is on. - A projection might not be able to restart after ad-hoc projection starts and ends. - QuickProjection fails to search for projectors when it is connected to a specific wireless LAN network. - Wireless LAN easy setup fails when a space is included in the SSID of the wireless LAN network. - Wireless LAN access connection while in Infrastructure mode fails to connect to a network that has multiple networks using the same SSID. - An error message appears during DMR projection.

Reissued: 12-Dec-14

Version	Modified Points or Symptom Corrected
10092205-1014-1015	Change specifications: <ul style="list-style-type: none">- Supports still images via DLNA.- Supports Web Image Monitor.
10082204-1013-1014	Symptom corrected: <ol style="list-style-type: none">1. Improved the touch response of the remote controller.2. A network board error occurs, which can only be cleared by rebooting the projector (removing/reinserting the power cord).3. Nothing is displayed if the user initiates a slide show just after booting up the projector. <p>Other changes:</p> <ol style="list-style-type: none">1. Added support for Crestron.2. Added support for AMX.3. Added support for UPnP.4. The aspect ratio doesn't change when using UPnP.
10042203-1012-1012	Fixed: <p>If WPA-PSK or WPA2-PSK is set to 27 characters or more and the user changes from Infrastructure mode to Adhoc mode, then a "Please wait" dialog appears and the system might become unresponsive. When the projector is restarted, the projected image is blacked out.</p>
10032202-1011-1010	Initial release

Reissued: 16-Dec-14

Model: Altair-PJ1	Date: 22-May-13	No.: RY025002f
-------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been corrected or added.

Subject: Firmware Release Note: MAIN:XGA:ALT-1		Prepared by: T. Takahashi	
From: NA Support Sect, Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Other (Firmware)	<input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **MAIN:XGA:ALT-1**.

Note: This firmware correspond to Y025/Y028

Version	Program No.	Effective Date	Availability of RFU
1014220500	Y0245951P	December 2014 production	Not available
1013220500	Y0245951N	July 2014 production	Not available
1012220500	Y0245951M	February 2014 production	Not available
1011220500	Y0245951L	January 2014 production	Not available
1010220500	Y0245951K	November 2013 production	Not available
1009220500	Y0245951J	September 2013 production	Not available
1008220400	Y0245951H	June 2013 production	Not available

Note: Definition of Availability of RFU via @Remote

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
1014220500	<p>1) Additional Model Information: N/A</p> <p>2) Specification Changes: N/A</p> <p>3) Error Corrections: - Automatic startup error when HDMI is connected.</p>
1013220500	<p>Changes:</p> <p>1) New hardware support: None</p> <p>2) Specification changes: None</p> <p>3) Fixes:</p> <ul style="list-style-type: none"> - The display might be abnormal when the input is changed from "video" to "Network PC". - When the device is turned on, some previously set operations might not be applied.

Reissued: 16-Dec-14

Model: Altair-PJ1	Date: 22-May-13	No.: RY025002f
-------------------	-----------------	----------------

Version	Modified Points or Symptom Corrected
1012220500	1) Additional Model Information N/A 2) Specification Change N/A 3) Error Correction Improved the Interactive function.
1011220500	1) Additional Model Information N/A 2) Specification Change Improved picture quality when projecting over a network or from a USB drive 3) Error Correction N/A
1010220500	1) Additional Model Information N/A 2) Specification Changes N/A 3) Error Corrections <ul style="list-style-type: none"> - Abnormal display of DMR projection. - The projector does not start up correctly after updating the firmware through @Remote when the device is powered off.
1009220500	1) Additional Model Information N/A 2) Specification Changes <ul style="list-style-type: none"> - Adjustments made to the subcontrast. - Change made to the default of the power off timer when there is no input signal. 3) Error Corrections <ul style="list-style-type: none"> - Unable to connect to the network when an error regarding the lamp not lighting up occurs at startup. - Frequent "Please wait" messages appear while in "Interactive ready (Point blank)" mode. - Input signal issue when an iPad is connected.
1008220400	Other changes: <ol style="list-style-type: none"> 1. Improved the touch response of the remote controller. 2. Added support for Crestron. 3. The aspect ratio doesn't change when using UPnP.