

Reissued: 23-Mar-16

Model: Altair-PJ2	Date: 04-Feb-15	No.: RY051003a
-------------------	-----------------	----------------

RTB Reissue

The items in ***bold italics*** have been corrected or added.

Subject: Firmware Release Note: MAIN:XGA:ALT-2		Prepared by: A. Iwaori	
From: VC Products Support Sect. Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **MAIN: XGA: ALT-2**.

Note: This firmware correspond to Y051, Y054

Version	Program No.	Effective Date	Availability of RFU
<i>1001160600</i>	<i>Y0505951E</i>	<i>March 2016 production</i>	<i>Not available</i>
V1000160600	Y0505951D	1st Mass production	Not available

Note: Definition of Availability of RFU via @Remote

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
<i>1001160600</i>	<i>1) Additional Model Information</i> - <i>None</i> <i>2) Changes</i> - <i>Improved stability when the temperature is high inside the projector.</i> - <i>The new version of the service tool can obtain detailed error log information regarding mercury bridge occurrences. The new version will be released around the middle of March 2016.</i> <i>3) Fixes</i> - <i>The following changes have been made to reduce the mercury bridge occurrence ratio.</i> - <i>Lamp driving management.</i> - <i>Increased the fan speed when turning off the projector.</i> - <i>Increased the cooling time when turning off the projector.</i> - <i>When the projector is installed on the floor: 5 sec. (current: 0 sec)</i> - <i>When the projector is mounted onto the ceiling or projecting onto the ceiling: 20 sec. (current: 0 sec.)</i> - <i>When the projector is projecting onto the floor: 20 sec. (current: 20 sec., no change)</i>
V1000160600	1st Mass production

Reissued: 23-Mar-16

Model: Altair-PJ2	Date: 04-Feb-15	No.: RY051004a
-------------------	-----------------	----------------

RTB Reissue

The items in ***bold italics*** have been corrected or added.

Subject: Firmware Release Note: MAIN:WXGA:ALT-2		Prepared by: A. Iwaori	
From: VC Products Support Sect. Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **MAIN: WXGA: ALT-2**.

Note: This firmware correspond to Y053, Y056

Version	Program No.	Effective Date	Availability of RFU
<i>1001160600</i>	<i>Y0525951E</i>	<i>March 2016 production</i>	<i>Not available</i>
V1000160600	Y0525951D	1st Mass production	Not available

Note: Definition of Availability of RFU via @Remote

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
<i>1001160600</i>	<i>1) Additional Model Information</i> - <i>None</i> <i>2) Changes</i> - <i>Improved stability when the temperature is high inside the projector.</i> - <i>The new version of the service tool can obtain detailed error log information regarding mercury bridge occurrences. The new version will be released around the middle of March 2016.</i> <i>3) Fixes</i> - <i>The following changes have been made to reduce the mercury bridge occurrence ratio.</i> - <i>Lamp driving management.</i> - <i>Increased the fan speed when turning off the projector.</i> - <i>Increased the cooling time when turning off the projector.</i> - <i>When the projector is installed on the floor: 5 sec. (current: 0 sec)</i> - <i>When the projector is mounted onto the ceiling or projecting onto the ceiling: 20 sec. (current: 0 sec.)</i> - <i>When the projector is projecting onto the floor: 20 sec. (current: 20 sec., no change)</i>
V1000160600	1st Mass production

Reissued: 12-Apr-16

Model: Soleil-PJ1a/Soleil-PJ1b/Soleil-PJ2/ Altair-PJ1/ Altair-PJ2/Soleil-PJ2.5	Date: 19-Oct-12	No.: RY011003f
---	-----------------	----------------

RTB Reissue

The items in bold italics have been corrected.

Subject: Firmware Release Note: Backup Tool		Prepared by: A. Iwaori	
From: VC Products Support Sec., Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **Backup Tool**.

Version	Program No.	Effective Date	Availability of RFU
1.7.0.0	Y0119100G	-	Not available
1.6.0.0	Y0119100F	-	Not available
1.5.0.0	Y0119100E	-	Not available
1.4.0.0	Y0119100D	-	Not available
1.3.0.0	Y0119100C	-	Not available
1.2.0.0	Y0119100B	-	Not available
1.1.0.0	Y0119100A	-	Not available

Note: Definition of Availability of RFU via @Remote
"Available": The firmware can be updated via RFU or SD card.

"Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
1.7.0.0	1) Additional Model Information None. 2) Specification Changes Able to obtain and display logs related to mercury bridge. 3) Error Corrections None.
1.6.0.0	1) Additional Model Information The following projector is now supported: Soleil PJ2.5 2) Specification Changes None. 3) Error Corrections None.
1.5.0.0	Additional Model Information: - Altair PJ2 models have been added. Specification Changes: The following functions have been added or changed for Altair PJ2:

Reissued: 12-Apr-16

Model: Soleil-PJ1a/Soleil-PJ1b/Soleil-PJ2/ Altair-PJ1/ Altair-PJ2/Soleil-PJ2.5		Date: 19-Oct-12	No.: RY011003f
Version	Modified Points or Symptom Corrected		
	<ul style="list-style-type: none">- Added functionality for obtaining service status information (Service Status Tool).- The tool automatically changes the projector's "Eco mode" settings to "Active stand-by mode" so that the tool can be executed without changing the setting in advance.		
1.4.0.0	Additional Supported Model: Soleil-PJ2		
1.3.0.0	Specification Change: Supports the Backup and Restore functions on the following versions of Altair-PJ1 firmware: Main: Ver. 1008220400 Network USB: Ver. 101300 ECO IO: Ver. 101400		
1.2.0.0	Additional Model Information: Support for the Altair-PJ1 was added.		
1.1.0.0	Initial release		

Reissued: 27-Jan-16

Model: Soleil-PJ1a/ Soleil-PJ1b/ Soleil-PJ2/ Soleil-PJ2.5/Altair-PJ1/ Altair-PJ2	Date: 21-Jul-12	No.: RY011004c
---	-----------------	----------------

RTB Reissue

The items in bold italics have been corrected or added.

Subject: Firmware Release Note: USB to UART Bridge Virtual COM Port driver		Prepared by: A. Iwaori	
From: VC Products Support Sec., Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Driver)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **USB to UART Bridge Virtual COM Port driver**.

Version	Program No.	Effective Date	Availability of RFU
1.0.0.0	Y0119102	-	Not available

Note: Definition of Availability of RFU via @Remote
"Available": The firmware can be updated via RFU or SD card.

"Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
1.0.0.0	<p><i>[Modifications made:]</i></p> <p><i>2015/02/02</i></p> <p><i>Additional support for Altair PJ2 has been included. No other changes have been made to the application.</i></p> <p><i>2016/01/20</i></p> <p><i>Additional support for Soleil PJ2.5 has been included. No other changes have been made to the application.</i></p> <p>---</p> <p>Initial Release</p>

Model: Altair-PJ1/Altair-PJ2/Soleil-PJ1b/ Soleil-PJ2/Soleil-PJ2.5	Date: 27-Jan-16	No.: RY011008
--	-----------------	---------------

Subject: Firmware Release Note: QuickPack		Prepared by: A. Iwaori	
From: VC Products Support Sec., Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **QuickPack**.

Version	Program No.	Effective Date	Availability of RFU
1001	PJSQPA_1001	-	Not available

Note: Definition of Availability of RFU via @Remote

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
1001	<p>1) Additional model information: Initial release.</p> <p>2) Specification changes: None.</p> <p>3) Error corrections: None.</p> <p>Remarks: QuickPack (Win. / Mac.) has been released via the following files.</p> <p>[Windows] QuickPack_WIN_V1000.zip Version: v1.0.0.0</p> <p>[Macintosh] QuickPack_MAC_V1102.zip Version: v1.1.0.2</p>

Reissued: 27-Jan-16

Model: Altair-PJ1/ Altair-PJ2/Soleil-PJ2/Soleil-PJ2.5	Date: 05-Feb-13	No.: RY024001c
--	-----------------	----------------

RTB Reissue

The items in ***bold italics*** have been corrected or added.

Subject: Release Note: FW Update		Prepared by: A. Iwaori	
From: VC Products Support Sec., Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware **FW Update Tool**.

Version	Program No.	Effective Date	Availability of RFU
1.3.0.0	Y0249101B	February 2015 production	Not available
1.1.0.0	Y0249101A	October 2013 production	Not available
1.0.0.0	Y0249101	Initial release	Not available

Note: Definition of Availability of RFU via @Remote
"Available": The firmware can be updated via RFU or SD card.

"Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
1.3.0.0	Additional Supported Model: Altair-PJ2 <i>Soleil-PJ2.5</i>
1.1.0.0	Additional Supported Model: Soleil-PJ2
1.0.0.0	This is a tool for updating the firmware for the main board on the following models only: Altair-PJ1 Important: This update tool can only be used on these models.