

Reissued: 18-May-16

Model: MD-A3M	Date: 18-May-16	No.: RE0A5001a
---------------	-----------------	----------------

RTB Reissue

The items in ***bold italics*** have been corrected or added.

Subject: Release Note: Firmware		Prepared by: A. Iwaori	
From: VC Products Support Sec., Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Other (Firmware)	<input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware **Firmware**.

Version	Program No.	Effective Date	Availability of RFU
<i>1.0.5</i>	<i>A3M105</i>	<i>April 2016 production</i>	<i>Not available</i>
1.0.4	A3M104	1st Mass production	Not available

Note: Definition of Availability of RFU via @Remote

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
<i>1.0.5</i>	<p><i>1) Additional Model Information</i> <i>No</i></p> <p><i>2) Specification Change</i></p> <ul style="list-style-type: none"> - <i>Disabled some Windows shortcut commands for security purposes.</i> - <i>Changed the pre-installed browser.</i> - <i>It is now possible to designate any port number for the proxy server.</i> <p><i>3) Error Correction</i></p> <ul style="list-style-type: none"> - <i>Unable to press the button on the pop-up window as it is occasionally hidden by other windows.</i>
1.0.4	1st Mass production

Model: MD-A3M	Date: 27-Dec-16	No.: RE0A5002
----------------------	-----------------	---------------

Subject: Release Note: System Updata		Prepared by: A. Iwaori	
From: VC Products Support Sec., Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Other (Firmware)	<input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware **System Updata**.

Version	Program No.	Effective Date	Availability of RFU
1.0.7.0	A3M107FirmUp	December 2016 production	Not available

Note: Definition of Availability of RFU via @Remote

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
1.0.7.0	1) Additional Model Information None. 2) Specification Changes - A dedicated application for UCS Advanced is installed - Possible to select a default application - Possible to select an external speaker - Support for OS update - Security update 3) Error Corrections None.