

=====
*** Basic Information ***
=====

[Create date] 2017/05/29

[Program Name] Main

[Version] B05N

[PCB No.]

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Others

Exported to(language) GEN(all)

[Firmware No.] Y0885510A

[File Information]

File Name Y0885510A.exe

File Type Module for Service

Size 1.14 MB (1191273 byte)

Check Sum -8Bit Sum: 6117

 -16Bit Sum(Little Endian): A402

 -16Bit Sum(Big Endian): D415

[Production reflection]

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]

1) Additional Model Information

None

2) Specification Change

New Main Firmware package including following three text file.

"FlashDeviceParameters.txt", "Info_Skip_32KB.txt",

"Info_FlashDeviceParameters installation.txt".

Read and follow the contents of "Info_Skip_32KB.txt" and

"Info_FlashDeviceParameters installation.txt" before doing firmware upgrade.

3) Error Correction

None

[Modification history]

Version B05

Sound volume command(VVL) and projection mode command(PJM) is available.

=====
*** Basic Information ***
=====

[Create date] 2018/03/13

[Program Name] FW Update 12

[Version] 12.6

[PCB No.]

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Others

Exported to(language) GEN(all)

[Firmware No.] Y0885520

[File Information]

File Name Y0885520.exe

File Type Module for Service

Size 49.29 MB (51680509 byte)

Check Sum -8Bit Sum: 919B

 -16Bit Sum(Little Endian): BA6C

 -16Bit Sum(Big Endian): 722F

[Availability of RFU] No

[Production reflection]

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]
Rank C

Firmware update tool: DLP Composer Lite v12.6

[Modification history]

Version 12.6
Additional Supported Model:
Capella-PJ1, Mira-PJ1, Hadar-PJ1

Version 12.6
DLP Composer Lite v12.6 release.

Note:
Use the FlashDeviceParameters.txt inside the Main firmware package for upgrading.

=====
*** Basic Information ***
=====

[Create date] 2017/05/29

[Program Name] Main

[Version] B02N

[PCB No.]

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Others

Exported to(language) GEN(all)

[Firmware No.] Y0895510A

[File Information]

File Name Y0895510A.exe

File Type Module for Service

Size 1.35 MB (1411515 byte)

Check Sum -8Bit Sum: 847C

 -16Bit Sum(Little Endian): 63ED

 -16Bit Sum(Big Endian): 9C8F

[Production reflection]

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]

1) Additional Model Information

None

2) Specification Change

New Main Firmware package including following three text file.

"FlashDeviceParameters.txt", "Info_Skip_32KB.txt",

"Info_FlashDeviceParameters installation.txt".

Read and follow the contents of "Info_Skip_32KB.txt" and

"Info_FlashDeviceParameters installation.txt" before doing firmware upgrade.

3) Error Correction

None

[Modification history]

Version B02

Sound volume command(VVL) and projection mode command(PJM) is available.