

Model: Russian-C5		Date: 12-May-08	No.: MD017001
Modified Article: Scanner heater option		Prepared by: Yuji Mimura	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Please apply the following changes to your Parts Catalogs

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2291688		Heater:Option:230V:9W	1	X/O	18	22	
	D0198464	HEATER:SCANNER:NA:ASS'Y	1				120V
	D0198466	HEATER:SCANNER:EU:ASS'Y	1				230V

Model: Russian-C5		Date: 6-Jun-08	No.: MD017002
Modified Article: Developer		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Please apply the following changes to your Parts Catalogs

part number	Wrong Description	Correct Description	Page	Index	Note
B1219640	Guide Plate: Entrance: Upper: Ass'y	Developer Type 28 Black	35	22	

Model: Russian-C5		Date: 10-Jun-08	No.: MD017003
Modified Article:		Prepared by: Yuji Mimura	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Please apply the following changes to your Parts Catalogs.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2097615	D0195615	Power Supply: Cord: Stopper: NA: Ass'y	1	X/O	54	23	
B2097631	D0195631	Power Supply Cord: Stopper: EU	1	X/O			
	B2097617	Power Supply Cord: Stopper: TWN	1				
	D0195691	Power Supply Cord: Stopper: CHN	1				

Model: Russian-C5		Date: 23-Jun-08	No.: MD017004
Modified Article: Sync. Detector Board		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Please apply the following changes to your Parts Catalogs

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
D0095320	D0095325	Sync. Detector Board	1-1		21	11	

Model: Russian-C5		Date: 23-Jun-08	No.: MD017005
Modified Article: Magnetic Clutch		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☒ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
D0191186	D0191187	Magnetic Clutch – 39Z	1-1	X/O	31	23	

Change: The length of the clutch harness was increased.

Reason: To facilitate assembly of the parts around the clutch.

Reissued: 1-Aug-08

Model: Russian-C5	Date: 10-Jul-08	No.: MD017006a
-------------------	-----------------	----------------

MB Reissue

The items in ***bold italics*** were corrected or added.

Modified Article: Lens Unit		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Please apply the following changes to your Parts Catalogs.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
D0201698	<i>D0201703</i>	Lens Unit	1		17	11	
D0191698	<i>D0191703</i>	Lens Unit	1		17	11	

Reissued: 18-Jul-08

Model: Russian-C5	Date: 14-Jul-08	No.: MD017007a
-------------------	-----------------	----------------


MB Reissue

The items in ***bold italics*** were corrected or added.

Modified Article: <i>Engine Board</i>		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction	☐ Vendor change	☐ To meet standards ()
	☐ To facilitate assembly	☐ To improve reliability	
	☐ Part standardization	☐ Other	

Please apply the following changes to your Parts Catalogs.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	14076362	EEPROM:BR24L64-W	1		55	114	



Reissued: 18-Aug-08

Model: Russian-C5	Date: 18-Jul-08	No.: MD017009a
-------------------	-----------------	----------------


MB Reissue

The items in ***bold italics*** were corrected or added.

Modified Article: Rear Frame		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction	☐ Vendor change	☐ To meet standards ()
	☐ To facilitate assembly	☐ To improve reliability	
	☐ Part standardization	☐ Other	

Please apply the following changes to your Parts Catalogs.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	D0191785	FRAME: REAR (MS models)	1		15	16	
	<i>B2381785</i>	FRAME: REAR (CS models)	1		15	16	



Model: Russian-C5		Date: 23-Jul-08	No.: MD017010
Modified Article: HDD		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
D3625130	M3445130	HDD	1-1	O/O	51	26	

Change/Reason: Vender change.

Model: Russian-C5		Date: 31-Jul-08	No.: MD017011
Modified Article: Duplex Main Harness		Prepared by: Yuji Mimura	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		


Please apply the following changes to your Parts Catalogs

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
D3695260		Duplex Main Harness	1	O/O	12	8	
	D3695270	HARNES:DUPLEX:MAIN	1				

Model: Russian-C5		Date: 3-Sep-08	No.: MD017012
Modified Article: Guide Plate		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Please apply the following changes to your Parts Catalogs.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	D0194158	SPRING:OPEN AND CLOSE:GUIDE	2		39	23	
	D0194156	GUIDE PLATE:FUSING:UPPER	1		39	24	



Model: Russian-C5		Date: 3-Sep-08	No.: MD017013
Modified Article: Fusing Unit		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

The following changes are for Taiwan models only.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
D0194001		Fusing Unit – 120V	1-1	X/O	39	*	
	D0194003	Fusing Unit – TWN					
AX440140		Fusing Lamp – 120V	1-1	X/O	39	10	
	AX440256	Heater: 110V: Main					
AX440141		Fusing Lamp – 120V	1-1	X/O	39	11	
	AX440257	Heater: 110V: Sub					

Change: The fusing lamps were changed.

Reason: To improve the copy quality.


Model: Russian-C5		Date: 8-Sep-08	No.: MD017014
Modified Article: Snap Ring/ Spring Plate		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Please delete the following part numbers from your Parts Catalogs.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2092870		Spring Plate: Paper Size Sensor: Ass'y	2		37	23	
B0902686		Snap Ring	2		35	7	

Model: Russian-C5		Date: 15-Oct-08	No.: MD017015
Modified Article: Screw / Spring		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Please correct the following index numbers in your Parts Catalogs.




Please correct the following description in your Parts Catalogs.

Part number	Wrong Description	Correct Description	Q'ty	Page	Index
D0192725	Cleaner - Registration	Bracket: UN Lock	1	29	15

Model: Russian-C5		Date: 21-Nov-08	No.: MD017016
Modified Article: Rear Cover		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Please add the following part numbers to your Parts Catalogs.



Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	D0191296	Cover: Paper Feed Sub-Unit: Rear	1		11	20	
	D0191393	Cover: Paper Feed Sub-Unit: Rear: EU	1		11	20	

Model: Russian-C5		Date: 02-Feb-09	No.: MD017017
Modified Article: BCU Board		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
D0195051	D0195055	BCU Board - 33	1-1	X/O	55	16	
D0195052	D0195056	BCU Board - 25	1-1	X/O	55	16	

Change: A resistor chip (0 ohm) was added.

Reason: The circuit pattern on the PCB was wrong.

Model: Russian-C5		Date: 09-Feb-09	No.: MD017018
Modified Article: Scanner Unit		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
D0191080	D0191081	Scanner Stay – Right Lower	1-1	X/O	57	19	
	D0191086	Seal Arm Scanner	0-1		57	25	
	D0191520	Seal Operation Sub Unit: A	0-1		13	33	
	D0191521	Seal Operation Sub Unit: B	0-1		13	34	
	D0191522	Cushion Operation Sub Unit: Front	0-1		13	32	
	D0191075	Sponge Side Plate Rear (D018/D020)	0-1		57	24	Color scanner model only

Change: The parts in the table were added.

Reason: To further minimize condensation inside the scanner unit.




Fig. 1




Fig.2



Part Change Information List

Date: March 18, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Russian-C5	D017	200903		D0191187	D0191188	MAGNETIC CLUTCH:0.5N M:Z35	0	1	O/O		31	23			Y		V0900540
Russian-C5	D018	200903		D0191187	D0191188	MAGNETIC CLUTCH:0.5N M:Z35	0	1	O/O		31	23			Y		V0900540
Russian-C5	D019	200903		D0191187	D0191188	MAGNETIC CLUTCH:0.5N M:Z35	0	1	O/O		31	23			Y		V0900540
Russian-C5	D020	200903		D0191187	D0191188	MAGNETIC CLUTCH:0.5N M:Z35	0	1	O/O		31	23			Y		V0900540
Russian-C5	D017	200903		D0192616	D0192816	MAGNETIC CLUTCH:0.35N M:Z50	0	2	O/O		47	13			Y		V0900540
Russian-C5	D017	200903		D0192617	AX200290	MAGNETIC CLUTCH:0.25N M:Z38	0	2	O/O		47	14			Y		V0900540
Russian-C5	D018	200903		D0192616	D0192816	MAGNETIC CLUTCH:0.35N M:Z50	0	2	O/O		47	13			Y		V0900540
Russian-C5	D018	200903		D0192617	AX200290	MAGNETIC CLUTCH:0.25N M:Z38	0	2	O/O		47	14			Y		V0900540
Russian-C5	D019	200903		D0192616	D0192816	MAGNETIC CLUTCH:0.35N M:Z50	0	2	O/O		47	13			Y		V0900540
Russian-C5	D019	200903		D0192617	AX200290	MAGNETIC CLUTCH:0.25N M:Z38	0	2	O/O		47	14			Y		V0900540
Russian-C5	D020	200903		D0192616	D0192816	MAGNETIC CLUTCH:0.35N M:Z50	0	2	O/O		47	13			Y		V0900540
Russian-C5	D020	200903		D0192617	AX200290	MAGNETIC CLUTCH:0.25N M:Z38	0	2	O/O		47	14			Y		V0900540



Part Change Information List

Date: April 30, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Russian-C5	D017	200904			B0392343	DRUM SHUTTER	0	1			35	23			Y		
Russian-C5	D018	200904			B0392343	DRUM SHUTTER	0	1			35	23			Y		
Russian-C5	D019	200904			B0392343	DRUM SHUTTER	0	1			35	23			Y		
Russian-C5	D020	200904			B0392343	DRUM SHUTTER	0	1			35	23			Y		



Part Change Information List

Date: June 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	200906		B0241365	D0191365	CAP:38X77	1	1	O/O		11	13					V0900703	9020352
R-C5	D018	200906		B0241365	D0191365	CAP:38X77	1	1	O/O		11	13					V0900703	9020352
R-C5	D019	200906		B0241365	D0191365	CAP:38X77	1	1	O/O		11	13					V0900703	9020352
R-C5	D020	200906		B0241365	D0191365	CAP:38X77	1	1	O/O		11	13					V0900703	9020352
R-C5	D018	200906		M3445130	M3085130	HDD:80GB:MHZ2080BH:FUJITSU	1	1	O/O		51	26					V0901020	9031090
R-C5	D020	200906		M3445130	M3085130	HDD:80GB:MHZ2080BH:FUJITSU	1	1	O/O		51	26					V0901020	9031090



Part Change Information List

Date: August 31, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	200908			D0091501	COVER:UPPER	0	1			13	35			RD017043		V0901734	
R-C5	D018	200908			D0091501	COVER:UPPER	0	1			13	35			RD017043		V0901734	
R-C5	D019	200908			D0091501	COVER:UPPER	0	1			13	35			RD017043		V0901734	
R-C5	D020	200908			D0091501	COVER:UPPER	0	1			13	35			RD017043		V0901734	
R-C5	D017	200908			D0091551	COVER:UPPER:NA	0	1			13	35			RD017043		V0901773	
R-C5	D018	200908			D0091551	COVER:UPPER:NA	0	1			13	35					V0901773	
R-C5	D019	200908			D0091551	COVER:UPPER:NA	0	1			13	35					V0901773	
R-C5	D020	200908			D0091551	COVER:UPPER:NA	0	1			13	35					V0901773	



Part Change Information List

Date: November 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D019	200911		D3702701	B2382753	DECAL:SIDE FENCE	1	1	X/O		3	23					V0701448	7120204
R-C5	D020	200911		D3702701	B2382753	DECAL:SIDE FENCE	1	1	X/O		3	23					V0701448	7120204
R-C5	D369	200911		D3702701	B2382753	DECAL:SIDE FENCE	1	1	X/O		3	23					V0701448	7120204
R-C5	D370	200911		D3702701	B2382753	DECAL:SIDE FENCE	1	1	X/O		3	23					V0701448	7120204
R-C5	D018	200911		B2385372	B2385345	Scanner Interface Cable	1	1	X/O		17	14					V0903007	
R-C5	D020	200911		B2385372	B2385345	Scanner Interface Cable	1	1	X/O		17	14					V0903007	
R-C5	D017	200911		AX040220	D3312680	DC MOTOR:PAPER FEED:ASS'Y	2	2	O/O		49	1					V0804693	8101773
R-C5	D018	200911		AX040220	D3312680	DC MOTOR:PAPER FEED:ASS'Y	2	2	O/O		49	1					V0804693	8101773
R-C5	D019	200911		AX040220	D3312680	DC MOTOR:PAPER FEED:ASS'Y	2	2	O/O		49	1					V0804693	8101773
R-C5	D020	200911		AX040220	D3312680	DC MOTOR:PAPER FEED:ASS'Y	2	2	O/O		49	1					V0804693	8101773
R-C5	D017	200911		D0195150	D0195152	PCB:IMAGE PROCESSING UNIT	1	1	X/O		51	5					V0902471	9090863
R-C5	D018	200911		D0195150	D0195152	PCB:IMAGE PROCESSING UNIT	1	1	X/O		51	5					V0902471	9090863
R-C5	D019	200911		D0195150	D0195152	PCB:IMAGE PROCESSING UNIT	1	1	X/O		51	5					V0902471	9090863
R-C5	D020	200911		D0195150	D0195152	PCB:IMAGE PROCESSING UNIT	1	1	X/O		51	5					V0902471	9090863



Part Change Information List

Date: December 29, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D019	200912		D0191461	D0191481	PCB:RUC5:LCDC:NA:ASS'Y	1	1	X/O		13	9					V0902935	9110418
R-C5	D020	200912		D0191461	D0191481	PCB:RUC5:LCDC:NA:ASS'Y	1	1	X/O		13	9					V0902935	9110418



Part Change Information List

Date: January 29, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	201001		D0191462	D0191482	PCB:RUC5:LCDC:EU:ASS'Y	1	1	X/O		13	9					V0902935	9110418
R-C5	D018	201001		D0191462	D0191482	PCB:RUC5:LCDC:EU:ASS'Y	1	1	X/O		13	9					V0902935	9110418
R-C5	D019	201001		D0191462	D0191482	PCB:RUC5:LCDC:EU:ASS'Y	1	1	X/O		13	9					V0902935	9110418
R-C5	D020	201001		D0191462	D0191482	PCB:RUC5:LCDC:EU:ASS'Y	1	1	X/O		13	9					V0902935	9110418
R-C5	D019	201001		D0195310	D0195315	PCB:CTL:RU-C5MS:MS33:EXP	1	1	X/O		51	12					V0902914	9110354
R-C5	D017	201001		D0195311	D0195316	PCB:CTL:RU-C5MS:MS25:EXP	1	1	X/O		51	12					V0902914	9110354
R-C5	D019	201001		D0195311	D0195316	PCB:CTL:RU-C5MS:MS25:EXP	1	1	X/O		51	12					V0902914	9110354



Part Change Information List

Date: February 26, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	201002		D0191412	D0191442	OPERATION SUB-UNIT:RU-C5:EU:ASS'Y	1	1	X/O		13	*					V0902935	9110418
R-C5	D018	201002		D0191412	D0191442	OPERATION SUB-UNIT:RU-C5:EU:ASS'Y	1	1	X/O		13	*					V0902935	9110418
R-C5	D019	201002		D0191412	D0191442	OPERATION SUB-UNIT:RU-C5:EU:ASS'Y	1	1	X/O		13	*					V0902935	9110418
R-C5	D020	201002		D0191412	D0191442	OPERATION SUB-UNIT:RU-C5:EU:ASS'Y	1	1	X/O		13	*					V0902935	9110418
R-C5	D018	201002		D0205311	D0205316	PCB:CTL:RU-C5CS:CS25:EXP	1	1	X/O		51	12					V0902914	9110354
R-C5	D020	201002		D0205310	D0205315	PCB:CTL:RU-C5CS:CS33:EXP	1	1	X/O		51	12					V0902914	9110354



Part Change Information List

Date: March 31, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	201003		7330408	D0194208	BUSHING:DIA4X8:FUSING	2	2	O/O		41	107					V1000304	10020672
R-C5	D018	201003		7330408	D0194208	BUSHING:DIA4X8:FUSING	2	2	O/O		41	107					V1000304	10020672
R-C5	D019	201003		7330408	D0194208	BUSHING:DIA4X8:FUSING	2	2	O/O		41	107					V1000304	10020672
R-C5	D020	201003		7330408	D0194208	BUSHING:DIA4X8:FUSING	2	2	O/O		41	107					V1000304	10020672



Part Change Information List

Date: April 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	201004		D0102951	D3312951	SHAFT:RELEASE:PAPER TRAY	1	1	O/O		23	24					V1000426	10030316
R-C5	D018	201004		D0102951	D3312951	SHAFT:RELEASE:PAPER TRAY	1	1	O/O		23	24					V1000426	10030316
R-C5	D019	201004		D0102951	D3312951	SHAFT:RELEASE:PAPER TRAY	1	1	O/O		23	24					V1000426	10030316
R-C5	D020	201004		D0102951	D3312951	SHAFT:RELEASE:PAPER TRAY	1	1	O/O		23	24					V1000426	10030316



Part Change Information List

Date: Jul 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	201007		11071066	11071303	FUSE:GLASS CARTRIDGE:FSL 250V 5A(EM)	4	4	X/O		55	116					V1000515	10031143
R-C5	D018	201007		11071066	11071303	FUSE:GLASS CARTRIDGE:FSL 250V 5A(EM)	4	4	X/O		55	116					V1000515	10031143
R-C5	D019	201007		11071066	11071303	FUSE:GLASS CARTRIDGE:FSL 250V 5A(EM)	4	4	X/O		55	116					V1000515	10031143
R-C5	D020	201007		11071066	11071303	FUSE:GLASS CARTRIDGE:FSL 250V 5A(EM)	4	4	X/O		55	116					V1000515	10031143

Model	Code	PCIL Nr.	PCIL Correctio	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	201008			D0091556	PANEL:UPPER:NA	0	1			13	36			Y		V1001748	
R-C5	D017	201008			D0091557	PANEL:UPPER:EU	0	1			13	36			Y		V1001918	
R-C5	D018	201008			D0091556	PANEL:UPPER:NA	0	1			13	36			Y		V1001748	
R-C5	D018	201008			D0091557	PANEL:UPPER:EU	0	1			13	36			Y		V1001918	
R-C5	D019	201008			D0091556	PANEL:UPPER:NA	0	1			13	36			Y		V1001748	
R-C5	D019	201008			D0091557	PANEL:UPPER:EU	0	1			13	36			Y		V1001918	
R-C5	D020	201008			D0091556	PANEL:UPPER:NA	0	1			13	36			Y		V1001748	
R-C5	D020	201008			D0091557	PANEL:UPPER:EU	0	1			13	36			Y		V1001918	
R-C5	D017	201008			B2381539	SHEET:POWER SOURCE:DISPLAY:NA	0	1			13	37			Y		V1001748	
R-C5	D017	201008			B2861479	SHEET:POWER SOURCE:N-C2:EU	0	1			13	37			Y		V1001918	
R-C5	D018	201008			B2381539	SHEET:POWER SOURCE:DISPLAY:NA	0	1			13	37			Y		V1001748	
R-C5	D018	201008			B2861479	SHEET:POWER SOURCE:N-C2:EU	0	1			13	37			Y		V1001918	
R-C5	D019	201008			B2381539	SHEET:POWER SOURCE:DISPLAY:NA	0	1			13	37			Y		V1001748	
R-C5	D019	201008			B2861479	SHEET:POWER SOURCE:N-C2:EU	0	1			13	37			Y		V1001918	
R-C5	D020	201008			B2381539	SHEET:POWER SOURCE:DISPLAY:NA	0	1			13	37			Y		V1001748	
R-C5	D020	201008			B2861479	SHEET:POWER SOURCE:N-C2:EU	0	1			13	37			Y		V1001918	

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D019	201009		D0191411	D0191441	OPERATION SUB-UNIT:RU-C5:NA:ASS'Y	1	1	X/O		13	*					V0902935	9110418
R-C5	D020	201009		D0191411	D0191441	OPERATION SUB-UNIT:RU-C5:NA:ASS'Y	1	1	X/O		13	*					V0902935	9110418
R-C5	D017	201009		D0195152	D0195153	PCB:IMAGE PROCESSING UNIT	1	1	O/O		51	5					V0903200	9120435
R-C5	D018	201009		D0195152	D0195153	PCB:IMAGE PROCESSING UNIT	1	1	O/O		51	5					V0903200	9120435
R-C5	D019	201009		D0195152	D0195153	PCB:IMAGE PROCESSING UNIT	1	1	O/O		51	5					V0903200	9120435
R-C5	D020	201009		D0195152	D0195153	PCB:IMAGE PROCESSING UNIT	1	1	O/O		51	5					V0903200	9120435



Part Change Information List

Date: October 29, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	201010		D0091466	D0091470	PCB:OP-R	1	1	O/O		13	31					V1000648	
R-C5	D018	201010		D0091466	D0091470	PCB:OP-R	1	1	O/O		13	31					V1000648	
R-C5	D019	201010		D0091466	D0091470	PCB:OP-R	1	1	O/O		13	31					V1000648	
R-C5	D020	201010		D0091466	D0091470	PCB:OP-R	1	1	O/O		13	31					V1000648	
R-C5	D017	201010		D0195316	D0195366	PCB:CTL-RU-C5MS.MS25:EXP	1	1	O/O		51	12			RD017047		V1000175	10010841
R-C5	D019	201010		D0195315	D0195365	PCB:CTL-RU-C5MS.MS33:EXP	1	1	O/O		51	12			RD017047		V1000175	10010841
R-C5	D019	201010		D0195316	D0195366	PCB:CTL-RU-C5MS.MS25:EXP	1	1	O/O		51	12			RD017047		V1000175	10010841

Model	Code	PCIL Nr.	PCIL Correctio	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D018	201011		A1931767	M0261815	CLAMP:MIRROR:NO.1	2	2	O/O		17	7					V1001619	10070454
R-C5	D020	201011		A1931767	M0261815	CLAMP:MIRROR:NO.1	2	2	O/O		17	7					V1001619	10070454
R-C5	D020	201011		D0205315	D0205365	PCB:CTL:RU-C5CS:CS33:EXP	1	1	O/O		51	12			RD017047		V1000175	10010841

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	201012			D0192796	SHEET:PAPER SIZE SENSOR:SIDE FENCE	0	2			49	32			RD017050		V1000442	10030400
R-C5	D018	201012			D0192796	SHEET:PAPER SIZE SENSOR:SIDE FENCE	0	2			49	32			RD017050		V1000442	10030400
R-C5	D018	201012		B2381692	B2381803	DOCUMENT FEEDER BRACKET	1	1	O/O		15	15					V1001869	
R-C5	D019	201012			D0192796	SHEET:PAPER SIZE SENSOR:SIDE FENCE	0	2			49	32			RD017050		V1000442	10030400
R-C5	D020	201012			D0192796	SHEET:PAPER SIZE SENSOR:SIDE FENCE	0	2			49	32			RD017050		V1000442	10030400
R-C5	D020	201012		B2381692	B2381803	DOCUMENT FEEDER BRACKET	1	1	O/O		15	15					V1001869	

RICOH**Part Change Information List**

Date: January 31, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D018	201101		D0205316	D0205366	PCB:CTL:RU-C5CS:CS25:EXP	1	1	O/O		51	12			RD017047		V1000175	10010841



Part Change Information List

Date: March 31, 2011

Model	Code	PCIL Nr.	PCIL Correcti on	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	201103		D0191413	D0191443	OPERATION SUB-UNIT:RU-C5:AA:ASS'Y	1	1	X/O		13	*					V0902935	09110418
R-C5	D018	201103		D0191413	D0191443	OPERATION SUB-UNIT:RU-C5:AA:ASS'Y	1	1	X/O		13	*					V0902935	09110418
R-C5	D019	201103		D0191413	D0191443	OPERATION SUB-UNIT:RU-C5:AA:ASS'Y	1	1	X/O		13	*					V0902935	09110418
R-C5	D020	201103		D0191413	D0191443	OPERATION SUB-UNIT:RU-C5:AA:ASS'Y	1	1	X/O		13	*					V0902935	09110418
R-C5	D017	201103		AA000301	GA000058	DECAL:H-TEMP WARNING:115:CUD	1	1	O/O		39	2					V1002478	10090261
R-C5	D018	201103		AA000301	GA000058	DECAL:H-TEMP WARNING:115:CUD	1	1	O/O		39	2					V1002478	10090261
R-C5	D019	201103		AA000301	GA000058	DECAL:H-TEMP WARNING:115:CUD	1	1	O/O		39	2					V1002478	10090261
R-C5	D020	201103		AA000301	GA000058	DECAL:H-TEMP WARNING:115:CUD	1	1	O/O		39	2					V1002478	10090261
R-C5	D017	201103		AA000301	GA000058	DECAL:H-TEMP WARNING:115:CUD	1	1	O/O		85	1					V1002478	10090261
R-C5	D018	201103		AA000301	GA000058	DECAL:H-TEMP WARNING:115:CUD	1	1	O/O		85	1					V1002478	10090261
R-C5	D019	201103		AA000301	GA000058	DECAL:H-TEMP WARNING:115:CUD	1	1	O/O		85	1					V1002478	10090261
R-C5	D020	201103		AA000301	GA000058	DECAL:H-TEMP WARNING:115:CUD	1	1	O/O		85	1					V1002478	10090261



Part Change Information List

Date: May 31, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	201105		D0099590	D0099593	NV-RAM	1	1	O/O		51	13					V1002448	
R-C5	D018	201105		D0099590	D0099593	NV-RAM	1	1	O/O		51	13					V1002448	
R-C5	D019	201105		D0099590	D0099593	NV-RAM	1	1	O/O		51	13					V1002448	
R-C5	D020	201105		D0099590	D0099593	NV-RAM	1	1	O/O		51	13					V1002448	



Part Change Information List

Date: July 28, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	201107		B2231521	R7241521	KEYTOP:10KEY:SERVICE	1	1	X/O		13	21					V1100517	
R-C5	D018	201107		B2231521	R7241521	KEYTOP:10KEY:SERVICE	1	1	X/O		13	21					V1100517	
R-C5	D019	201107		B2231521	R7241521	KEYTOP:10KEY:SERVICE	1	1	X/O		13	21					V1100517	
R-C5	D020	201107		B2231521	R7241521	KEYTOP:10KEY:SERVICE	1	1	X/O		13	21					V1100517	



Part Change Information List

Date: August 31, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	201108		D0191463	D0191483	PCB:RUC5.LCDC:TWN/AA:ASS'Y	1	1	X/O		13	9					V0902935	09110418
R-C5	D018	201108		D0191463	D0191483	PCB:RUC5.LCDC:TWN/AA:ASS'Y	1	1	X/O		13	9					V0902935	09110418
R-C5	D019	201108		D0191463	D0191483	PCB:RUC5.LCDC:TWN/AA:ASS'Y	1	1	X/O		13	9					V0902935	09110418
R-C5	D020	201108		D0191463	D0191483	PCB:RUC5.LCDC:TWN/AA:ASS'Y	1	1	X/O		13	9					V0902935	09110418



Part Change Information List

Date: October 31, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	201110		AA120094	D0194453	DISCHARGE BRUSH:PAPER EXIT SUB-UNIT	1	1	O/O		43	11					V1101086	11050641
R-C5	D018	201110		AA120094	D0194453	DISCHARGE BRUSH:PAPER EXIT SUB-UNIT	1	1	O/O		43	11					V1101086	11050641
R-C5	D019	201110		AA120094	D0194453	DISCHARGE BRUSH:PAPER EXIT SUB-UNIT	1	1	O/O		43	11					V1101086	11050641
R-C5	D020	201110		AA120094	D0194453	DISCHARGE BRUSH:PAPER EXIT SUB-UNIT	1	1	O/O		43	11					V1101086	11050641
R-C5	D017	201110		D0191442	D0191432	OPERATION SUB-UNIT:RU-C5:EU:ASS'Y	1	1	X/O		45	3					V1102293	11081554
R-C5	D018	201110		D0191442	D0191432	OPERATION SUB-UNIT:RU-C5:EU:ASS'Y	1	1	X/O		45	3					V1102293	11081554
R-C5	D019	201110		D0191442	D0191432	OPERATION SUB-UNIT:RU-C5:EU:ASS'Y	1	1	X/O		45	3					V1102293	11081554
R-C5	D020	201110		D0191442	D0191432	OPERATION SUB-UNIT:RU-C5:EU:ASS'Y	1	1	X/O		45	3					V1102293	11081554
R-C5	D018	201110		M3085130	M0805321	HDD:OPTION:160GB:MK1676GSX	1	1	O/O		51	26					V1101538	11061311
R-C5	D020	201110		M3085130	M0805321	HDD:OPTION:160GB:MK1676GSX	1	1	O/O		51	26					V1101538	11061311



Part Change Information List

Date: November 30, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	201111		B2231541	R7241541	KEYTOP:10KEY.SERVICE:AA	1	1	O/O		13	21					V1101088	11041262
R-C5	D018	201111		B2231541	R7241541	KEYTOP:10KEY.SERVICE:AA	1	1	O/O		13	21					V1101088	11041262
R-C5	D019	201111		B2231541	R7241541	KEYTOP:10KEY.SERVICE:AA	1	1	O/O		13	21					V1101088	11041262
R-C5	D020	201111		B2231541	R7241541	KEYTOP:10KEY.SERVICE:AA	1	1	O/O		13	21					V1101088	11041262
R-C5	D019	201111		B2231540	R7241540	KEYTOP:10KEY.SERVICE:NA	1	1	O/O		13	21					V1101088	11041262
R-C5	D020	201111		B2231540	R7241540	KEYTOP:10KEY.SERVICE:NA	1	1	O/O		13	21					V1101088	11041262
R-C5	D017	201111		B2093616	D0853616	DC MOTOR:TONER BOTTLE:Z:2.52W:ASS'Y	1	1	O/O		33	11					V1002821	10110803
R-C5	D018	201111		B2093616	D0853616	DC MOTOR:TONER BOTTLE:Z:2.52W:ASS'Y	1	1	O/O		33	11					V1002821	10110803
R-C5	D019	201111		B2093616	D0853616	DC MOTOR:TONER BOTTLE:Z:2.52W:ASS'Y	1	1	O/O		33	11					V1002821	10110803
R-C5	D020	201111		B2093616	D0853616	DC MOTOR:TONER BOTTLE:Z:2.52W:ASS'Y	1	1	O/O		33	11					V1002821	10110803



Part Change Information List

Date: February 29, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C5	D017	201202		D0091498	D0891498	LCD:TF1:WVGA:MV	1	1	O/O		13	18					V1102293	11081554
R-C5	D018	201202		D0091498	D0891498	LCD:TF1:WVGA:MV	1	1	O/O		13	18					V1102293	11081554
R-C5	D019	201202		D0091498	D0891498	LCD:TF1:WVGA:MV	1	1	O/O		13	18					V1102293	11081554
R-C5	D020	201202		D0091498	D0891498	LCD:TF1:WVGA:MV	1	1	O/O		13	18					V1102293	11081554
R-C5	D019	201202		D0195365	D0195351	PCB:CTL:RU-C5MS:MS33:EXP	1	1	X/O		51	12					V1103676	11111618



Part Change Information List

Date: July 30, 2013

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D017	201307		B2381795	D1051795	EXPOSURE GLASS:DOCUMENT FEEDER	1	1	O/O		15	2					V1203831	12112447
R-C5	D018	201307		B2381795	D1051795	EXPOSURE GLASS:DOCUMENT FEEDER	1	1	O/O		15	2					V1203831	12112447
R-C5	D019	201307		B2381795	D1051795	EXPOSURE GLASS:DOCUMENT FEEDER	1	1	O/O		15	2					V1203831	12112447
R-C5	D020	201307		B2381795	D1051795	EXPOSURE GLASS:DOCUMENT FEEDER	1	1	O/O		15	2					V1203831	12112447



Part Change Information List

Date: September 30, 2013

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D017	201309		B2094094	B0274094	THERMOSTAT HOUSING	2	2	O/O		41	2				V1201471	
R-C5	D018	201309		B2094094	B0274094	THERMOSTAT HOUSING	2	2	O/O		41	2				V1201471	
R-C5	D019	201309		B2094094	B0274094	THERMOSTAT HOUSING	2	2	O/O		41	2				V1201471	
R-C5	D020	201309		B2094094	B0274094	THERMOSTAT HOUSING	2	2	O/O		41	2				V1201471	



Part Change Information List

Date: November 29, 2013

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D017	201311		B2231497	B2231475	PCB OP-L	1	1	O/O		13	4					V1000642	
R-C5	D018	201311		B2231497	B2231475	PCB OP-L	1	1	O/O		13	4					V1000642	
R-C5	D019	201311		B2231497	B2231475	PCB OP-L	1	1	O/O		13	4					V1000642	
R-C5	D020	201311		B2231497	B2231475	PCB OP-L	1	1	O/O		13	4					V1000642	



Part Change Information List

Date: January 31, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D017	201401		B0902686	52062686	SNAP RING	3	3	O/O		25	6					V1302626	
R-C5	D018	201401		B0902686	52062686	SNAP RING	3	3	O/O		25	6					V1302626	
R-C5	D019	201401		B0902686	52062686	SNAP RING	3	3	O/O		25	6					V1302626	
R-C5	D020	201401		B0902686	52062686	SNAP RING	3	3	O/O		25	6					V1302626	
R-C5	D017	201401		B0902686	52062686	SNAP RING	1	1	O/O		27	6					V1302626	
R-C5	D018	201401		B0902686	52062686	SNAP RING	1	1	O/O		27	6					V1302626	
R-C5	D019	201401		B0902686	52062686	SNAP RING	1	1	O/O		27	6					V1302626	
R-C5	D020	201401		B0902686	52062686	SNAP RING	1	1	O/O		27	6					V1302626	
R-C5	D017	201401		B0902686	52062686	SNAP RING	2	2	O/O		31	18					V1302626	
R-C5	D018	201401		B0902686	52062686	SNAP RING	2	2	O/O		31	18					V1302626	
R-C5	D019	201401		B0902686	52062686	SNAP RING	2	2	O/O		31	18					V1302626	
R-C5	D020	201401		B0902686	52062686	SNAP RING	2	2	O/O		31	18					V1302626	



Part Change Information List

Date: February 28, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D017	201402		B2094095	B0274095	THERMOSTAT ASS'Y	2	2	O/O		41	3					V1302949	
R-C5	D018	201402		B2094095	B0274095	THERMOSTAT ASS'Y	2	2	O/O		41	3					V1302949	
R-C5	D019	201402		B2094095	B0274095	THERMOSTAT ASS'Y	2	2	O/O		41	3					V1302949	
R-C5	D020	201402		B2094095	B0274095	THERMOSTAT ASS'Y	2	2	O/O		41	3					V1302949	



Part Change Information List

Date: April 30, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D017	201404		D0193950	D1823950	RECEPTACLE:TRANSFER/SEPARATION UNIT:ASS'Y	1	1	O/O		45	16					V1400326	
R-C5	D018	201404		D0193950	D1823950	RECEPTACLE:TRANSFER/SEPARATION UNIT:ASS'Y	1	1	O/O		45	16					V1400326	
R-C5	D019	201404		D0193950	D1823950	RECEPTACLE:TRANSFER/SEPARATION UNIT:ASS'Y	1	1	O/O		45	16					V1400326	
R-C5	D020	201404		D0193950	D1823950	RECEPTACLE:TRANSFER/SEPARATION UNIT:ASS'Y	1	1	O/O		45	16					V1400326	



Part Change Information List

Date: May 30, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D017	201405		D0193461	D1823461	RECEPTACLE:CHARGE:ASS'Y	1	1	O/O		45	21					V1400945	
R-C5	D018	201405		D0193461	D1823461	RECEPTACLE:CHARGE:ASS'Y	1	1	O/O		45	21					V1400945	
R-C5	D019	201405		D0193461	D1823461	RECEPTACLE:CHARGE:ASS'Y	1	1	O/O		45	21					V1400945	
R-C5	D020	201405		D0193461	D1823461	RECEPTACLE:CHARGE:ASS'Y	1	1	O/O		45	21					V1400945	



Part Change Information List

Date: May 8, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D017	201504		D0194208	D1204208	PLAIN SHAFT BEARING:FUSING	2	2	O/O	N	41	107					V1500625	
R-C5	D018	201504		D0194208	D1204208	PLAIN SHAFT BEARING:FUSING	2	2	O/O	N	41	107					V1500625	
R-C5	D019	201504		D0194208	D1204208	PLAIN SHAFT BEARING:FUSING	2	2	O/O	N	41	107					V1500625	
R-C5	D020	201504		D0194208	D1204208	PLAIN SHAFT BEARING:FUSING	2	2	O/O	N	41	107					V1500625	
R-C5	D018	201504		M0805322	M4445201	HDD:320GB:AQUARIUS	1	1	O/O	N	51	26					V1402311	14060936
R-C5	D020	201504		M0805322	M4445201	HDD:320GB:AQUARIUS	1	1	O/O	N	51	26					V1402311	14060936
R-C5	D018	201504		M0805321	M0805322	HDD:OPTION:160GB:MK1676GSX	1	1	O/O	N	51	26					V1200400	
R-C5	D020	201504		M0805321	M0805322	HDD:OPTION:160GB:MK1676GSX	1	1	O/O	N	51	26					V1200400	



Part Change Information List

Date: July 2, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q' ty	New Q' ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D019	201506		D0195352	D0195372	PCB:CTL:RU-C5MS:MS25:EXP	1	1	X/O	N	51	12					V1501202	15040544
R-C5	D019	201506		D0195366	D0195352	PCB:CTL:RU-C5MS:MS25:EXP	1	1	X/O	N	51	12					V1103676	
R-C5	D019	201506		D0195351	D0195371	PCB:CTL:RU-C5MS:MS33:EXP	1	1	X/O	N	51	12					V1501202	15040544



Part Change Information List

Date: August 3, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D018	201507		D0205366	D0205376	PCB:CTL:RU-C5CS:CS25:EXP	1	1	X/O	N	51	12					V1501265	
R-C5	D020	201507		D0205366	D0205376	PCB:CTL:RU-C5CS:CS25:EXP	1	1	X/O	N	51	12					V1501265	
R-C5	D017	201507		D0195311	D0195372	PCB:CTL:RU-C5MS:MS25:EXP	1	1	X/O	N	51	12					V1501265	
R-C5	D019	201507		D0195311	D0195372	PCB:CTL:RU-C5MS:MS25:EXP	1	1	X/O	N	51	12					V1501265	
R-C5	D019	201507		D0195351	D0195371	PCB:CTL:RU-C5MS:MS33:EXP	1	1	X/O	N	51	12					V1501265	

RICOH

Part Change Information List

Date: January 5, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D020	201512		D0205365	D0205375	PCB:CTL:RU-C5CS:CS33:EXP	1	1	X/O	N	51	12					V1501265	

RICOH

Part Change Information List

Date: April 28, 2016

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D017	201604		B2050151	B2050153	PROCESSES AROUND PHOTOCONDUCTOR:R-C4:EXP:SERVICE	1	1	O/O	N	9	20					V1503505	
R-C5	D018	201604		B2050151	B2050153	PROCESSES AROUND PHOTOCONDUCTOR:R-C4:EXP:SERVICE	1	1	O/O	N	9	20					V1503505	
R-C5	D019	201604		B2050151	B2050153	PROCESSES AROUND PHOTOCONDUCTOR:R-C4:EXP:SERVICE	1	1	O/O	N	9	20					V1503505	
R-C5	D020	201604		B2050151	B2050153	PROCESSES AROUND PHOTOCONDUCTOR:R-C4:EXP:SERVICE	1	1	O/O	N	9	20					V1503505	



Part Change Information List

Date: Apeil 4, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D017	201703		B2093831	A2673831	TRANSFER/SEPARATION UNIT	1	1	O/O	N	37	23					V1602257	
R-C5	D018	201703		B2093831	A2673831	TRANSFER/SEPARATION UNIT	1	1	O/O	N	37	23					V1602257	
R-C5	D019	201703		B2093831	A2673831	TRANSFER/SEPARATION UNIT	1	1	O/O	N	37	23					V1602257	
R-C5	D020	201703		B2093831	A2673831	TRANSFER/SEPARATION UNIT	1	1	O/O	N	37	23					V1602257	



Part Change Information List

Date: June 5, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D017	201705		D0102822	D0182832	FRICTION PAD:F2:ADHESION	2	2	O/O	N	23	17					V1700087	16121166
R-C5	D019	201705		D0102822	D0182832	FRICTION PAD:F2:ADHESION	2	2	O/O	N	23	17					V1700087	16121166
R-C5	D018	201705		D0102822	D0182832	FRICTION PAD:F2:ADHESION	2	2	O/O	N	23	17					V1700087	16121166
R-C5	D020	201705		D0102822	D0182832	FRICTION PAD:F2:ADHESION	2	2	O/O	N	23	17					V1700087	16121166



Part Change Information List

Date: November 2, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D017	201711		B0903571	A1843420	BOTTLE CHUCK	1	1	O/O	N	33	8					V1701963	
R-C5	D018	201711		B0903571	A1843420	BOTTLE CHUCK	1	1	O/O	N	33	8					V1701963	
R-C5	D019	201711		B0903571	A1843420	BOTTLE CHUCK	1	1	O/O	N	33	8					V1701963	
R-C5	D020	201711		B0903571	A1843420	BOTTLE CHUCK	1	1	O/O	N	33	8					V1701963	



Part Change Information List

Date: April 2, 2018

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D017	201803		D0195366	D0195352	PCB:CTL-RU-C5MS.MS25.EXP	1	1	X/O	N	51	12					V1103676	11111618



201805 Part Change Information List

Date: June 5, 2018

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C5	D017	201805		B0903605	A2673605	CAM - HANDLE	1	1	O/O	N	37	7					V1800573	
R-C5	D018	201805		B0903605	A2673605	CAM - HANDLE	1	1	O/O	N	37	7					V1800573	
R-C5	D019	201805		B0903605	A2673605	CAM - HANDLE	1	1	O/O	N	37	7					V1800573	
R-C5	D020	201805		B0903605	A2673605	CAM - HANDLE	1	1	O/O	N	37	7					V1800573	
R-C5	D017	201805		B0913912	AA063607	PRESSURE SPRING	1	1	O/O	N	37	7					V1800573	
R-C5	D018	201805		B0913912	AA063607	PRESSURE SPRING	1	1	O/O	N	37	7					V1800573	
R-C5	D019	201805		B0913912	AA063607	PRESSURE SPRING	1	1	O/O	N	37	7					V1800573	
R-C5	D020	201805		B0913912	AA063607	PRESSURE SPRING	1	1	O/O	N	37	7					V1800573	
R-C5	D017	201805		B0903573	G0203334	SLIDER ASS`Y	1	1	O/O	N	37	7					V1800573	
R-C5	D018	201805		B0903573	G0203334	SLIDER ASS`Y	1	1	O/O	N	37	7					V1800573	
R-C5	D019	201805		B0903573	G0203334	SLIDER ASS`Y	1	1	O/O	N	37	7					V1800573	
R-C5	D020	201805		B0903573	G0203334	SLIDER ASS`Y	1	1	O/O	N	37	7					V1800573	