



Part Change Information List

Date: October 4, 2016

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Brazil-P1a	M281	201609		M2811494	M2811470	PCB:OPU	1	1	O/O	N	4	20		0			V1602913	
Brazil-P1b	M282	201609		M2811494	M2811470	PCB:OPU	1	1	O/O	N	4	20		0			V1602913	
Brazil-P1a	M281	201609		M2811493	M1291470	PCB:4.3-P:SENSOR:ASS'Y	1	1	O/O	N	4	21		0			V1602913	
Brazil-P1b	M282	201609		M2811493	M1291470	PCB:4.3-P:SENSOR:ASS'Y	1	1	O/O	N	4	21		0			V1602913	



Part Change Information List

Date: November 2, 2016

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Brazil-P1a	M281	201611		M2811058	M28222550	JCB:302SB94290:PARTS_GUIDE_C	1	1	X/O	N	6	16					V1603630	16110207
Brazil-P1b	M282	201611		M2811058	M28222550	JCB:302SB94290:PARTS_GUIDE_C	1	1	X/O	N	6	16					V1603630	16110207



Part Change Information List

Date: January 6, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Brazil-P1a	M281	201612			D2555321	JCB:302SB94280:PARTS_IC_EEPR	---	1	-	N	6	22		0	RM281018		V1602400	16061329
Brazil-P1b	M282	201612			D2555321	JCB:302SB94280:PARTS_IC_EEPR	---	1	-	N	6	22		0	RM281018		V1602400	16061329



Part Change Information List

Date: March 3, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Brazil-P1a	M281	201702		M2812531	M2822531	JCB:302SB93081:CT-3160	1	1	O/O	N	8	1					V1603630	16110207
Brazil-P1b	M282	201702		M2812531	M2822531	JCB:302SB93081:CT-3160	1	1	O/O	N	8	1					V1603630	16110207
Brazil-P1a	M281	201702		M2812538	M2822861	JCB:303RZ09060:CURSOR_RIGHT	1	1	X/O	N	8	10					V1603630	16110207
Brazil-P1b	M282	201702		M2812538	M2822861	JCB:303RZ09060:CURSOR_RIGHT	1	1	X/O	N	8	10					V1603630	16110207



Part Change Information List

Date: Apeil 4, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Brazil-P1a	M281	201703		M2818533	M2818538	JCB:302SB34091:SHEET LID TOP	1	1	X/O	N	4	27					V1603540	16100145
Brazil-P1b	M282	201703		M2818533	M2818538	JCB:302SB34091:SHEET LID TOP	1	1	X/O	N	4	27					V1603540	16100145



Part Change Information List

Date: September 1, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Brazil-P1a	M281	201707			M2811420	JCB:302SB05010:LID_OPERATION	0	1		N	4	35			RM281020		V1604016	
Brazil-P1b	M282	201707			M2811420	JCB:302SB05010:LID_OPERATION	0	1		N	4	35			RM281020		V1604016	
Brazil-P1a	M281	201707			M2811424	JCB:302SB05060:KEY_A	0	1		N	4	36			RM281020		V1604016	
Brazil-P1b	M282	201707			M2811424	JCB:302SB05060:KEY_A	0	1		N	4	36			RM281020		V1604016	
Brazil-P1a	M281	201707			M2811425	JCB:302SB05070:KEY_PAUSE	0	1		N	4	37			RM281020		V1604016	
Brazil-P1b	M282	201707			M2811425	JCB:302SB05070:KEY_PAUSE	0	1		N	4	37			RM281020		V1604016	
Brazil-P1a	M281	201707			M2811427	JCB:302SB05090:LENS_LED	0	3		N	4	38			RM281020		V1604016	
Brazil-P1b	M282	201707			M2811427	JCB:302SB05090:LENS_LED	0	3		N	4	38			RM281020		V1604016	



Part Change Information List

Date: October 2, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Brazil-P1a	M281	201709			M2812860	JCB:7SP03072001:SW.PUSH	0	1		N	6	23			RM281022		V1700517	17030330
Brazil-P1b	M282	201709			M2812860	JCB:7SP03072001:SW.PUSH	0	1		N	6	23			RM281022		V1700517	17030330
Brazil-P1a	M281	201709			M2811182	JCB:3V2LV02042:GUIDE_CASSETT	0	1		N	20	14			RM281021		V1701241	17070219
Brazil-P1b	M282	201709			M2811182	JCB:3V2LV02042:GUIDE_CASSETT	0	1		N	20	14			RM281021		V1701241	17070219



Part Change Information List

Date: November 2, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Brazil-P1a	M281	201710			M2811422	JCB:302SB05030:COVER OPERATI	0	1		N	4	39			RM281020a		V1701090	
Brazil-P1b	M282	201710			M2811422	JCB:302SB05030:COVER OPERATI	0	1		N	4	39			RM281020a		V1701090	
Brazil-P1a	M281	201710			M2811130	JCB:3V2LV31490:GEAR Z35S-Z13	0	1		N	20	15			RM281023		V1701241	17070219
Brazil-P1b	M282	201710			M2811130	JCB:3V2LV31490:GEAR Z35S-Z13	0	1		N	20	15			RM281023		V1701241	17070219



Part Change Information List

Date: November 2, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Brazil-P1a	M281	201711		M2815541	M2815544	PCB:CTL:BRA-P1A:50PPM	1	1	O/O	N	6	20					V1701904	17091078



Part Change Information List

Date: February 1, 2018

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Brazil-P1b	M282	201801		M2815542	M2815545	PCB:CTL:BRA-P1B:60PPM	1	1	O/O	N	6	20					V1701904	17091078



Part Change Information List

Date: April 26, 2018

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Brazil-P1a	M281	201804			M2814458	JCB:302LV28241:SPRING_ACTUAT	-	1		N	18	17			RM281024		V1800251	18020553
Brazil-P1b	M282	201804			M2814458	JCB:302LV28241:SPRING_ACTUAT	-	1		N	18	17			RM281024		V1800251	18020553



Part Change Information List

Date: December 28, 2018

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
B-P1b	M003	201811		AA143570	D2706453	SHAFT:MI	2	2	O/O	N	51	9					V1802366	
B-P1b	M003	201811		D0592512	D0599501	PAPER FE	1	1	O/X	N	53 *				RD059114		V1800579	
B-P1b	M003	201812		M0026871	M0026873	HDD:PRO	1	1	O/O	N	143	1					V1602434	16070248
B-P1b	M003	201901		D0592550	D0599502	PCB:URB I	1	1	O/X	N	55	24			Y		V1800579	
B-P1b	M003	201902		A2943451	D0BX3451	LEVER:TO	2	2	O/O	N	61	11					V1801987	
B-P1c	M004	201811		AA143570	D2706453	SHAFT:MI	2	2	O/O	N	51	9					V1802366	
B-P1c	M004	201811		D0592512	D0599501	PAPER FE	1	1	O/X	N	53 *				RD059114		V1800579	
B-P1c	M004	201812		M0026871	M0026873	HDD:PRO	1	1	O/O	N	143	1					V1602434	16070248
B-P1c	M004	201901		D0592550	D0599502	PCB:URB I	1	1	O/X	N	55	24			Y		V1800579	
B-P1c	M004	201902		A2943451	D0BX3451	LEVER:TO	2	2	O/O	N	61	11					V1801987	