RICOH

Modification Bulletin

PAGE: 1/1

Model: Pegasus-C	2	ate: 26-Jun	-08	No.: MD045001					
Modified Article:	CONIJ board		Prepared by: K. Moriizumi						
From: 1st Tech. Su	pport Sec. Service Support								
Reason for	Parts catalog correction	U Vendor	cha	ange	Other				
Modification:	To facilitate assembly	🗌 To improve reliabili			🗸 🗌 To meet standards				
	Part standardization	Product	t Sa	afety	()			

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
D0455190	D0455191	PCB: CONIJ: P-C2	1 - 1	0/0	29	5	

Change/Reason: The part number was corrected.

RICOH

Modification Bulletin

PAGE: 1/1

Model: Pegasus-C	2	ate: 14-Jul	-08	No.: MD045002					
Modified Article:	Harness - Paper Exit Section		Prepared by: K. Moriizumi						
From: 1st Tech. Su	pport Sec. Service Support								
Reason for	Parts catalog correction Uendor cl			ange	Other				
Modification:	🗌 To facilitate assembly 🛛 🗌 To impro			e reliability	🗌 To mee	et standards			
	Part standardization	Product	t Sa	afety	()			

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
D0455543	D0455550	Harness: Paper Exit Section	1 - 1	0/0	39	1	

Change/Reason: The part number was corrected.

RICOH

Modification Bulletin

PAGE: 1/1

Model: Pegasus-C	2	ate: 15-Jul-	·08	No.: MD045003					
Modified Article:	Lens Unit		Prepared by: K. Moriizumi						
From: 1st Tech. Su	pport Sec. Service Support								
Reason for	Parts catalog correction	U Vendor	ch	ange	Other				
Modification:	☐ To facilitate assembly ☐ To improv			e reliability	🗌 To mee	et standards			
	Part standardization	Product	t Sa	afety	()			

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
D0201698	D0201703	Lens Unit	1 - 1	0/0	11	21	

Change/Reason: The part number was corrected.



Part Change Information List

Model	Code	PCIL Number PCIL Correction	Old part number	New part number		Description
VM Option TypeH	M344	201601	M3445722	M3445522	PCB:W-LAN1S:LP:EU:ASS'Y	
VM Option TypeH	M344	201601	M3445701	M3445521	PCB:W-LAN1S:LP:NA:ASS'Y	

Date: Feburary 1, 2016

Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
1	1	O/O	N			G				V1000908	10041233
1	1	0/0	Ν			J				V1001013	10050136

RICOH Part Change Information List

Date: November 2, 2016

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
VM Option TypeH	M344	201610		M3445522		PCB:W-LAN1S:LP:EU:ASS'Y			O/X	Ν	*	*				Only EU	V1603299	Ī
VM Option TypeH	M344	201610		M3445521		PCB:W-LAN1S:LP:NA:ASS'Y			O/X	Ν	*	*				Only NA	V1603299	
VM Option TypeH	M344	201610		M3445542		PCB:W-LAN1S:LP-11G:EU:ASS'Y			O/X	Ν	*	*				Only EU	V1603299	