



## Part Change Information List

Date: May 12, 2017

| Model | Code | PCIL Number | PCIL Correction | Old part number | New part number | Description                    | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB      | Note | Ref Number | ECN Number |
|-------|------|-------------|-----------------|-----------------|-----------------|--------------------------------|----------|----------|-----|------|------|-------|-----|---------|----------|------|------------|------------|
| HL-F2 | H560 | 201704      |                 | H5601709        | H5602601        | AQN:D00E8R008:SIDE_COVER_R2    | 1        | 1        | X/X | N    | 17   | 11    |     |         | RH560001 |      | V1603375   | 16100283   |
| HL-F2 | H560 | 201704      |                 | H5602001        | H5602602        | AQN:D00GD4002:MAIN_PCB_ASSY2   | 1        | 1        | X/X | N    | 23   | 1     |     |         | RH560001 |      | V1603375   | 16100283   |
| HL-F2 | H560 | 201704      |                 | H5602002        | H5602603        | AQN:D00FZR001:MODEM_PCB_ASSY2  | 1        | 1        | X/X | N    | 23   | 2     |     |         | RH560001 |      | V1603375   | 16100283   |
| HL-F2 | H560 | 201704      |                 | H5602003        | H5602604        | AQN:D00GJK001:LOW_VOLTAGE_P2   | 1        | 1        | X/X | N    | 23   | 3     |     |         | RH560001 |      | V1603375   | 16100283   |
| HL-F2 | H560 | 201704      |                 |                 | H5602606        | AQN:D00FE6001:AO_HARNESS_ASSY2 | 0        | 1        |     | N    |      |       |     |         | RH560001 |      | V1603375   | 16100283   |