

Model: Kaiser1		Date: 25-Aug-00	No.: MH306007
Modified Article: Parts Catalog Correction		Prepared by: M. Mano	
From: Technical Services Dept., GTS Division			
Reason for Modification:	<input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

Please make the following corrections to your parts catalogs.

PIF (H144)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	H3065148	PIF – FCU Harness NA	1		5	1	*1
H3064640	H3064642	Rear Bracket	1	X/O	5	2	*2

*1: This part number is for the USA model only.

(This part number was not included in the original table: it is not a new part)

*2: This part number was misprinted.

PFU (H110)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
H5194547	A8601140	Spring Plate	1	X/O	3	12	*1
-	H5194736	Balancer	2	X/O	5	20	*2
-	H5194725	Paper Feed Shaft	1	X/O	5	22	*2

*1: The new part has been used since the March mass production lot.

*2: This part number is for the Asian model (H110-85) only.

(This part number was not included in the original table: it is not a new part)

Model: Kaiser1		Date: 07-Nov-01	No.: MH306009
Modified Article: Kaiser1 Parts Catalog Correction		Prepared by: M. Mano	
From: Technical Services Dept., GTS Division			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

The following parts have been modified to increase paper feed performance and reliability.

PFU (H110)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
H5194717	H3103372	Paper Feed Stay	1	O/O	4	3	
H5194731	H3103368	Paper End Sensor Bracket	1	O/O	4	9	
H5194540	H3103367	Slide Rail	1	O/O	6	5	
H5194756	H3103369	Motor Bracket	1	O/O	6	14	
H5194797	H3103365	Spring Plate	1	O/O	8	5	
H3063501	H3103364	Decal – Size Indication	1	O/O	8	24	
H5194776	H3103373	Paper Tray	1	O/O	8	28	

Model: Kaiser1		Date: 08-Nov-01	No.: MH306010
Modified Article: Kaiser1 Parts Catalog Correction		Prepared by: M.Mano	
From: Technical Services Dept., GTS Division			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input checked="" type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

One of the Transport Relay Rollers may shift position along the shaft when clearing a paper feed jam, which can then cause another jam. The roller has been modified to ensure this does not occur.

PFU (H110)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
H5194741	H5194742	Transport Relay Roller	1	X/O	6	3	

Model: Kaiser 1		Date: 23-Jan-03	No.: MH306020
Modified Article: Parts Catalog Corrections		Prepared by: M. Mano	
From: Technical Services Sec. Service Planning Dept.			
Reason for Modification:	<input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

The following part has been changed to increase paper feed reliability.

PFU (H110)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
H5194781	H3103376	Separation Hook - Front	1	X/O	9	11	
H5194782	H3103377	Separation Hook - Rear	1	X/O	9	15	

Model: Kaiser 1		Date: MH306021	No.: MH306021
Modified Article: Parts Catalog Corrections		Prepared by: M. Mano	
From: Technical Services Sec. Service Planning Dept.			
Reason for Modification:	<input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

The following parts have been changed due to parts standardization with the Model K3.

Mainframe (H306)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
H3063125	H3103125	Interlock Switch Cover	1	O/O	37	10	
G0291064	H3105072	Toner End Sensor	1	O/O	31	20	

PFU (H110)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AX200129	H3105042	Magnetic Clutch	1	O/O	5	24	
H3103364	-	Decal - Size Indication	1→0	-	9	24	
H5194784	H3103378	Bottom Plate	1	X/O	9	25	