വയത	叽
160	lnl

Modification Bulletin

PAGE: 1/1

Model: Adonis-C2 Printer Unit Type 1045 Modified Article: Printer Option DIMM From: 1st Tech. Support Sec. Service Support Dept.				e: 6-Aug-04		No.: MB362001		
Modified Article:	Printer Option DIMM	Prepared by: K. Takagi						
From: 1st Tech. S	upport Sec. Service Support Dep							
Reason for	☐ Parts catalog correction	☐ Vend	☐ Vendor change		☐ To n	neet standards		
Modification:	☐ To facilitate assembly	☐ To improve rel		reliability ()		
	☐ Part standardization	Othe	Other					

The following parts have been registered per a request from the field.

Old part	New part	Description	Q'ty	int	Page	Index	Note
number	number						
	B3625318	PCB: DIMM: PRT: EXP: ASS'Y	1	ı	-	-	



Part Change Information List

Date: March 18, 2009

		PCIL	PCIL	Old	New												
Model	Code	Number	Correction	part number	part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Adonis-C2 Printer Unit Type 1045	B362	200903		AW010048	AW010106	PAPER FEED SENSOR	1	1	O/O		3	6					V0804408