വത്ത	吅
160	띪

Modification Bulletin

Model: Adonis-C2 P	rinter/Scanner Unit Type 1045	e: 6-Aug-04		No.: MB361001		
Modified Article: P	rinter/Scanner Option DIMM	Prepared by: K. Takagi				
From: 1st Tech. Sup	port Sec. Service Support Dep					
Reason for	Parts catalog correction	☐ Vendo	or cha	ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliability		()	
	☐ Part standardization					

PAGE: 1/1

The following parts have been registered per a request from the field.

Old part	New part	Description	Q'ty	int	Page	Index	Note
number	number						
	B3615318	PCB: DIMM: PRT/SCN: EXP: ASS'Y	1	ı	-	-	



Part Change Information List

Date: July 31, 2009

Model	Code	PCIL Nr.	PCIL	Old part	New part		Description	Old O'ty	New O'ty	Int 3DPC	Page Inde	y Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr
Model		Correction	number	number		Description	Cla Q ty New Q t	NOW Q ty	ty iiit obi c	o rage maez	x 061	Oet IIIt	IIID	14018		LOIVINI.	
A-C2 Printer/Scanner Unit Type 1045 E	3361	200907		AW010048	AW010106	PAPER FEED SENSOR		1	1	0/0	3	6				V0804408	
•																	