RIGOH

Technical Bulletin

PΑ	GE:	1/3
----	-----	-----

Model: Adonis-C3			Date: 27-Jun-03		03	No.: RB082016
Subject: Service Manual Correction (Fax Option)				Prepared by: K. Takagi		
From: 1st Tech. Support Sec. Service Support Dept.						
Classification:	Classification: Troubleshooting Part info		ormat	tion	☐ Action	required
		☐ Electric	al		⊠ Service	e manual revision
	☐ Paper path	Transm	it/rec	eive	☐ Retrof	fit information
	Other ()					

Please make the following corrections to your Model A-C3 Fax Option Service Manuals (machine code: B547).

Revised items are <u>underlined</u> and items to be deleted are in *italics*.

1. Section 1 (Installation)

1.4.1 JBIG A892 (Page 1-14)

REVISE the following (underlined portions):

- 1.4.1 FAX FUNCTION UPGRADE BOARD
- 2. Section 3 (Service Tables)
 - 3.1 Service Program Mode SP1-XXX (Bit Switches) (Page 3-2)

DELETE SP1-102 and SP1-110 from the table below.

Note: SP1-102 has been renamed as "SP3-201" – see next page.



Technical Bulletin

PAGE: 2/3

Model: Adonis-C3 Date: 27-Jun-03 No.: RB082016

3.2.2 FAX Switches Page (3-18 ~ 22)

REVISE titles in the SP tables from "1-102-XXX" to "3-201-XXX", as this SP has been renamed.

Also, REVISE the underlined portions below, as there have been some revisions applied to the content.

FAX Switch 08 -	Not used	(do not chan	<u>ge the settings)</u>	SP No. 3-201-009

FAX Switch 09 - Not	used (do not chang	<u>ge the settings)</u>	SP No. 3-201-010
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		 	

FAX Switch 0A		SP No. 3-201-011	
No	No FUNCTION COMMENTS		
0-3	Not used Do not change the settings.		
4	MTF filter level (Colored background special original mode)		
to	The value can be between 0 (Off) and F. For a weaker threshold, input a lower value.		
7	Default setting: 7		
	This setting is independent from the threshold specified by the copier SP modes.		

FAX	Switch 0C	<u>SP No. 3-201-013</u>	
No	FUNCTION	COMMENTS	
0	Action when an original jam has occurred while scanning the original into memory for memory tx 0: Continues scanning after recovery 1: Stops scanning and erases all scanned pages for that job	This bit is only effective when parallel memory tx is disabled (user parameter 07 - bit 2). If parallel memory tx is enabled, the machine always erases the scanned pages when an original jam occurs. The machine then asks the user to retry from the first page, even if the parallel memory tx is not actually used. O: The machine displays a message asking the user to put the jammed page back into the original stack, and continues scanning. The message is displayed for the time period specified by scanner switch 0E, bit 2. 1: The machine erases all the scanned pages and asks the user to retry from the first page.	
1	Setting when an original size		
to	cannot be recognized		
2	Bit 2 1 Setting 0 0 No original 0 1 A5 □ 1 0 A5 □ 1 1 No original		
<u>3-7</u>	Not used	Do not change the settings.	



Model: Adonis-C3

Technical Bulletin

 Ulletin
 PAGE: 3/3

 Date: 27-Jun-03
 No.: RB082016

FAX	Switch 0E	SP No. 3-201-015	
No	FUNCTION	COMMENTS	
0	Not used	Do not change the settings.	
1	Scan resolution unit	This bit determines which resolution unit will be	
	0 : mm	used for scanning a fax message.	
	1: inches	Default setting: mm	
<u>2-7</u>	Not used	Do not change the settings.	

FAX Switch 10 ~ 1F - Not used (do not change the settings)

3. SPECIFICATIONS

2 Capabilities of Programmable Items (Page Spec-2)

REVISE the following (underlined portions).

Note: "With HDD" column has been deleted.

Item	Standard	With Fax Function Upgrade Unit
Quick Dial	<u>500</u>	1200 <u>(2000*)</u>
Groups	64	64
Destination per Group	500	500
Boxes (Information/Personal/Transfer)	150	400
Destinations dialed from the ten-key pad overall	100	1000
Programs	100	200
Auto Document	6	18
Communication records for Journal stored in the memory	200	1000
Specific Senders	30	50

^{*} With the Printer/Scanner Option