RICOH

## Technical Bulletin

**PAGE: 1/1** 

Model: R-C5 By-Pass Tray			Dat	Date: 23-Oct-09		No.: RD370001		
Subject: Harness				Prepared by: T. Nihei				
From: 1st Tech. Support Sec. Service Support Dept.								
Classification:	☐ Troubleshooting	⊠ Part info	ormat	tion	☐ Action	required		
	☐ Mechanical	☐ Electrical ☐ Transmit/receiv			☐ Service manual revision			
	☐ Paper path			eive	☐ Retrof	fit information		
	☐ Product Safety	Other (		)				

Please apply the following changes to your Parts Catalogs.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
D3705267		Harness - Manual Feed	1				
	D3705277	Harness - Manual Feed :MAIN :Service	1	X/O	4	11	
1105 0488		Harness Clamp	1				
	11050508	HARNESS CLAMP - LWS-0711	1	X/O	4	106	

**Change:** The P/N shown in bold italics was corrected.

Reason: The P/N announced in MB #MD370001was incorrect.