

=====
*** Basic Information ***
=====

[Create date] 2019/09/19

[Program Name] Inserter_CI4030

[Version] 01.000:03

[PCB No.] D3D75100C

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D3D75300B

[File Information]

File Name D3D75300B.fwu

File Type Module for Service

Size 0.13 MB (131576 byte)

[Availability of RFU] No

[Production reflection] 2019/10

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]

Rank C

Symptom corrected:

- When the finisher is equipped with cover interposer, roller stains might be transferred to the paper on horizontal transport path.

[Modification history]

Version 00.100:03
1st Mass production