

CONTROLLER INTERFACE TYPE F (A839)

PARTS CATALOG


INTRODUCTION

This chapter instructs you the numbers and names of parts on this machine.

INDEX to PARTS CATALOG

1.Controller Interface Type F (A839)	2
PARTS INDEX	5

1.Controller Interface Type F (A839)



1.Controller Interface Type F (A839)



Index No.	Part No.	Description	Q'ty Per Assembly
1	A839 5815	Upper Shielding Cover	1
2	A839 5216	Harness - DC Power Supply Unit	1
3	A848 5300	Power Supply Unit - 120V	1
3	A848 5310	Power Supply Unit 230V 54W	1
4	AA14 3020	Stepped Screw - M4	2
5	A839 1050	Stud	2
6	A839 5830	Interface Gasket	2
7	A839 5821	Left Shielding Cover	1
8	A839 5218	Harness I/F Video	1
9	A848 5111	PCB BUSSW	1
10	A839 5810	Base Ass'y	1
11	A839 5831	Upper Gasket - Right Shielding Cover	1
12	A839 5832	Lower Gasket - Right Shielding Cover	1
13	A839 5814	Right Shielding Cover	1
14	A839 1200	Upper Cover	1
15	A848 1451	Operation Panel - NA	1
15	A848 1452	Operation Panel - 230V	1
16	A839 5222	Ground Wore	1

Index No.	Part No.	Description	Q'ty Per Assembly
101	0451 3006B	Tapping Screw - M3X6	
102	0451 4006B	Tapping Screw - 4x6	
103	0451 4008H	Tapping Screw - 4x8	
104	0954 3006Z	Screw - M3x6	
105	1105 0481	Harness Clamp:LWS-1.5SL(VOBK)	
106	1105 0243	Wire Saddle	
107	0954 4008Z	Double Sens Screw - M4X8	
108	1105 0487	Harness Clamp:LWS-0511	

PARTS INDEX

Part No.	Description	Page and Index No.
A839 1050	Stud	3- 5
A839 1200	Upper Cover	3- 14
A839 5216	Harness - DC Power Supply Unit	3- 2
A839 5218	Harness I/F Video	3- 8
A839 5222	Ground Wore	3- 16
A839 5810	Base Ass'y	3- 10
A839 5814	Right Shielding Cover	3- 13
A839 5815	Upper Shielding Cover	3- 1
A839 5821	Left Shieding Cover	3- 7
A839 5830	Interface Gasket	3- 6
A839 5831	Upper Gasket - Right Shielding Cover	3- 11
A839 5832	Lower Gasket - Right Shielding Cover	3- 12

Part No.	Description	Page and Index No
AA14 3020	Stepped Screw - M4	3- 4
A848 1451	Operation Panel - NA	3- 15
A848 1452	Operation Panel - 230V	3- 15
A848 5111	PCB BUSSW	3- 9
A848 5300	Power Supply Unit - 120V	3- 3
A848 5310	Power Supply Unit 230V 54W	3- 3
0451 3006B	Tapping Screw - M3X6	3-101
0451 4006B	Tapping Screw - 4x6	3-102
0451 4008H	Tapping Screw - 4x8	3-103
0954 3006Z	Screw - M3x6	3-104
0954 4008Z	Double Sens Screw - M4X8	3-107
1105 0243	Wire Saddle	3-106
1105 0481	Harness Clamp:LWS-1.5SL(VOBK)	3-105
1105 0487	Harness Clamp:LWS-0511	3-108