## RICOH

## Modification Bulletin

PAGE: 1/1

Model: V-C1: Copy Connector Type 3260 Date: 12-Feb-08 No.: MB328001

Modified Article: Keytop: Function			Prepared by: Y.Ikeda		
From: 2nd Tech. Support Sec. Service Support Dept.					
Reason for	☐ Parts catalog correction	☐ Vendor cha	ange	⊠ Other	
Modification:	☐ To facilitate assembly	☐ To improve reliability			
	☐ Part standardization	☐ Product Sa	afety	(WEEE compliance)	

New part	Description	Q'ty	Page	Index	Note
number					
B2231533	KEYTOP: FUNCTION: NA	2	3	8	
B2231593	KEYTOP: FUNCTION: EU	2	3	8	
16071715	FERRITE CORE - RFC-5	2	3	9	

**Change/Reason:** These parts are added.

