

Model: Russian-P Mailbox		Date: 11-Dec-01	No.: MG518001
Modified Article: DC Motor		Prepared by: K.Misugi	
From: Technical Services Dept., GTS Division			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

The Stepper Motor and Main Control Board for the Russian-P Mailbox Unit have been changed so that the Mailbox Unit can also be used with the Russian-P2.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G5185100	G5185105	Main Control Board	1-1	X/O	5	14	1
AX040116	AX040200	Stepper Motor – DC24V	1-1	X/O	9	4	1

Note: The Main Control Board and Stepper Motor must be replaced together as a set.

RCL (Japan) Production

MODEL NAME	DESTINATION	CODE	SERIAL NO.
CS370	USA/Europe/Asia	G518-17	P21 007 00001
CS370	Infotec	G518-26	4F5 070 0001



Part Change Information List

Date: March 18, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Russian-P Mailbox (CS370)	G518	200903		G5181245	C6851245	LEVER:RELEASE	1	1	O/O		7	19					V0803129
Russian-P Mailbox (CS370)	G518	200903		G5182555	C6852555	BRACKET:TIGHTENER	1	1	O/O		9	14					V0803129
Russian-P Mailbox (CS370)	G518	200903		AA063337	B7623337	COMPRESSION SPRING:DRIVEN	12	12	O/O		5,7	4,3					V0804008



Part Change Information List

Date: May 30, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
R-P Mailbox (CS370)	G518	200905		G5661220	G5661210	REAR SIDE PLATE	1	1	O/O		9	1					V0803314
R-P Mailbox (CS370)	G518	200905		G5661210	C6851210	SIDE PLATE:REAR:ASS'Y	1	1	O/O		9	1					V0803314