

Modification Bulletin

PAGE: 1/1

Model: Iris/Lilac Printer Controller Date			9: 15-Oct-99		No.: MA752001		
Modified Article: System CD			Prepared by: Chisato Tsuji				
From: Technical Ser	vice Dept., GTS Division						
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor cha☐ To improve☐ Other				neet standards)	

Due to upgrade of the system CD from Ver.1.0 to Ver.1.01, the part number has been changed as follows.

Old part	New part	Description	Q'ty	Int	Page	Index
number	number					
A7529500-	Ī	System CD English: 45004256	1-0	X/O	2	15
	[∟] A7529501	System CD English V1.01: 45008367	0-1			

Major improvements

Description	Details
Yellow print problem for A3 paper size	When printing scanned images with the A3 400dpi setting, only yellow toner will be used for printing.
A4 paper size and White lines	White line appears when printing out on A4 size from Power Point.
New Bootrom	"Please Wait" displays after turning off/on the power while the controller is booting up.
Full Color Speed printing when sorting	Print speed is slow when using a sorter.
Color Shift	The color may shift when printing out. e.g. M to C, C to Y etc.
SWOP Quick sent from RC	Adopted SWOP simulation sent from RC.
Spanish Appletalk Queue name change	Spanish Appletalk Queue name from "impression" to "imprimir"

Cut-in serial number

Model Name	Destination	Code	Serial Number
Color Controller E-300	USA	A752-01	A9039890072 -
Color Controller E-300	Europe, etc.	A752-02	A9039899801 -