

Model: Multi-Folding Unit FD5010 (D521)	Date: 20-Jun-11	No.: RD521001
---	-----------------	---------------

Subject: Firmware Release Note: Multi-Folding Unit FD5010		Prepared by: K.Tsutsui	
From: PPBG Service Planning Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **Multi-Folding Unit**.

Version	Program No.	Effective Date	Availability of RFU
01.010:07	D5215300B	1st Mass production	Available

**Note: Definition of Availability of RFU via @Remote**

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
01.010:07	1st Mass production