Modification Bulletin

PAGE: 1/1

Model: Manual Fee	eder for N-C2/Be-C1	ate: 17-Sep	p-08	No.: MD333001				
Modified Article:	Parts Catalog		Prepared by: F.Noguchi					
From: 2nd Tech. S	upport Sec. Service Support							
Reason for	Parts catalog correction	U Vendor	ch	ange	Other			
Modification:	To facilitate assembly	🗌 To impr	ove	e reliability	To meet standards			
	Part standardization	Product	t Sa	afety	()		

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	B8891451	Guard: Cover: Connecting	0 - 2		3	17	
	B8891678	Decal: Paper jam: 1	0 - 1		3	19	
D3337691		Decal: Paper Jam	1 - 1	X/O	3	20	
	D3337699	Decal: Paper Jam: Manual Feed Unit	1 - 1	X/U	3	20	
11050348		Clamp	n n	X/O	2	109	
	11050706	Clamp: RSPC-325P	n - n	~/0	3	109	

Change/Reason: Parts standardization with new model.

Note: These changes are included in the Manual Feeder Parts Catalog revision for N-C2/Be-C1. The Parts Catalog was revised due to the release of the Be-C1.

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
Manual Feeder	120/60	USA, Canada, S. America	D333-17	M35810xxxxx
Manual Feeder	220-240/50, 60	Europe, Asia, Oceania, etc	D333-27	M3580900001

Modification Bulletin

Reissued: 28-Jan-09

Model: Manual Feeder for N-C2/Be-C1

Date: 26-Jan-09

No.: MD333002a

MB Reissue

The	items	in	bold	italics	have	been	corrected.
-----	-------	----	------	---------	------	------	------------

Modified Article:	Cover: Upper Front	Prepared by: F.Noguchi						
From: 2nd Tech. S	upport Sec. Service Support	Dept.						
Reason for	Parts catalog correction	Vendor cha	ange	Other				
Modification:	To facilitate assembly	🗌 To improve	e reliability	🗌 To me	eet standards			
	Part standardization	Product Sa	afety	()			

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
D3337651	D3337668	COVER: UPPER FRONT	1 - 1	0/0	5	12	

Change/ Reason: Due to parts standardization

Modification Bulletin

PAGE: 1/1

Model: Manual Fee	eder for N-C2/Be-C1	Da	ate: 26-Fet	o-09	No.: MD333003			
Modified Article:	Decal: Paper Jam: 1		Prepared by: F.Noguchi					
From: 2nd Tech. S	upport Sec. Service Support							
Reason for	Parts catalog correction	ch	ange	Other				
Modification:	☐ To facilitate assembly ☐ To in			e reliability	et standards			
	Part standardization	Product	Sa	afety	()		

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B8891678	B8891679	DECAL: PAPER JAM: 1	1 - 1	X/O	3	19	

Change/Reason: The size of the decals was changed for use on the Be-C1.

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
Manual Feeder	120/60	USA, Canada, S. America	D333-17	M35903xxxxx
Manual Feeder	220-240/50, 60	Europe, Asia, Oceania, etc	D333-27	M35903xxxxx

Part Change Information List

Date: March 31, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int 3D	OPC Page	Index Se	t Set Int	RTB	Note	Ref. Nr.	ECN Nr.
N-C2 Manual Feeder	D333	201003		D3337690	D3337670	GUIDE:COVER:UPPER FRONT	3	3	X/O	5	13				V1000205	10010486
N-C2 Manual Feeder	D333	201003		D3337690	D3337670	GUIDE:COVER:UPPER FRONT	3	3	X/O	5	13				V1000205	10010486