## RICOH

## **M**odification **B**ulletin

**PAGE: 1/1** 

Model: Be-C1: Folder FD6500B Da				ate: 13-Feb-09		No.: MB890001
Modified Article:	Prepared by: F.Noguchi					
From: 2nd Tech. Support Sec. Service Support Dept.						
Reason for	☐ Parts catalog correction	☐ Vendor	cha	ange	Other	
Modification:	☐ To facilitate assembly	☐ To improve		e reliability	☐ To me	et standards
	□ Part standardization	☐ Product Safety		afety	(	)

Old part	Description		Page	Index	Note
number					
D4361244	COVER:INTERFACE: KEY CARD	1 - 0	3	4	
B8891694	COVER:INTERFACE: SCANNER: DIVISION	1 - 0	3	5	

**Change:** The parts in the table were deleted as service parts. **Reason:** These parts are now included in the Be-C1 accessories.

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
Folder 6500B	120/60	USA, Canada, S. America	B890-17	From first production
Folder 6500B	220-240/50, 60	Europe, Asia, Oceania, etc	B890-27	V34902XXXXX

## RICOH

## **M**odification **B**ulletin

**PAGE: 1/1** 

Model: Be-C1: Folder FD6500B			ate: 13-Feb	-09	No.: MB890002	
Modified Article: Decal: Paper Jam: 1					by: F.Nog	guchi
From: 2nd Tech. Support Sec. Service Support Dept.						
Reason for	☐ Parts catalog correction	☐ Vendor	cha	ange	Other	
Modification:	☐ To facilitate assembly	o facilitate assembly 🔲 To improv		e reliability	☐ To me	et standards
☐ Part standardization ☐ Product Sa		Sa	afety	(	)	

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B8891678	B8891679	DECAL: PAPER JAM: 1	1 - 1	X/O	3	30	
					15	7	
					17	18	
					19	33	
					27	23	
					29	22	
B8902950	B8902951	DECAL: MULTI-LANGUAGE: CROSS	1 - 1	X/0	49	7	
					53	4	
					55	14	
					83	18	
					87	18	
					97	4	
					99	24	
					105	25	
					109	3	
					123	20	

Change/Reason: The size of the decals was changed for use on the Be-C1.

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
Folder 6500B	120/60	USA, Canada, S. America	B890-17	V340903XXXXX
Folder 6500B	220-240/50, 60	Europe, Asia, Oceania, etc	B890-27	V340903XXXXX