ര	пп
[(比(0)	11 12 1
ハシワリ	

Modification Bulletin


P	Α	G	Ε	:	1	1

Model: Kir-C2 GW Expansion Unit (B658)			Date	e: 6-Jul-04		No.: MB658001
Modified Article: Parts Catalog Correction				Prepared	by: M.	Ishihara
From: 1st Tech. Sup	port Sec. Service Support Dep					
Reason for	□ Parts catalog correction	☐ Vendo	☐ Vendor change		☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliability		()	
	☐ Part standardization	☐ Other	•			

Please correct your Parts Catalogs as follows:

Page 2 and 3 - Addition -

Part number	Description	Q'ty	Index	Note
B6201461	Fax Decal – NA ASIA	1	20	
B6201450	Fax Cover EU	1	21	
B6201421	Fax Cover NA	1	21	
B6581455	Expansion Sheet	1	22	



RIGOH

Reason for

Modification:

Modification Bulletin

Other

Da	ate: 20-Jul-04	ļ	No.: MB658002	
l.	Prepared	by: M.	Ishihara	
☐ Vendor (☐ To impro	change ove reliability	☐ To n	neet standards	_

PAGE: 1/1

Please note the following changes:

Model: Kir-C2 GW Expansion Unit (B658)

From: 1st Tech. Support Sec. Service Support Dept.

Modified Article: Fax Cover

1. A vinyl bag was added to the Fax Cover for more protection.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Note: This is the only difference, so both the new and old parts can be used in the field.

2. The page number for the Fax Cover was corrected:

Incorrect: pg. 12 Correct: pg. 3

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B6201421	B6201415	Fax Cover NA	1-1	O/O	3	21	
B6201450	B6201422	Fax Cover EU	1-1	O/O	3	21	

NOTE: The first P/N for the Fax Cover was announced in MB658001.

	ΙПЛ
II いし	IJπI

Modification Bulletin

PAGE: 1/	1

Model: Kir-C2 GW Expansion Unit (B658)			e: 22-Apr-0	5	No.: MB658003		
Modified Article: PCB Ct I: Exp : Ass'y					by: M.	Ishihara	
From: 1 st Tech. Sup	port Sec. Service Support Dep						
Reason for	☐ Parts catalog correction	☐ Vend	Vendor change		☐ To n	neet standards	
Modification:	☐ To facilitate assembly			()			
	☐ Part standardization	☐ Othei	r				

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B6585700	B6585701	PCB Ct I: Exp : Ass'y	1-1	X/O	5	2	

Change: A jumper wire was added and a resistor (R524) was removed from the controller

board.

Reason: To improve the power distribution to the Piccolo ASIC.

Note: This change was applied to the machine production line from October 2004.

RICOH

Modification **B**ulletin

PAGE: 1/1

Model: Kir-C2.5 GV	W Expansion Unit (B658-57)]	Da	ate:14-Dec	-05	No.: MB658004	-
Modified Article: PCB CTL				Prepared	by: M. Ish	nihara	
From: 1st Tech. Su	pport Sec. Service Support D	Dept.					
Reason for	□ Parts catalog correction	☐ Vendor o	cha	ange	Other		
Modification:	☐ To facilitate assembly	☐ To impro	ove	reliability	☐ To me	et standards	
	☐ Part standardization	☐ Product	Sa	fety	()	

Kir- C2 Part Number	Kir- C2.5 Part Number	Description	Q'ty	Int	Page	Index	Note
B6585701	B6585757	PCB CTL	1-1	X/O	5	2	

Change/Reason: The controller PCB for the Kir-**C2.5** was newly added.

Note: This PCB can also be used on the Kir-C2.



Part Change Information List Date: April 30, 2009

			PCIL													
		PCIL	Correcti	Old	New											
Model	Code	Number	on	part number	part number	Description	Old Q'ty	New Q'ty Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
KIR-C2:Feature Expansion Board OP:EXP/GEF	R B658	200904		B6581421	B6581451	OPERATION SUB-UNIT:EXPAND:EXP:ASS'Y	1	1 0/0		2	*					