

Model: Finisher Adapter Type-A		Date:10-Jul-06	No.: MB698001
Modified Article: EPROM on Finisher Adapter Type-A		Prepared by: H. Matsui	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> Other
	<input type="checkbox"/> To facilitate assembly	<input type="checkbox"/> To improve reliability	<input type="checkbox"/> To meet standards
	<input checked="" type="checkbox"/> Part standardization	<input type="checkbox"/> Product Safety	()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B6985800	B6985810	EPROM:ACCESSORY:ASS'Y	1-1	X/O	3	1	

Change: The parts in the table were changed.

Reason:

1. Finisher Adapter Type-A has been discontinued and it has been upgraded to Finisher Adapter Type-B. With this change, its ROM has been standardized to Finisher Adapter Type-B.

2. Fixed: No Punch with Thick 1 is selected.

Model: Finisher Adapter Type-A / B		Date: 12-Sep-06	No.: MB698002
Modified Article: EPROM on Finisher Adapter Type-A / B		Prepared by: H. Matsui	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> Other
	<input type="checkbox"/> To facilitate assembly	<input checked="" type="checkbox"/> To improve reliability	<input type="checkbox"/> To meet standards
	<input type="checkbox"/> Part standardization	<input type="checkbox"/> Product Safety	()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B6985810	B6985820	EPROM:ACCESSORY:ASS'Y	1-1	X/O	3	1	

Change: The parts in the table were changed.

Reason:

1. Improved: Reliability of stapling in Thick2 paper mode with GBC Stream Punch III.