RICOH

Modification Bulletin

PAGE: 1/2

Model: Russian-C4 G3 Unit Date					6	No.: MB768001	
Modified Article: CCUIF and Harness					Prepared by: S. Tomoe		
From: Technical Service Dept., GTS Division							
Reason for			☐ Vendor change			neet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability☐ Other		e reliability	(HO	HS)	
	☐ Part standardization						

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B7125190	B7685140	PCB: CCUIF	1-1	X/O	3	9	
B7685270	B7685240	HARNESS: FCU-CCU	1-1	X/O	3	4	

Change: The materials for the part was changed. **Reason:** To comply with the RoHS Directive.

Note: The functions of the parts were not changed.

IMPORTANT:

The materials for the parts were changed before the part numbers were changed.
 To make sure the correct parts are used on the correct machines, please handle the parts as follows:

Parts with the **old** P/N: **Non-RoHS** compliant parts Parts with the **new** P/N: **RoHS** compliant parts

	RoHS	Non-RoHS
	Compliant Parts	Compliant Parts
RoHS Compliant Machines	OK	DO NOT USE
Non-RoHS Compliant Machines	OK	OK

- Continue using non-RoHS compliant parts on non-ROHS compliant machines until
 the stock of these parts runs out. Then, start using RoHS compliant parts on the
 non-RoHS compliant machines.
- DO NOT use <u>non-RoHS</u> compliant parts on <u>RoHS</u> compliant machines.
 Note: This is to make sure that all machines are in full compliance with the RoHS Directive.



Modification Bulletin

PAGE: 2/2

Model: Russian-C4 G3 Unit Date: 21-Aug-06 No.: MB768001

Gotenba (Japan) Production

· · · · · · · · · · · · · · · · · · ·				l
MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
G3 Interface Unit Type 3030	120/60	USA, Taiwan	B768-17	K9051100001
G3 Interface Unit Type 3030	220,230,240/50, 60	Europe, Asia, etc	B768-27	K9051100014

RICOH

Modification Bulletin

PAGE: 1/2

Model: Russian-C4 G3 Unit Date				Ð: 21-Aug-06		No.: MB768002	
Modified Article: Modular Harness					Prepared by: S. Tomoe		
From: Technical Service Dept., GTS Division							
Reason for Modification:	☐ Parts catalog correction☐ To facilitate assembly☐ Part standardization	☐ Vend☐ To ir☐ Othe	nprove	ange e reliability	⊠ To n (Ro	neet standards HS)	

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B7505378	B7515243	HARNESS: MODULAR: G3	1	X/O	3	6	

Change: The materials for the part was changed. **Reason:** To comply with the RoHS Directive.

Note: The functions of the parts were not changed.

IMPORTANT:

The materials for the parts were changed before the part numbers were changed.
 To make sure the correct parts are used on the correct machines, please handle the parts as follows:

Parts with the **old** P/N: **Non-RoHS** compliant parts Parts with the **new** P/N: **RoHS** compliant parts

	RoHS	Non-RoHS
	Compliant Parts	Compliant Parts
RoHS Compliant Machines	OK	DO NOT USE
Non-RoHS Compliant Machines	OK	OK

- Continue using non-RoHS compliant parts on non-ROHS compliant machines until
 the stock of these parts runs out. Then, start using RoHS compliant parts on the
 non-RoHS compliant machines.
- DO NOT use <u>non-RoHS</u> compliant parts on <u>RoHS</u> compliant machines.
 Note: This is to make sure that all machines are in full compliance with the RoHS Directive.



Modification Bulletin

PAGE: 2/2

Model: Russian-C4 G3 Unit Date: 21-Aug-06 No.: MB768002

Gotenba (Japan) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.			
G3 Interface Unit Type 3030	120/60	USA, Taiwan	B768-17	K9060300001			
G3 Interface Unit Type 3030	220,230,240/50, 60	Europe, Asia, etc	B768-27	K9060300078			