

Model: Hard Disk Drive option Type 2027		Date: 10-May-06	No.: MB592001
Modified Article: HDD		Prepared by: Y. Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input checked="" type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index
B0955760	B0955763	HD:TOSHIBA:MK4032GAX:ROHS	1-1	O/O	3	3

Change: The part number of the HDD unit was changed.

Reason: The old HDD was discontinued from production.

Note: Both parts have the same function and performance.