

Model: Russian-C		Date: 19-Jun-02	No.: MA265034
Modified Article: Guide Plate, Arm Gate Pawl		Prepared by: M.Mano	
From: Technical Services sec. Service Planning Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☒ To improve reliability ☐ Other	☐ To meet standards ()

The shapes of the following parts have been changed to ensure that dog ears do not occur in the copy paper.

Interchange Unit (B300)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B3004562	B3004563	Guide Plate	1	X/X	3	13	
B3004573	B3004575	Arm Gate Pawl Lower Front	1	X/X	3	14	

RCL (Japan) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
Interchange Unit Type 270	115/60 220/50, 60	Generic	B300-17	H4000500001
Interchange Unit Type 1027	115/60 220/50, 60	Generic	B416-17	(see Note)

Note: Interchange Unit Type 1027 (for the R-C2) uses the new parts above from the beginning of Type 1027 mass production.



Part Change Information List

Date: March 18, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Russian-C Interchange Unit Type 270	B300	200903		AA145818	AA143653	SHAFT:ROLLER:TENSION	1	1	O/O		3	21					V0803537



Part Change Information List

Date: January 29, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C Interchange Unit Type 270	B300	201001		B3004542	B3004543	TRANSPORT ROLLER	1	1	O/O		5	7					V0902308	



Part Change Information List

Date: December 29, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C Interchange Unit Type 270	B300	201012		B3004536	B3004538	SIDE PLATE - FRONT	1	1	O/O		5	4					V0902240	