


Model: Kir-C Printer Controller		Date: 30-May-01	No.: MB405001
Modified Article: Parts Catalog Correction		Prepared by: K. Miura	
From: Technical Services Dept., GTS Division			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Please correct your Parts Catalog as follows:

Page 3

- Deletion -

Part number	Description	Q'ty	Index	Note
B4055172	Controller Board (Lanier)	1	5	



Model: Kir-C Printer Controller	Date: 30-May-01	No.: MB405001
---------------------------------	-----------------	---------------

Page 7

- Part Number Changes -

Old part number	New part number	Description	Q'ty	Index	Note
14075334	14075353	IC - SN74LV244APW		117	
16304103	16504103	Resistor - 10KOHM +-5% 1/10W		146	
16304122	16504122	Chip Resistor - 1.2KOHM +-5% 1/10W		147	
16304220	16504220	Chip Resistor - 22OHM +-5% 1/10W		148	
16304330	16504330	Chip Resistor - 33OHM +-5% 1/10W		149	
16304472	16504472	Resistor - 4.7KOHM +-5% 1/10W		150	
16304560	16504560	Chip Resistor - 56OHM +-5% 1/10W		151	
16341000	16541000	Chip Resistor - 100OHM +-1% 1/10W 1		153	
16341004	16541004	Chip Resistor - 1MOHM +-1% 1/10W		154	
16342001	16542001	Chip Resistor - 2KOHM +-1% 1/10W		155	
16343301	16543301	Chip Resistor - 3.3KOHM +-1% 1/10W		156	

- Description Change -

Part number	Old description	New description	Q'ty	Index	Note
B4045170	Controller Board (NA)	Controller Board (NA/EU)	1	29	

- Q'ty Change -

Part number	Old description	Old Q'ty	New Q'ty	Index	Note
B4055300	IC – M4A3-32/32-10VC48		1	29	

- Deletion -

Part number	Description	Q'ty	Index	Note
B4055172	Controller Board (EU)	1	*	