RICOH

Modification **B**ulletin

PAGE: 1/1

Model: Model U-P	1 4 Bin Mail Box (G312)		Da	ate: 3-Dec-0	08	No.: MG312001	
Modified Article: See list			Prepared by: H.K.				
From: 1st Tech. Support Sec. Service Support Dept.							
Reason for	☐ Parts catalog correction	☐ Vendor o	cha	ange	Other		
Modification:	☐ To facilitate assembly	☐ To improv		e reliability	☐ To me	et standards	
	□ Part standardization	☐ Product Saf		afety	()	

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G5181245	C6851245	LEVER:RELEASE	1 - 1	0/0	7	23	
G5182555	C6852555	BRACKET:TIGHTENER	1 - 1	0/0	9	8	
G5661111	C6851111	SIDE PLATE:FRONT	1 - 1	0/0	9	20	
G5661220	G5661210	REAR SIDE PLATE	1 - 1	0/0	9	19	1
G5661210	C6851210	SIDE PLATE:REAR:ASS'Y	1 - 1	0/0	9	19	1
G5661411	C6851411	STAY:LOWER	1 - 1	O/O	7	19	
G5662512	C6852512	BRACKET:STEPPER MOTOR	1 - 1	0/0	9	15	

Change: The materials of the parts in the table were changed. **Reason:** Parts standardization

Note: The rear side plate was changed twice (G5661220 \rightarrow G5661210 \rightarrow C6851210).