


Model: Kir-C Plate Cover		Date: 22-Oct-01	No.: MB406001
Modified Article: Platen Cover Feeler		Prepared by: K. Miura	
From: Technical Services Dept., GTS Division			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☒ To improve reliability ☐ Other	☐ To meet standards ()

The following parts have been changed to maximize paper size detection accuracy.
For details, please see RTB #RB040007.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
A2501384	B4061384	Feeler - Platen Cover	1	X/O	3	8	
A2501383	B4061383	Bracket - Platen Cover	1	X/O	3	10	





Part Change Information List

Date: November 30, 2009

[illegible]



Part Change Information List

Date: October 29, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Platen Cover Type 1018	B406	201010		A5486121	D5406121	FULL DUG POINT SCREW:FIX-HINGE	2	2	X/O		3	9					V1002171	10090229