Modification Bulletin

Reissued: 16-Jul-03

Model: Model U-C1 Paper Tray Unit (PS510)

Date: 19-Jun-03

No.: MB456001a

MB Correction

The items in bold italics have been corrected or added.

Modified Article: Stand				Prepared by: Y.Urushihara			
From: 1st Tech. Sup	port Sec. Service Support Dep	ot.					
Reason for	Parts catalog correction	Vendor change		To meet standards			
Modification:	To facilitate assembly			()			
	Part standardization	Other					

The following have been changed due to a vendor change.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G5696160	B4566160	Front Stand	1	X/O	3	1	
G5696161	B4566161	Rear Stand	1	X/O	3	2	

Model	V/Hz	Destination	Code	Serial Number
PS510	120/60	All RICOH subsidiaries,	B456-17	J3930400001
		NRG, SAVIN		
PS510	220-240/50, 60	Infotec	B456-26	6P50430001

M odification B ulletin

Model: Model U-C1	e: 25-Sep-0	3	No.: MB456002			
Modified Article: H		Prepared by: S. Tomoe				
From: 1st Tech. Sup						
Reason for	Parts catalog correction	I Parts catalog correction		ange	🗌 To n	neet standards
Modification:			e reliability	()	
	Part standardization	Other				

Please apply the following corrections to your Parts Catalogs.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B5685340	B4565340	Heater Harness	1-1		4	20	


Modification Bulletin

Model: Model U-C1 Paper Tray Unit (PS510) Date:			e: 22-Mar-0	5	No.: MB456003			
Modified Article: Cushions					Prepared by: S. Tomoe			
From: 1st Tech. Support Sec. Service Support Dept.								
Reason for	Parts catalog correction	Vendor ch		ange	🗌 To n	neet standards		
Modification:	To facilitate assembly	🗌 To in	To improve r		()		
	Part standardization	🛛 Othe	r					

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	G3132787	Cushion – Bottom Plate	0-2		5	28	
	G3132788	Cushion – Base -2	0-1		5	29	

Change: The parts in the table were added. **Reason:** To minimize the sound that occurs when the operator pulls out the paper tray.

Note: This sound comes from the bottom plate and lift bracket.



Model	V/Hz	Destination	Code	Serial Number
PS510	120/60	All RICOH subsidiaries,	B456-17	J3930901533
		NRG, SAVIN		
PS510	220-240/50,60	Infotec	B456-26	6P50930455

Modification Bulletin

Model: Model U-C1 Paper Tray Unit (PS510) Date				e: 22-Mar-0	5	No.: MB456004
Modified Article: T		Prepared by: S. Tomoe				
From: 1st Tech. Sup						
Reason for Modification:	 Parts catalog correction To facilitate assembly Part standardization 	☐ Vendor chan ☐ To improve r ⊠ Other		0	□ To n (neet standards)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0602900	B1802900	Torque Limiter – 40MN.M:MM18	1-1	0/0	7	22	

Change: The material for this part was changed to a more environmentally friendly type. **Reason:** This is part of Ricoh's ongoing application of in-house environmental standards.

Modification Bulletin

Reissued:2-Aug-06

MB Reissue

he items in bold italics have been corrected or added.						
Modified Article: Rollers				by: H.K		
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	Parts catalog correction	U Vendor ch	ange	To meet standards		
Modification:	🖂 To improve	⊠ To improve reliability ()				
	Part standardization	Other				

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
AF030049	AF030085	Pick-up Roller	1-1	X/O	7	2	
	AA100014	Retaining Ring C – Separate	2-3		7	15	
AF031049	AF031085	Feed Roller	1-1	X/O	7	14	
AF032049	AF032085	Separation Roller	1-1	X/O	7	23	
G5682650	G5682665	Paper Feed Unit	1-1	X/O	7	1	

Change: The material for these parts was changed. **Reason:** To further improve the reliability of the parts.

Important: When you install the new pick-up roller for the first time, install it with the retaining ring together as a set.

Modification Bulletin

Model: Model U-C1 Paper Tray Unit (PS510) Date			te: 22-Mar-05		No.: MB456006		
Modified Article: Control Board					Prepared by: S. Tomoe		
From: 1st Tech. Support Sec. Service Support Dept.							
Reason for	Parts catalog correction	U Vend	lor ch	ange	🗌 To n	neet standards	
Modification:			nprove	e reliability	()	
	Part standardization	🛛 Othe	r				

I	Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B4565100	B4565115	Control Board	1-1	0/0	9	7	

Change: The materials for the board were changed to more environmentally-friendly types.

Reason: This is part of Ricoh's ongoing application of in-house environmental standards.

Modification Bulletin

Reissued: 12-Apr-05

Model: Model U-C1 Paper Tray Unit (PS510)

Date: 22-Mar-05

No.: MB456007a

MB Correction

The items in bold italics have been corrected or added.

Modified Article: Vertical Guide			Prepared by: S. Tomoe			
From: 1st Tech. Sup	oport Sec. Service Support Dep	ot.				
Reason for Modification:	 Parts catalog correction To facilitate assembly Part standardization 	Uendor ch To improve	0	☐ To meet standards ()		

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
A2322785	B0822785	Vertical Guide	1-1	0/0	7	38	

Change: The position of the Mylar on the vertical guide was changed.

Reason: To minimize paper jams that occur when feeding curled paper.

Modification Bulletin

Reissued: 12-Apr-05

Model: Model U-C1 Paper Tray Unit (PS510)

Date: 22-Mar-05

No.: MB456008a

MB Correction

The items in bold italics	have been	corrected	or added.
---------------------------	-----------	-----------	-----------

Modified Article: Heater Harnesses			Prepared by: S. Tomoe			
From: 1st Tech. Sup	port Sec. Service Support Dep	ot.				
Reason for	Parts catalog correction	U Vendor ch	ange	To meet standards		
Modification:	To facilitate assembly	mbly 🗌 To improve		()		
	Part standardization	Other				


Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B4565340	B4565350	Heater Harness	1-1	0/0	3	20	
	B4565360	Heater Sub Harness	0-1		3	44	

Changes:

- 1) The material of the I/F harness (heater harness) was changed to a more environmentally-friendly type.
- 2) A relay harness was added (heater sub harness).

Reasons:

- 1) This is part of Ricoh's ongoing application of in-house environmental standards.
- 2) So that the LCT can connect to the mainframe PSU.
 - **Note:** The position of the LCT connector on the TH-C1 PSU is different from the previous model.



Modification Bulletin

PAGE: 1/1

Model: Model U-C1 / TH-C1 Paper Tray Unit (PS510) Date						No.: MB456009
Modified Article: See Table				Prepared	by: H.H	Κ.
From: Technical Service Dept., GTS Division						
Reason for Modification:	 Parts catalog correction To facilitate assembly Part standardization 	U Venc	nprove	ange e reliability	⊠ To n (Ro	neet standards HS)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
A2042972	B1802972	LEVER:RISE:TRAY BOTTOM PLATE	2	X/O	5	26	
G3132788	B5982788	CUSHION:BASE:2	2	X/O	5	29	
G3132952	B4562952	PAPER TRAY ASS'Y	2	X/O	5	1	
G5682665	G5682675	PAPER FEED UNIT: PAPER BANK:ASS'Y	2	X/O	7	1	А
G5682675	B5982660	PAPER FEED UNIT: APER BANK: ASS'Y	2	X/O	7	1	А
G5682770	B5982770	TRAY BOTTOM PLATE: HLTR: ASS'Y	2	X/O	5	12	
G5682781	G5682783	SIDE FENCE: FRONT: ASS'Y	2	X/O	5	6	
G5682782	B5982786	SIDE FENCE: REAR: ASS'Y	2	X/O	5	20	
G5682790	B5982790	COVER: PAPER SIZE SENSOR:PEEN	2	X/O	5	2	
G5696168	B6006168	BRACKET: STAND: REAR LEFT	1	X/O	3	13	
G5696169	B6006169	BRACKET: STAND: REAR RIGHT	1	X/O	3	42	

Change: The materials for these parts were changed. **Reason:** To comply with the RoHS Directive.

Note:

RICOH

- The functions of these parts were not changed.
- "A": The P/N for this part was changed as follows:G5682665→G5682675→ B5982660.

IMPORTANT:

• The materials for the parts were changed before the part numbers were changed. To make sure the correct parts are used on the correct machines, please handle the parts as follows:

Parts with the **old** P/N: Parts with the **new** P/N: Non-RoHS compliant parts RoHS compliant parts



Model: Model U-C1 / TH-C1 Paper Tray Unit (PS510)

)) Date: 31-Jul-06

No.: MB456009

	RoHS Compliant Parts	Non-RoHS Compliant Parts
RoHS Compliant Machines	OK	DO NOT USE
Non-RoHS Compliant Machines	ОК	OK

- Continue using non-RoHS compliant parts on non-ROHS compliant machines until the stock of these parts runs out. Then, start using RoHS compliant parts on the non-RoHS compliant machines.
- **DO NOT use** <u>non-RoHS</u> compliant parts on <u>RoHS</u> compliant machines. **Note:** This is to make sure that all machines are in full compliance with the RoHS Directive.

Model	V/Hz	Destination	Code	Serial Number
PS510	-,,	All RICOH subsidiaries, NRG, SAVIN	B456-17	J39603xxxxx
PS510	220-240/50,60	Infotec	B456-26	6P5036xxxx

Modification Bulletin

PAGE: 1/2

Model: Model U-C1 / TH-C1 Paper Tray Unit (PS510) Da			ate: 3-Oct-06		No.: MB456010	
Modified Article:	MAGNETIC CLUTCH - PAPI		Prepared	by: H.K.		
From: Global Tech						
Reason for	Parts catalog correction	U Vendor	cha	ange	Other	
Modification:			e reliability	🛛 To mee	et standards	
	Part standardization	Product Sa		afety	(RoH	S)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
AX200221	AX200279	MAGNETIC CLUTCH - PAPER FEED	1-1	X/O	11	5	

Change: The materials for these parts were changed. **Reason:** To comply with the RoHS Directive.

Note:

• The functions of these parts were not changed.

IMPORTANT:

• The materials for the parts were changed before the part numbers were changed. To make sure the correct parts are used on the correct machines, please handle the parts as follows:

Parts with the **old** P/N: Parts with the **new** P/N: **Non-RoHS** compliant parts **RoHS** compliant parts

	RoHS	Non-RoHS
	Compliant Parts	Compliant Parts
RoHS Compliant Machines	ОК	DO NOT USE
Non-RoHS Compliant Machines	ОК	ОК

- **Continue using** non-RoHS compliant parts on non-ROHS compliant machines **until the stock of these parts runs out**. Then, start using RoHS compliant parts on the non-RoHS compliant machines.
- DO NOT use <u>non-RoHS</u> compliant parts on <u>RoHS</u> compliant machines.
 Note: This is to make sure that all machines are in full compliance with the RoHS Directive.



Modification Bulletin

PAGE: 2/2

Model: Model U-C1 / TH-C1 Paper Tray Unit (PS510) Date: 3-Oct-06 No.: MB456010

RCL (Japan) Production									
Model	V/Hz	Destination	Code	Serial Number					
PS510		All RICOH subsidiaries, NRG, SAVIN	B456-17	J39603xxxx					
PS510	220-240/50,60	Infotec	B456-26	6P5036xxxx					

M odification B ulletin

PAGE: 1/2

Model: Model U-C1 / TH-C1 Paper Tray Unit (PS510) Dat			Date	e: 15-Jun-0	7	No.: MB456011	
Modified Article: See Table				Prepared by: H.K.			
From: Technical Service Dept., GTS Division							
Reason for Modification:	 Parts catalog correction To facilitate assembly Part standardization 	U Venc	nprove	ange e reliability	⊠ To n (Ro	neet standards HS)	

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AX040128	AX040211	MOTOR – DC2.88W	2	X/O	9	4	
A2322881	B5982881	MICRO SWITCH:ON OFF DETECTOR:ASS'Y	1	X/O	9	2	
A6821067	B5421067	STAY:UPPER:PROTECT	1	X/O	3	12	
A6822559	B5422559	STOPPER:LEVER:VERTIC	1	X/O	3	31	
A6822565	B5982565	STOPPER:VERTICAL TRANSPORT:PEEN	1	X/O	3	36	
G5681187	B5981187	BRACKET:INTERFACE BOARD	1	X/O	9	8	
G5682700	B5982700	BRACKET:STEPPER MOTOR:ASS'Y	1	X/O	11	15	
G5682702	B5982703	STEPPER MOTOR – DC 4.2W	1	X/O	11	16	
G5682830	B5982830	BRACKET:STEPPER MOTOR:PEEN	1	X/O	11	18	
G5682842	B5982842	DRUM STAY:FEED ROLLER	1	X/O	11	14	
G5682990	B5982990	SUPPORTER:PAPER TRAY:ASS'Y	2	X/O	3	3	
G5685300	B5985300	HARNESS:MAIN:ASS'Y	1	X/O	9	5	
G5685310	B5985310	HARNESS:PAPER SIZE SENSOR:ASS'Y	1	X/O	9	6	
G5686560	B5986560	HEAT SINK:HEATER	1	X/O	3	17	
G5692565	B6002565	GUIDE PLATE:VERTICAL TRANSPORT	1	X/O	3	28	
G5692846	B6002846	DRUM STAY:FEED ROLLER:UPPER	1	X/O	11	7	

Change: The materials for these parts were changed. **Reason:** To comply with the RoHS Directive.



Model: Model U-C1 / TH-C1 Paper Tray Unit (PS510) Date: 15-Jun-07 No.: MB456011

Note:

• The functions of these parts were not changed.

IMPORTANT:

• The materials for the parts were changed before the part numbers were changed. To make sure the correct parts are used on the correct machines, please handle the parts as follows:

Parts	with	the	old	P/N:
Parts	with	the	new	/ P/N:

Non-RoHS compliant parts **RoHS** compliant parts

	RoHS Compliant Parts	Non-RoHS Compliant Parts
RoHS Compliant Machines	ОК	DO NOT USE
Non-RoHS Compliant Machines	ОК	OK

- Continue using non-RoHS compliant parts on non-ROHS compliant machines until the stock of these parts runs out. Then, start using RoHS compliant parts on the non-RoHS compliant machines.
- **DO NOT use** <u>non-RoHS</u> compliant parts on <u>RoHS</u> compliant machines. **Note:** This is to make sure that all machines are in full compliance with the RoHS Directive.

Model	V/Hz	Destination	Code	Serial Number
PS510	120, 220-240/50, 60	All RICOH subsidiaries,	B456-17	J39603xxxxx
		NRG, SAVIN		
PS510	220-240/50,60	Infotec	B456-26	6P5036xxxx

Modification Bulletin

PAGE: 1/2

Model: Model U-C1 / TH-C1 Paper Tray Unit (PS510)			Date: 3-Jul-07			No.: MB456012
Modified Article: S		Prepared by: H.K.				
From: Technical Service Dept., GTS Division						
Reason for	Parts catalog correction To facilitate assembly	U Venc		ange e reliability	(D-110)	
Modification:	Part standardization	Othe	•	e renaenty		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G5682689	B5982689	SHAFT:SEPARATE:DRIVE N:BANK:ASS'Y	1	X/O	7	21	
AW020131	AW020161	PHOTOINTERRUPTOR:VE RTICAL TRANSPORT	1	X/O	7	7	
A2322780	B1802780	STAY:FEED	1	X/O	7	8	
A2322781	B0772781	BRACKET:SENSOR	1	X/O	7	6	
G0602725	B1802722	STAY: SEPARATE: NO.2: ASS'Y	1	X/O	7	24	
G5685370	B5985370	HARNESS: PAPER FEED UNIT:ASS'Y	1	X/O	7	10	

Change: The materials for these parts were changed. **Reason:** To comply with the RoHS Directive.

Note:

• The functions of these parts were not changed.

IMPORTANT:

• The materials for the parts were changed before the part numbers were changed. To make sure the correct parts are used on the correct machines, please handle the parts as follows:

Parts with the **old** P/N: Parts with the **new** P/N: Non-RoHS compliant parts RoHS compliant parts

	RoHS	Non-RoHS
	Compliant Parts	Compliant Parts
RoHS Compliant Machines	ОК	<u>DO NOT USE</u>
Non-RoHS Compliant Machines	ОК	OK

• **Continue using** non-RoHS compliant parts on non-ROHS compliant machines **until the stock of these parts runs out**. Then, start using RoHS compliant parts on the non-RoHS compliant machines.



Model: Model U-C1 / TH-C1 Paper Tray Unit (PS510) Date: 3-Jul-07 No.: MB456012

DO NOT use <u>non-RoHS</u> compliant parts on <u>RoHS</u> compliant machines.
 Note: This is to make sure that all machines are in full compliance with the RoHS Directive.

Model	V/Hz	Destination	Code	Serial Number		
PS510	-,,	All RICOH subsidiaries, NRG, SAVIN	B456-17	J39603xxxx		
PS510	220-240/50,60	Infotec	B456-26	6P5036xxxx		

Part Change Information List

Date: January 31, 2013

	PCI	. PCIL	Old part	New part		Old	New						Set				ECN
Model C	Code Numb	er Correction	number	number	Description	Q'ty	Q'ty	Int	3DPC	Page	Index	Set	Int	RTB	Note	Ref Number	Number
U-C1 Paper Tray Unit (PS510) B4	456 20130	1	AH012014	AH012050 CASTER:STOPPER:NO		2	2	0/0		3	5					V1203033	12091652



Part Change Information List

	PCIL PCIL	Old part New part		Old New	Set			ECN
Model	Code Number Correction	ion number number	Description	Q'ty Q'ty Int 3DPC	Page Index Set Int	RTB	Note	Ref Number Number
U-C1 Paper Tray Unit (PS510)	B456 201406	AX040211 D0599500 MOTOR -	DC2.88W	2 2 O/O	9 4			V1401371

Date: June 30, 2014