


Model: Model J-C1 LCT 		Date: 27-Dec-05	No.: MB600001
Modified Article: End Fence		Prepared by: H.Taguchi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety ()		

The shape of the end fence has been changed to ensure that the paper stock can move from the right side to the left side smoothly to prevent SC503.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G5692707	B6002707	End Fence –Tandem Tray	X/O	1-1	5	14	

Model: Model J-C1 / J-C2 LCT		Date: 15-Jun-07	No.: MB600002
Modified Article: See Table		Prepared by: H.K.	
From: Technical Service Dept., GTS Division			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input checked="" type="checkbox"/> To meet standards (RoHS)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AX200158	AX200276	MAGNETIC CLUTCH:0.8NM:Z28	1	X/O	15	7	
A6821067	B5421067	STAY:UPPER:PROTECT	2	X/O	3	5	
A6822559	B5422559	STOPPER:LEVER:VERTICAL TRANSPORT	1	X/O	3	18	
A6822565	B5982565	STOPPER:VERTICAL TRANSPORT:PEEN	1	X/O	3	22	
G5682700	B5982700	BRACKET:STEPPER MOTOR:ASS'Y	1	X/O	15	5	
G5691087	B6001087	BRACKET:SAFETY	1	X/O	15	28	
G5692826	B6002826	BRACKET:MAGNETIC CLUTCH	1	X/O	15	10	
G5692827	B6002827	DRUM STAY:TIMING BELT	1	X/O	15	12	
G5692846	B6002846	DRUM STAY:FEED ROLLER:UPPER	1	X/O	11	6	
G5681187	B5981187	BRACKET:INTERFACE BOARD	1	X/O	15	25	
G5682702	B5982703	STEPPER MOTOR – DC 4.42W	1	X/O	15	31	
G5692565	B6002565	GUIDE PLATE: VERTICAL TRANSPORT	1	X/O	3	12	
AX200221	AX200279	MAGNETIC CLUTCH - PAPER FEED	1	X/O	11	13	

Change: The materials for these parts were changed.

Reason: To comply with the RoHS Directive.

Model: Model J-C1 / J-C2 LCT

Date: 15-Jun-07

No.: MB600002

Note:

- The functions of these parts were not changed.

IMPORTANT:

- The materials for the parts were changed before the part numbers were changed. To make sure the correct parts are used on the correct machines, please handle the parts as follows:

Parts with the **old** P/N: **Non-RoHS** compliant parts
Parts with the **new** P/N: **RoHS** compliant parts

	RoHS Compliant Parts	Non-RoHS Compliant Parts
RoHS Compliant Machines	OK	<u>DO NOT USE</u>
Non-RoHS Compliant Machines	OK	OK

- **Continue using** non-RoHS compliant parts on non-RoHS compliant machines **until the stock of these parts runs out**. Then, start using RoHS compliant parts on the non-RoHS compliant machines.
- **DO NOT use** non-RoHS compliant parts on RoHS compliant machines.
Note: This is to make sure that all machines are in full compliance with the RoHS Directive.

RCL (Japan) Production

Model	V/Hz	Destination	Code	Serial Number
RICOH, GESTETNER, SAVIN, Lanier PS560	120/60	USA,	B600-17	Spare parts only
RICOH, NRG, LANIER PS560	220-240/50, 60	EUROPE, etc	B600-27	Spare parts only
Infotec PS560	220-240/50, 60	EUROPE	B600-26	Spare parts only
RICOH, GESTETNER, SAVIN, Lanier PS600	120/60	USA	B600-57	K07603xxxxx
RICOH, NRG, LANIER PS600	220-240/50, 60	EUROPE, etc	B600-67	K07603xxxxx
Infotec PS600	220-240/50, 60	EUROPE	B600-66	5J6036xxxx

Model: Model J-C1 / J-C2 LCT		Date: 3-Jul-07	No.: MB600003
Modified Article: See Table		Prepared by: H.K.	
From: Technical Service Dept., GTS Division			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input checked="" type="checkbox"/> To meet standards (RoHS)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G5682689	B5982689	SHAFT:SEPARATE:DRIVE N:BANK:ASS'Y	1	X/O	13	16	
AW020131	AW020161	PHOTOINTERRUPTOR:VERTICAL TRANSPORT	1	X/O	11	7	
A2322780	B1802780	STAY:FEED	1	X/O	11	10	
A2322781	B0772781	BRACKET:SENSOR	1	X/O	11	8	
G0602725	B1802722	STAY:SEPARATE:NO.2:ASS'Y	1	X/O	13	14	
G5685370	B5985370	HARNESS:PAPER FEED UNIT:ASS'Y	1	X/O	11	11	

Change: The materials for these parts were changed.

Reason: To comply with the RoHS Directive.

Note:

- The functions of these parts were not changed.

IMPORTANT:

- The materials for the parts were changed before the part numbers were changed. To make sure the correct parts are used on the correct machines, please handle the parts as follows:

Parts with the **old** P/N:
Parts with the **new** P/N:

Non-RoHS compliant parts
RoHS compliant parts

	RoHS Compliant Parts	Non-RoHS Compliant Parts
RoHS Compliant Machines	OK	<u>DO NOT USE</u>
Non-RoHS Compliant Machines	OK	OK

- **Continue using** non-RoHS compliant parts on non-RoHS compliant machines **until the stock of these parts runs out**. Then, start using RoHS compliant parts on the non-RoHS compliant machines.

Model: Model J-C1 / J-C2 LCT

Date: 3-Jul-07

No.: MB600003

- **DO NOT use non-RoHS** compliant parts on **RoHS** compliant machines.

Note: This is to make sure that all machines are in full compliance with the RoHS Directive.

RCL (Japan) Production

Model	V/Hz	Destination	Code	Serial Number
RICOH, GESTETNER, SAVIN, Lanier PS560	120/60	USA,	B600-17	Spare parts only
RICOH, NRG, LANIER PS560	220-240/50, 60	EUROPE, etc	B600-27	Spare parts only
Infotec PS560	220-240/50, 60	EUROPE	B600-26	Spare parts only
RICOH, GESTETNER, SAVIN, Lanier PS600	120/60	USA	B600-57	K07603xxxxx
RICOH, NRG, LANIER PS600	220-240/50, 60	EUROPE, etc	B600-67	K07603xxxxx
Infotec PS600	220-240/50, 60	EUROPE	B600-66	5J6036xxxx



Part Change Information List

Date: Jul 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
J-C1 LCT	B600	201007		G5691175	B6001175	SLIDE RAIL:RIGHT	1	1	X/O		5	8					V1001166	4060443



Part Change Information List

Date: January 31, 2013

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
J-C1 LCT	B600	201301		AH012014	AH012050	CASTER:STOPPER:NO	2	2	O/O		3	26					V1203033	12091652