

Model: Ring Binder RB5000		Date: 12-Sep-08	No.: MD392001
Modified Article: BASE:MAIN:MB70241:ASS'Y		Prepared by: T. Tadokoro	
From: PPBG QA/Service Planning Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
D3925550	D3925551	BASE:MAIN:MB70241:ASS'Y	1	O/O	55	14	

Change/ Reason: The software was modified.

Model: Ring Binder RB5000		Date: 30-Oct-08	No.: MD392002
Modified Article: LeakBreaker		Prepared by: T. Tadokoro	
From: PPBG QA/Service Planning Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
D3925130	D3925178	LeakBreaker:BJC152100F1:MB11303	1	O/O	53	18	
D3923116	D3923162	Pan Head Screw:M3x22:AA21122	2	O/O	53	20	

Change/ Reason: Due to vendor change, the part number has been changed.

Model: Ring Binder RB5000		Date: 30-Oct-08	No.: MD392003
Modified Article: Bracket:Coupling:Main:Ass'y		Prepared by: T. Tadokoro	
From: PPBG QA/Service Planning Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
D4341471	D4341476	Bracket:Coupling:Main:Ass'y	1	X/O	3	16	

Change: The shape of the Bracket:Coupling:Main:Ass'y was changed.


Reason: Support for Aegis.

Model: Ring Binder RB5000		Date: 09-Dec-08	No.: MD392004
Modified Article: Parts Catalog Correction		Prepared by: T. Tadokoro	
From: PPBG QA/Service Planning Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	D3924120	Tapping Screw: M3x6	4→6	-	2	9	
-	B8307511	CONNECTING GUIDE PLATE - LOWER	1	-	2	20	Add
-	B8351188	GUIDE PLATE – UPPER	1	-	2	21	Add

Change: Parts were added.

Reason: These parts were missing from the Parts Catalog.



Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
D3921284	-	HINGE: BUSHING: MB11421	4	-	4	3	Delete

Change: This part has been deleted.

Reason: D3921284 is not appropriate for supply.



Part Change Information List

Date: May 30, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Katana-C1.5 Ring Binder RB5000 (ISHIKARI)	D392	200905		D3925560	D3925561	PCB.SUB:MB70242	1	1	X/O		22	3	A				V0900419
Katana-C1.5 Ring Binder RB5000 (ISHIKARI)	D392	200905		D3925562	D3925563	BASE.SUB:MB70242:ASS'Y	1	1	X/O		22	3					V0901182
Katana-C1.5 Ring Binder RB5000 (ISHIKARI)	D392	200905		D3925551	D3925552	PCB.MAIN:MB70241	1	1	X/O		54	14	A				V0900419



Part Change Information List

Date: July 31, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Ring Binder RB5000	D392	200907			8025276	TAPPING SCREW WITH WASHER - M3X6	0	2			2	26			RD392004		V0901126	9040661
Ring Binder RB5000	D392	200907			B4082191	GUIDE PLATE - CONNECTING LOWER	0	1			2	24			RD392004		V0901126	9040661
Ring Binder RB5000	D392	200907			B4682196	UPPER GUIDE PLATE	0	1			2	25			RD392004		V0901126	9040661
Ring Binder RB5000	D392	200907			B468T021	GUIDE PLATE:CONNECTING:ASS'Y	0	1			2	27			RD392004		V0901092	
Ring Binder RB5000	D392	200907		D3921117	D3921119	PUNCH UNIT:A4:MB70098	1	1	X/O		14	21					V0901126	9040661



Part Change Information List

Date: August 31, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Ring Binder RB5000	D392	200908		D3921116	D3921118	PUNCH UNIT:LETTER:MB70100	1	1	X/O		14	21					V0901126	9040661
Ring Binder RB5000	D392	200908		D3921114	D3921120	UNIFORM UNIT:MB92006:ASS'Y	1	1	X/O		18	1					V0901125	9040657
Ring Binder RB5000	D392	200908		D3925561	D3925562	BASE:SUB:MB70242:ASS'Y	1	1	X/O		22	3					V0901180	9011142



Part Change Information List

Date: November 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Ring Binder RB5000	D392	200911		D3921161	D3921330	GUIDE:EXIT:MB10563	2	2	X/O		33	1					V0901125	9040657
Ring Binder RB5000	D392	200911		D3925552	D3925553	BASE:MAIN:MB70241:ASS'Y	1	1	X/O		54	14					V0901180	9011142
Ring Binder RB5000	D392	200911		D3925553	D3925554	BASE:MAIN:MB70241:ASS'Y	1	1	X/O		54	14					V0901181	9030712
Ring Binder RB5000	D392	200911		D3925554	D3925555	PCB:MAIN:MB70241	1	1	X/O		54	14					V0902149	9070582



Part Change Information List

Date: May 31, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Ring Binder RB5000	D392	201005		D3925555	D3925556	BASE:MAIN:MB70241:ASS'Y	1	1	X/O		55	14					V1000477	10020951



Part Change Information List

Date: October 29, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Ring Binder RB5000	D392	201010		D3925114	D3925180	BASE.SURGE ABSORBER.MB70243.0020	1	1	X/O		41	13					V1002218	10070910



Part Change Information List

Date: October 31, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Ring Binder RB5000	D392	201110		D3925556	D3925557	BASE:MAIN:MB70241:ASS'Y	1	1	X/O		55	14					V1101618	10110488



Part Change Information List

Date: January 31, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Ring Binder RB5000	D392	201201		D3925557	D3925558	BASE:MAIN:MB70241:ASSY	1	1	X/O		55	14					V1102931	11071265



Part Change Information List

Date: December 26, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5000	D392	201308			D5191415	GUIDE MILER:UNIFORM:TRAILING EDGE:MB80015:ASS'Y	0	1			19	1			RD392008		V1301891	12122343



Part Change Information List

Date: December 26, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5000	D392	201407		D5191415	D7371415	GUIDE MILER:UNIFORM:TRAILING EDGE:MB80015:ASS'Y	1	1	X/O		19	10			RD392008		V1400836	14030889



Part Change Information List

Date: August 29, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5000	D392	201408		D4341476	D4341470	BRACKET:COUPLING:MAIN:ASS'Y	1	1	O/O		3	16					V1401598	13020842

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5000	D392	201501			D7373165	PLAIN WASHER:4.3X9X0.8CF:EE39829	0	4			55	31			Y		V1404119	14120171
Ring Binder RB5000	D392	201501			D7373166	PIN:1706:FF51706	0	2			55	32			Y		V1404119	14120171



Part Change Information List

Date: February 27, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q' ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5000	D392	201502		D3925558	D3925559	BASE:MAIN:MB70241:ASS'Y	1	1	O/O		55	14					V1400439	13030343



Part Change Information List

Date: June 4, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5000	D392	201505		D3921305	D7371305	GUIDE PLATE:TRANSPORT:B:MB70082	1	1	X/O	N	7	3			Y		V1500043	14120399
Ring Binder RB5000	D392	201505		D3921304	D7371304	GUIDE PLATE:TRANSPORT:A:MB70081	1	1	X/O	N	7	12			Y		V1500043	14120399
Ring Binder RB5000	D392	201505		D3921240	D7371240	GUIDE PLATE:TRANSPORT:C:MB10729	1	1	X/O	N	7	13			Y		V1500043	14120399
Ring Binder RB5000	D392	201505		D3921306	D7371306	GUIDE PLATE:TRANSPORT:C:MB70083	1	1	X/O	N	9	1			Y		V1500043	14120399
Ring Binder RB5000	D392	201505		D3921307	D7371307	GUIDE PLATE:TRANSPORT:D:MB70085	1	1	X/O	N	9	3			Y		V1500043	14120399
Ring Binder RB5000	D392	201505		D3921242	D7371242	GUIDE PLATE:TRANSPORT:C:MB10731	1	1	X/O	N	9	21			Y		V1500043	14120399



Part Change Information List

Date: August 3, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5000	D392	201507		D3921241	D7371241	GUIDE PLATE:TRANSPORT:C:MB70093	1	1	X/O	N	7	6					V1500043	14120399



Part Change Information List

Date: October 2, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5000	D392	201509		D3927711	D7377711	LABEL:CARTRIDGE:MB10001	1	1	X/O	N	3	11			Y		V1501620	15040640

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Ring Binder RB5000	D392	201901		D3921289	D7371289	DC STEPPER MOTOR:MB70022	1	1	X/O	N	51	21					V1801911	
Ring Binder RB5000	D392	201901		D3921310	D7371310	DC STEPPER MOTOR:MB70118	5	5	X/O	N	27, 29, 51	1, 4, 25					V1801911	
Ring Binder RB5000	D392	201902		D3921112	D7371112	CLAMP:UNI:MB92004:ASS'Y	1	1	X/O	N	19	5			Y		V1303776	13110470