RIGOH

Modification Bulletin

Model: Russian-C1 Printer Option Date			e: 29-Mar-0	0	No.: MB306001			
Modified Article: Operation Switch				Prepared by: S. Tomoe				
From: Technical Services Dept., GTS Division								
Reason for Modification:	 Parts catalog correction To facilitate assembly Part standardization 	Vendor cha		nprove reliability		neet standards)		

The following should be corrected. Please correct your parts catalog.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
A9851480	A8951480	Operation Switch	1		5	12	


RIGOH

M odification B ulletin

Model: Russian-C Printer Controller Type270 Date			e: 30-Aug-0	2	No.: MB306002			
Modified Article: Network Interface Board				Prepared by: S. Tomoe				
From: Technical Services sec. Service Planning Dept.								
Reason for	Parts catalog correction	U Venc		-	🗌 To n	neet standards		
Modification:	To facilitate assembly	To improve		To improve reliability)		
	Part standardization	⊠ Other						

As per a field request, the Network Interface Board has been registered as a service part.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	G6785714	Network Interface Board	0-1		3	6	



RIGOH

M odification B ulletin

Model: Russian-C Printer Controller Type270 Date			e: 3-Apr-03		No.: MB306003	
Modified Article: P	Prepared by: S. Tomoe					
From: 1st Tech. Sup						
Reason for	on for Parts catalog correction Vendor cl			ange	neet standards	
Modification:	To facilitate assembly	te assembly		e reliability	()
	Part standardization	⊠ Other				

As per a field request, the PS3 Board has been registered as a service part.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B3085181	PS3 Board	0-1		3	7	

