

## Technical Bulletin

**PAGE: 1/1** 

Reissued: 18-Apr-16

Model: CH-C1/CH-C1pro LCT_MALAY	Date: 20-May-13	No.: RD710001a
---------------------------------	-----------------	----------------

## **RTB Reissue**

The items in bold italics have been corrected or added.

Subject: Firmware Release Note: LCT_MALAY		Prepared by: K.Hamada		
From: 1st Tech Service Sect., MFP/Printer Tech Service Dept				
Classification:	Troubleshooting	☐ Part informat	tion	Action required
	☐ Mechanical	☐ Electrical		☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	☐ Product Safety	Other (Firmv	vare)	☑ Tier 2

This RTB has been issued to announce the firmware release information for the **LCT\_MALAY.** 

Version	Program No.	Effective Date	Availability of RFU
01.070:06	D7105510C	December 2015 production	Available
01.060:06	D7105510B	1st Mass production	Available

Note: Definition of Availability of RFU via @Remote

<sup>&</sup>quot;Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
01.070:06	Specification Change:
	Setting SRA3 paper on the Wide LCT will enable the machine to automatically detect SRA3 on Europe and Asia models. SRA3 will continue to be detected as 12"x18" on NA models (no spec change).
01.060:06	1st Mass production

<sup>&</sup>quot;Available" The firmware can be updated via RFU or SD card.