

Model: Bellini-C3 Finisher(VICTORIA-E)		Date: 23-Feb-07	No.: MB830001
Modified Article: PCB Main Control		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B8305050	B8305055	PCB Main Control	1	O/O	55	4	

Reason: A software change.

Model: Bellini-C3 Finisher(VICTORIA-E)		Date: 20-Nov-07	No.: MB830002
Modified Article: PCB Main Control		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B8305055	B8305057	PCB Main Control	1	O/O	55	4	

Reason: A software change.

RCL (Japan) Production

MODEL NAME	CODE	SERIAL NO.
Finisher SR5000	B830-17	L5870400052
	B830-26	9Z70470001

Reissued: 18-Mar-08

Model: Bellini-C3 Finisher (VICTORIA-E)	Date: 20-Nov-07	No.: MB830003a
---	-----------------	----------------

Serial Number Update

The Serial Number information has been updated.

Modified Article: Standard Fence		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B8304531	B8304581	Auxiliary Standard Fence - Rear	1	X/O	15	14	
B8304521	B8304571	Standard Fence - Rear	1	X/O	15	19	
B8304511	B8304561	Standard Fence - Front	1	X/O	15	24	

Change: The opening in the standard fence was expanded.

Reason: To further ensure that the stapler head does not touch the fence when the paper is stapled.

Serial Number

Old Part Number	New Part Number		Serial No
B8304531	B8304581	B83017	L5871000347
		B83026	9Z71070001
B8304521	B8304571	B83017	L5871000279
		B83026	9Z71070001
B8304511	B8304561	B83017	L5871000347
		B83026	9Z71070001

Model: Bellini-C3 Finisher(VICTORIA-E)		Date: 29-Nov-07	No.: MB830004
Modified Article: Magnet		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0121531	B3522650	Magnet	2	O/O	31	8	

Change/Reason: Vendor change

Model: Bellini-C3 Finisher (VICTORIA-E)		Date: 26-May-08	No.: MB830005
Modified Article: PCB Main Control		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B8305057	B8305058	PCB Main Control	1	O/O	55	4	

Change/Reason: The software was modified.

Reissued: 15-Jul-08

Model: Bellini-C3 Finisher (VICTORIA-E)	Date: 27-May-08	No.: MB830006a
---	-----------------	----------------

MB Reissue

The items in ***Bold italics*** were corrected or added.

Modified Article: Side Plate: Shift Tray: Front: Unit		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards () ☐ Part standardization ☐ Product Safety		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B8303320	B8303340	Side Plate: Shift Tray: Front: Unit	1	X/O As a set	41	19	
B8303325	B8303345	Side Plate: Shift Tray: Rear: Unit	1		41	21	
B8303311	B8303350	Shift Tray Base	1		41	18	
04513006N	04543008Q	Tapping Screw – 3 x 8	2=>4		41	102	
<i>B8303331</i>	<i>B8303335</i>	<i>Shift Tray</i>	<i>1</i>	<i>X/O</i>	<i>7</i>	<i>22</i>	


Change: The shape of the shift tray was changed.

Reason: To further strengthen the shift tray.

Model: Bellini-C3 Finisher (VICTORIA-E)		Date: 13-Jun-08	No.: MB830007
Modified Article: Lever: Driven Gathering Roller: Back		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction	☐ Vendor change	☐ Other
	☐ To facilitate assembly	☐ To improve reliability	☒ To meet standards
	☐ Part standardization	☐ Product Safety	()

Page	Index	Part number	Description	Q'ty	Note
46	25	B4783509	Lever: Driven Gathering Roller: Back	1	

Change/ Reason: Call-out 25 was added (it was missing from the Parts Catalog).



Model: Bellini-C3 Finisher (VICTORIA-E)		Date: 13-Jun-08	No.: MB830008
Modified Article: Front & Rear Exit Roller		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B3022302	B8302302	Front & Rear Exit Roller	2	X/O	43	9	

CHANGE: Shape of the roller

REASON: To further improvement of reliability.

Model: Bellini-C3 Finisher (VICTORIA-E)		Date: 23-Jul-08	No.: MB830009
Modified Article: Timing Belt: B40S2m158		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B6522347	B7004428	Timing Belt: B40S2m158	1	O/O	45		


Change/ Reason: Vendor change.

Model: Bellini-C3 Finisher (VICTORIA-E)		Date: 4-Aug-08	No.: MB830010
Modified Article: PartsCatalogCorrection(PhotoReflectionSensor)		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction	☐ Vendor change	☐ Other
	☐ To facilitate assembly	☐ To improve reliability	☐ To meet standards
	☐ Part standardization	☐ Product Safety	()

New P/N added to the Parts catalog.

New P/N	Description	Q'ty	Page	Index	Note
AW010109	Photo Reflection Sensor	1	37	31*	*: New Index


16.PAPER EXIT SECTION 1 (B830)



Model: Finisher SR5000 (VICTRIA-E)		Date: 10-Sep-08	No.: MB830011
Modified Article: Exchange of Finisher's casters		Prepared by: K. Tsutsui	
From: PPBG QA&Service Planning Center			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B5452019	B8041035	Caster	4→4	O/O	61	15	

Change: 4 casters will be exchanged with new parts.



Reason: To reduce costs by using lower price components.

Model: Bellini-C3 Finisher (VICTORIA-E)		Date: 11-Sep-08	No.: MB830012
Modified Article: PCB Main Control		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B8305058	B8305059	PCB Main Control	1	O/O	55	4	

Change/Reason: The software was modified.

Model: Bellini-C3 Finisher (VICTORIA-E)		Date: 12-Sep-08	No.: MB830013
Modified Article: PCB Main Control		Prepared by: T. Tadokoro	
From: PPBG QA/Service Planning Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B8305059	B8305060	PCB Main Control	1	O/O	55	4	

Change/Reason: The software was modified.

Model: Bellini-C3 Finisher (VICTORIA-E)		Date: 30-Oct-08	No.: MB830014
Modified Article: Connecting Guide Plate - Upper		Prepared by: T. Tadokoro	
From: PPBG QA/Service Planning Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B8307512	B8307516	Connecting Guide Plate - Upper	1	O/O	27	4	


CHANGE/ Reason: The shape of this part was changed.

Model: Bellini-C3 Finisher (VICTORIA-E)		Date: 04-Nov-08	No.: MB830015
Modified Article: Tray-Slide		Prepared by: T. Tadokoro	
From: PPBG QA/Service Planning Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards () ☐ Part standardization ☐ Product Safety		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B8303332	B8303333	Tray-Slide	1	X/O	9	20	

CHANGE: Holes were added.

REASON: To prevent coated paper from dashing out when Aegis is connected.



RCL (Japan) Production

MODEL NAME	CODE	SERIAL NO.
Finisher SR5000	B830-17	L5880900146
	B830-26	

Model: Bellini-C3 Finisher (VICTORIA-E)		Date: 4-Nov-08	No.: MB830016
Modified Article: End Fence		Prepared by: T. Tadokoro	
From: PPBG QA/Service Planning Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B8303410	B8303400	End Fence	1	X/O	45	16	

CHANGE: The material of the End fence was changed.

REASON: To prevent dirt collecting on the paper side.

Model: Bellini-C3 Finisher (VICTORIA-E)		Date: 4-Nov-08	No.: MB830017
Modified Article: Interlock Switch		Prepared by: T. Tadokoro	
From: PPBG QA/Service Planning Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
12042752	12042844	Interlock Switch	1	X/O	59	105	

Change/ Reason: To improve reliability.

Model: Bellini-C3 Finisher (VICTORIA-E)		Date: 4-Nov-08	No.: MB830018
Modified Article: Exit Roller:Driven		Prepared by: T. Tadokoro	
From: PPBG QA/Service Planning Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B4782328	B8302324	Exit Roller:Driven	2	X/O	39	27	

CHANGE / REASON: To accommodate coated paper.

RCL (Japan) Production

MODEL NAME	CODE	SERIAL NO.
Finisher SR5000	B830-17	L5881000001
	B830-26	

Model: Bellini-C3 Finisher (VICTORIA-E)		Date: 16-Jan-09	No.: MB830019
Modified Article: PCB Main Control		Prepared by: T. Tadokoro	
From: PPBG QA/Service Planning Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old P/N	New P/N	Description	Q'ty	Int	Page	Index	Note
B8305060	B8305061	PCB Main Control	1	O/O	55	4	

Change: The firmware of the PCB was changed.

Model: Bellini-C3 Finisher (VICTORIA-E)		Date: 16-Jan-09	No.: MB830020
Modified Article: Harness:Interface		Prepared by: T. Tadokoro	
From: PPBG QA/Service Planning Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other		
	☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards		
	☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B8305201	D4605201	Harness:Interface	1	O/O	56	12	

CHANGE / REASON: Vendor change.



Part Change Information List

Date: June 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Katana-C1 Finisher (VICTORIA-E)	B830	200906		B4782324	C3082324	SHAFT:EXIT ROLLER:DRIVEN	1	1	X/O		38	29					V0901501	7021022



Part Change Information List

Date: July 31, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.
Katana-C1 Finisher (VICTORIA-E)	B830	200907		B4783552	B4783555	FEELER:PAPER SENSER	1	1	O/O		46	12	A	O/O	RB830001		V0901001
Katana-C1 Finisher (VICTORIA-E)	B830	200907		B4783554		GUIDE:FEELER:PAPER SENSER	1	0	O/X		46	11	A	O/O	RB830001		V0901001



Part Change Information List

Date: August 31, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Katana-C1 Finisher SR5000	B830	200908		B8305061	B8305062	PCB:MAIN CONTROL:ASS'Y	1	1	X/O		56	4					V0900998	9030674
Katana-C1 Finisher SR5000	B830	200908		B8305062	B8305063	PCB:MAIN CONTROL:ASS'Y	1	1	X/O		56	4					V0901608	9060089



Part Change Information List

Date: October 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Katana-C1 Finisher SR5000	B830	200910		B8302466	B8302468	COMPRESSION SPRING:DUPLEX STACK	2	2	X/O		33	1					V0901798	9061355



Part Change Information List

Date: January 29, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Katana-C1 Finisher SR5000	B830	201001		AX050277	B8303111	DRIVE UNIT:UPPER LOWER:ASS'Y	1	1	X/O		41	2			RB830002		V0902075	9070503
Katana-C1 Finisher SR5000	B830	201001		B8303118	B8303128	BRACKET:DRIVE:UPPER LOWER:ASS'Y	1	1	X/X		41	7			RB830002		V0902075	9070503



Part Change Information List

Date: May 31, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Katana-C1 Finisher SR5000	B830	201005		B8305063	B8305064	PCB:MAIN CONTROL:ASS'Y	1	1	O/O		57	4					V0902078	9070928
Katana-C1 Finisher SR5000	B830	201005		B8305064	B8305065	PCB:MAIN CONTROL:ASS'Y	1	1	X/O		57	4					V1000138	10010065



Part Change Information List

Date: Jun 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Katana-C1 Finisher SR5000	B830	201006		B8304782	B8304784	BRACKET:EXIT:UPPER	1	1	O/O		13	11					V0902550	



Part Change Information List

Date: Jul 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Katana-C1 Finisher SR5000	B830	201007		B8303163	B8303164	BRACKET:SENSOR:PAPER VOLUME SENSOR	1	1	X/O		41	23					V1001228	10040804



Part Change Information List

Date: Aug 31, 2010

Model	Code	PCIL Nr.	PCIL Correctio	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Katana-C1 Finisher SR5000	B830	201008		B8303163	B8303164	BRACKET:SENSOR:PAPER VOLUME SENSOR	1	1	X/O		41	23					V1001264	
Katana-C1 Finisher SR5000	B830	201008		B8304235	B8304236	SLIDER:BASE:STAPLER:ASS'Y	1	1	O/O		23	8					V1001421	10040794



Part Change Information List

Date: December 29, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Katana-C1 Finisher SR5000	B830	201012		B8305065	B8305066	PCB:MAIN CONTROL:ASS'Y	1	1	X/O		57	4					V1002385	10100089



Part Change Information List

Date: May 31, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Qty	New Qty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Katana-C1 Finisher SR5000	B830	201106	Cancel		B8302459	DISCHARGE BRUSH-STAPLE-EXIT-SHORT	0	2			35	23			No	This information was incorrect.	V1002226	10080952
Katana-C1 Finisher SR5000	B830	201106	Cancel		B8302458	DISCHARGE BRUSH-STAPLE-EXIT-LONG	0	4			36	24			No	This information was incorrect.	V1002226	10080952
Katana-C1 Finisher SR5000	B830	201106		B8305066	B8305067	PCB-MAIN CONTROL ASS'Y	1	1	X/O		57	4					V1100708	11020078



Part Change Information List

Date: August 31, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Katana-C1 Finisher SR5000	B830	201108		D4606211	D4606213	COVER:REAR	1	1	O/O		9	1					V0902426	09080801
Katana-C1 Finisher SR5000	B830	201108			B8304811	STAY:MIDDLE:SLIDE RAIL	0	1			15	19			RB830004		V1101123	



Part Change Information List

Date: June 29, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Qty	New Qty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Katana-C1 Finisher SR5000	B830	201111		AF022148	D4342551	EXIT ROLLER:DRIVEN:PROOF TRAY:ASS'Y	2	2	X/O		37	4	B		RB830005		V1102423	10120054
Katana-C1 Finisher SR5000	B830	201111		B8302225		PROOF TRAY GUIDE PLATE - LOWER	1	0	X/X		37	11	B		RB830005		V1102423	10120054
Katana-C1 Finisher SR5000	B830	201111		B8302202	B8302204	EXIT ROLLER:PROOF TRAY:ASS'Y	0	1	X/X		37	12	B		RB830005		V1102423	10120054
Katana-C1 Finisher SR5000	B830	201111		B4782243	B8302243	END PLATE:UPPER:EXIT:PROOF TRAY	1	1	X/O		37	19	B		RB830005		V1102423	10120054
Katana-C1 Finisher SR5000	B830	201111			B8302228	GUIDE PLATE:PROOF TRAY:LOWER	0	1			37	21	B		RB830005		V1102423	10120054
Katana-C1 Finisher SR5000	B830	201111			AA080237	BUSHING - 4X5X7	0	4			37	22	B		RB830005		V1102423	10120054
Katana-C1 Finisher SR5000	B830	201111			B3022229	BRACKET:EXIT ROLLER:PROOF TRAY	0	1			37	23	B		RB830005		V1102423	10120054
Katana-C1 Finisher SR5000	B830	201111			B8302203	SHAFT:EXIT ROLLER:PROOF TRAY	0	1			37	24	B		RB830005		V1102423	10120054
Katana-C1 Finisher SR5000	B830	201111			B8302227	GUIDE PLATE:PROOF TRAY:LOWER:SUB-ASS'Y	0	1			37	25	B		RB830005		V1102423	10120054
Katana-C1 Finisher SR5000	B830	201111			D4342577	ROLLER:EXIT ROLLER:PROOF TRAY	0	4			37	26	B		RB830005		V1102423	10120054
Katana-C1 Finisher SR5000	B830	201111		B8302324		EXIT ROLLER:DRIVEN	1	0	X/X		39	27	A		RB830005		V1102423	10120054
Katana-C1 Finisher SR5000	B830	201111		C3082324	D4342458	EXIT ROLLER:DRIVEN:SHIFT TRAY:ASS'Y	1	1	X/X		39	29	A		RB830005		V1102423	10120054
Katana-C1 Finisher SR5000	B830	201111		B8302302	D4342474	ROLLER:EXIT ROLLER:SHIFT	2	2	X/X		43	9			RB830005		V1102423	10120054



Part Change Information List

Date: June 29, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Katana-C1 Finisher SR5000	B830	201201		B4782243	B8302243	END PLATE:UPPER.EXIT.PROOF TRAY	1	1	X/O		37	19			RB830005		V1102905	
Katana-C1 Finisher SR5000	B830	201201	Cancel		B8303600	UNIFORM UNIT:ASS'Y	0	1			49	1			No	This information was incorrect.	V1102539	



Part Change Information List

Date: March 30, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Katana-C1 Finisher SR5000	B830	201203		B8305067	B8305068	PCB:MAIN CONTROL ASS'Y	1	1	X/O		57	4					V1200303	11121657



Part Change Information List

Date: July 31, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Katana-C1 Finisher SR5000	B830	201206		B8303600	B8303601	UNIFORM UNIT:ASS'Y	1	1	O/O		49	*			RB830006		V1200146	





Part Change Information List

Date: November 29, 2013

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Katana-C1 Finisher SR5000	B830	201302		B8305068	B8305069	PCB:MAIN CONTROL:ASS'Y	1	1	X/O		57	4					V1203500	12110799



Part Change Information List

Date: November 29, 2013

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set Int	RTB	Note	Ref Number	ECN Number
Katana-C1 Finisher SR5000	B830	201303		B8305285	D7075485	HARNESS:MOTOR:DRAWER:SUB-ASS'Y	1	1	X/O		57	8				V1203414	12112035
Katana-C1 Finisher SR5000	B830	201303		B8305249	D7075449	HARNESS:SENSOR:MAIN:SHIFT	1	1	X/O		57	11				V1203414	12112035



Part Change Information List

Date: June 28, 2013

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Katana-C1 Finisher SR5000	B830	201306		B8304235	B8304236	SLIDER:BASE:STAPLER:ASSY	1	1	O/O		23	8					V1203619	



Part Change Information List

Date: January 31, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Katana-C1 Finisher SR5000	B830	201401		B8307530	D7077530	BRACKET:COUPLING:ASS'Y	1	1	O/O		9	39					V1303737	13101911



Part Change Information List

Date: February 28, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Katana-C1 Finisher SR5000	B830	201402		B7063172	D4603172	ACTUATOR BRACKET	1	1	O/O		11	43					V1300600	13020357



Part Change Information List

Date: April 30, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Katana-C1 Finisher SR5000	B830	201404		B8303685	B8303694	JOGGER FENCE:INNER BACK:ASS'Y	1	1	X/O		49	25					V1400448	13100418
Katana-C1 Finisher SR5000	B830	201404		B8303680	B8303693	JOGGER FENCE:FRONT:ASS'Y	1	1	X/O		49	26					V1400448	13100418



Part Change Information List

Date: November 28, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Katana-C1 Finisher SR5000	B830	201411			B8304821	STAY:LOWER:SLIDE RAIL	0	1	O/O		14	19			Y		V1403157	
Katana-C1 Finisher SR5000	B830	201411			B8304252	STAY:STAPLER:MOVE	0	1	O/O		14	20			Y		V1403157	

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Katana-C1 Finisher SR5000	B830	201501		B8304125	B8304128	COMPRESSION SPRING:VIBRATING PLATE:MIDDLE	1	1	X/O		19	9					V1403408	14091170
Katana-C1 Finisher SR5000	B830	201501		B8302468	B8302460	COMPRESSION SPRING:DUPLEX STACK	2	2	X/O		33	1					V1403408	14091170



Part Change Information List

Date: February 27, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q' ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Katana-C1 Finisher SR5000	B830	201502			D7342039	GUIDE:PAPER:EH-17262	0	1			25	14			Y		V1500328	15010239
Katana-C1 Finisher SR5000	B830	201502		B7062224	B8302224	COMPRESSION SPRING:TRANSPORT:6.5N	4	4	X/O		29	8			Y		V1403408	14091170



Part Change Information List

Date: April 1, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Katana-C1 Finisher SR5000	B830	201503		AJ011023	AJ011036	STAPLER:EH-1200R10	1	1	O/O	N	25	8					V1403706	14111241



Part Change Information List

Date: July 2, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q' ty	New Q' ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Katana-C1 Finisher SR5000	B830	201506		B7062224	B8302224	COMPRESSION SPRING:TRANSPORT:6.5N	4	4	X/O	N	29	8					V1403673	



Part Change Information List

Date: December 2, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Katana-C1 Finisher SR5000	B830	201511		B8304252	B8304251	STAY:STAPLER:ASS'Y	1	1	X/O	N	14	20					V1500850	



Part Change Information List

Date: April 7, 2016

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Katana-C1 Finisher SR5000	B830	201603		B8303587	B8303588	BRACKET:DC STEPPER MOTOR:TRANSPORT:GATHERING ROLLER:ASS'Y	1	1	X/X	N	47	3	A	X/O	Y		V1503549	15110919
Katana-C1 Finisher SR5000	B830	201603		B8303520	B8303522	SHAFT:GATHERING ROLLER:DRIVE:ASS'Y	1	1	X/O	N	47	31	A	X/O	Y		V1503549	15110919



Part Change Information List

Date: October 4, 2016

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Katana-C1 Finisher SR5000	B830	201609		B8301554	D7071554	GEAR:Z30:PULLEY:20T	1	1	X/O	N	53	18			Y		V1602204	16031443