ിഫി	$J\Pi\Pi$
](K)(I	朏(

Modification **B**ulletin

	M odificat	tion t	3 ul	lletin		PAGE:	: 1/1
lodel: Model U-P1	Finisher		Date	e: 6-Nov-03		No.: MG314001	
lodified Article: P	arts Catalogue			Prepared	by: н.к	ζ.	
rom: 1st Tech. Sup	pport Sec. Service Support Dep	pt.					
eason for	□ Parts catalog correction	☐ Vend	or ch	ange	☐ To m	neet standards	
lodification:	☐ To facilitate assembly	☐ To im	prove	e reliability	()	
	☐ Part standardization	☐ Other					

P/N Correction

Please correct your parts catalogue as follows:

Incoorect	Correct part	Description	Q'ty	Int	Page	Index	Note
part number	number						
G3142124	G3143315	Lever Spring	1		11	14	

Model Name	V/Hz	Destination	Code	Serial Number
Ricoh SR780 Gestetner SR780	120,/220,230 ,240/50,60	USA, Europe, Asia,	G314-17	
Savin SR780 Lanier SR780		etc		
nasuatec SR780				
Rex-Rotary SR780				
infotec SR780	220,230,240/ 50,60	Europe	G314-26	

RICOH

Modification Bulletin

PAGE: 1/1

Model: Model U-P1 Finisher Dat			Date	te:7-Jul-06		No.: MG314002		
Modified Article: See below				Prepared by: H.K.				
From: Technical Se	rvice Dept., GTS Division							
Reason for	☐ Parts catalog correction	☐ Vend	dor ch	ange	☐ To meet standard			
Modification:	☐ To facilitate assembly	☐ To improve reliability		e reliability				
	☑ Part standardization	☐ Othe	r					

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G3020220	B4580220	ROLLER:FEED- OUT:ASS'Y	1	0/0	7	9	
G3020230	B4580230	ROLLER:FEED- OUT:ASS'Y	1	0/0	7	10	
G3021038	B4581038	STEPPER MOTOR BRACKET	1	0/0	7	32	
G3021041	B4581041	BRACKET - PAPER EXIT UNIT	1	0/0	9	11	
G3021054	B4581054	SHAFT:MM4	2	O/O	7	15	
					11	104	
G3021501	B4581501	PAN HEAD SCREW - 4X7	11	O/O	13	104	
G3021301				0,0	3	103	
					7	108	
C2021507	B4581507	SCREW - 2.3X12	1	0/0	7	104	
G3021507	D4301307	SCREW - 2.3X12	'	0/0	9	49	
					13	102	
G3021508	B4581508	TAPPING SCRER - 3X6	2	O/O	3	102	
					7	107	
G3021509	B4581509	PAN HEAD SCREW - 3X6	4	0/0	11	101	
G3021309	D4001009	FANTIEAD SCREW - 3X0	7	5,0	7	105	
G3141162	B4581162	HOLDER:FEED- OUT:FRONT	1	0/0	7	14	
G3142122	B4582122	GEAR - 85Z ASS'Y	1	0/0	11	13	

Change: The materials for these parts were changed. **Reason:** Parts standardization

Model Name	V/Hz	Destination	Code	Serial Number
Ricoh SR780	120,/220,230	USA,	G314-17	
Gestetner SR780	,240/50,60	Europe, Asia,		
Savin SR780		etc		
Lanier SR780				
nasuatec SR780				
Rex-Rotary SR780				
infotec SR780	220,230,240/	Europe	G314-26	
	50,60	-		

		\sim	ı
-			ı
	•		ı

Modification Bulletin

PAGE: 1/1

Model: Model U-P1 Finisher		Date: 23-May-08		18	No.: MG314003		
Modified Article: Tray Seal			Prepared by: H.K.				
From: 1st Tech. Sup	pport Sec. Service Support Dep	ot.					
Reason for	□ Parts catalog correction	☐ Vendor change		☐ To n	neet standards		
Modification:	☐ To facilitate assembly	To improve reliability ())			
	☐ Part standardization	☐ Othe	r				

Incorrect	Correct part	Description	Q'ty	Int	Page	Index	Note
part number	number						
G3141172	G3141186	Seal: Front: Tray	1-1		7	40	

Please correct your parts catalogue as shown above.