


IMPORTANT NOTE:

Do not hold this part when moving the product or removing it from its packaging.



CEA002

Holding this part can bend the entrance guide plate, or cause the connector for the sensor to become unplugged, which can lead to paper jams.

© 2010
Printed in China
EN 
B804-8802



B8048802