



Part Change Information List

Date: September 1, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Napa	J096	201707		J0974726		NEEDLE:151115	4	6		N	1	59					V1701176	17060861
Napa	J096	201707		J0974208		CABLE:MAINT-PCB:150597	2	4		N	1	94					V1701176	17060861
Napa	J096	201707		J0974382	J0974396	VALVE:PINCH VALVE ASSY	2	2	X/O	N	1	103					V1701176	17060861
Napa	J096	201707		J0974764		CABLE:151271	2	1		N	1	107					V1701176	17060861
Napa	J096	201707		J0974766		CABLE:151275	2	1		N	1	109					V1701176	17060861



Part Change Information List

Date: November 2, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Napa	J096	201710		J0973449		DAMPER UNIT:SUB HIGHCAPACITY:151311	3	6		N	-	-					V1701803	17091313



Part Change Information List

Date: November 2, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Napa	J096	201711		J0972803	J0972840	DC MOTOR:150294-SPCAR	1	1	X/O	N	-	-					V1701922	17100245
Napa	J096	201711		J0961080	J0971238	PCB:BBB_CAPE:51-20025-001:ASS'Y	1	1	X/O	N	-	-					V1701974	
Napa	J096	201711		J0974690	J0974660	TOUCH PANEL:ASS'Y	1	1	O/O	N	-	-					V1701922	17100245



Part Change Information List

Date: December 27, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Napa	J096	201712		J0974755	J0974758	CABLE:HDMI:HD-MA-MD-42:151277	1	1	X/O	N	-	-					V1702314	17111275
Napa	J096	201712		J0971103	J0971249	LASER:CLASS1:BLOCK:ASS'Y	1	1	X/O	N	-	-					V1702253	17101087
Napa	J096	201712		J0974660	J0974663	TOUCH PANEL:ASS'Y	1	1	X/O	N	-	-					V1702341	17111727



Part Change Information List

Date: February 1, 2018

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Napa	J096	201801		J0970270	J0970271	TRANSPORT SECTION:150880	1	1	O/O	N	-	-					V1702409	17120571
Napa	J096	201801		J0974354		TUBE:J_SHAPE_DOWN:151426:ASS'Y	2	4		N	-	-					V1702410	17120570
Napa	J096	201801		J0974352		TUBE:J_SHAPE_UP:151424:ASS'Y	2	4		N	-	-					V1702410	17120570



Part Change Information List

Date: April 2, 2018

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Napa	J096	201803		J0971249	J0971253	LASER;HOLDER;BRACKET;ASSY	1	1	X/O	N	-	-					V1800222	18020428
Napa	J096	201803		J0970051	J0970052	POWER SUPPLY UNIT;ASSY;151249	1	1	O/O	N	-	-					V1800207	18020140
Napa	J096	201803		J0970051	J0970052	POWER SUPPLY UNIT;ASSY;151249	1	1	X/O	N	-	-					V1800207	18020140



Part Change Information List

Date: April 26, 2018

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Napa	J096	201804		J0971238	J0965010	PCB:BBB_CAPE:51-20025-001:ASS'Y	1	1	X/O	N	-	-					V1800386	18030843
Napa	J096	201804		J0973487	J0975013	PCB:CAR_CTL:51-20003-001	1	1	X/O	N	-	-					V1800386	18030843
Napa	J096	201804		J0971170	J0975011	PCB:CAR_MOTION:51-20023-001	1	1	X/O	N	-	-					V1800386	18030843
Napa	J096	201804		J0972823	J0975012	PCB:TBL_MOTION:51-20023-002	1	1	X/O	N	-	-					V1800386	18030843
Napa	J096	201804		J0970271	J0970272	TRANSPORT SECTION:150880	1	1	X/O	N	-	-					V1800386	18030843



Part Change Information List

Date: August 3, 2018

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Napa	J096	201807		J0974658	J0974649	DEVELOPER SUPPLY NOZZLE:ASSY:151547	6	6	O/O	N							V1800694	18050281
Napa	J096	201807		J0974765	J0974666	LEVER SWITCH:COVER:UPPER:ASSY	1	1	X/O	N							V1800693	18050278
Napa	J096	201807		J0960410	J0960411	MAINTENANCE RECOVERY SECTION:151220	1	1	X/O	N							V1801255	18061160
Napa	J096	201807		J0974149	J0974148	SUPPORTER:VACUUM:CAP	3	3	X/O	N							V1801255	18061160
Napa	J096	201807		J0974663	J0974664	TOUCH PANEL:ASSY	1	1	X/O	N							V1800725	18050886

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Napa	J096	201808		J0965010	J0965014	PCB:BBB_CAPE:51-20025-001:ASS'Y	1	1	O/O	N							V1801466	18070798
Napa	J096	201808		J0965010	J0965014	PCB:BBB_CAPE:51-20025-001:ASS'Y	1	1	O/O	N							V1801466	18070798