Technical Bulletin

Reissued: 03-Aug-15

Model: Polaris-PJ1 XGA

Date: 12-Dec-14

No.: RY042001a

RTB Reissue

The items in bo	ld italics have been corre	ected.	
Subject: Firmwar	re Release Note: Main		Prepared by: T. Takahashi
From: VC Produc	ts Support Sect, Solution Sup	port Dept.	
Classification:	Troubleshooting	Part information	Action required
	🗌 Mechanical	Electrical	Service manual revision
	Paper path	Transmit/receive	Retrofit information
	Product Safety	Other (Firmware)	🛛 Tier 2

This RTB has been issued to announce the firmware release information for the Main.

Version	Program No.	Effective Date	Availability of RFU
B03	Y0435510A	May 2015 production	Not available
B02	Y0435510	1st Mass production	Not available

Note: Definition of Availability of RFU via @Remote

"Available": The firmware can be updated via RFU or SD card.

Version	Modified Points or Symptom Corrected
B03	1) Additional Model Information:
	N/A
	<i>2) Specification Change In standard picture mode, the brightness has been increased.</i>
	<i>3) Error Corrections: N/A</i>
B02	1st Mass production

Technical Bulletin

Reissued: 03-Aug-15

Model: Polaris-PJ1 WXGA

Date: 12-Dec-14

No.: RY042002a

RTB Reissue

The items in bold italics have been corrected.					
Subject: Firmwar	e Release Note: Main		Prepared by: T. Takahashi		
From: VC Produc	ts Support Sect, Solution Sup	port Dept.			
Classification:	Troubleshooting	Part information	Action required		
	🗌 Mechanical	Electrical	Service manual revision		
	Paper path	Transmit/receive	Retrofit information		
	Product Safety	🛛 Other (Firmware)	🛛 Tier 2		

This RTB has been issued to announce the firmware release information for the Main.

Version	Program No.	Effective Date	Availability of RFU
B03	Y0425510A	May 2015 production	Not available
B02	Y0425510	1st Mass production	Not available

Note: Definition of Availability of RFU via @Remote

"Available": The firmware can be updated via RFU or SD card.

Version	Modified Points or Symptom Corrected
B03	1) Additional Model Information:
	N/A
	2) Specification Change
	In standard picture mode, the brightness has been increased.
	3) Error Corrections:
	N/A
B02	1st Mass production

Technical Bulletin

Reissued: 03-Aug-15

Model: Polaris-PJ1 SVGA

Date: 12-Dec-14

No.: RY042003a

RTB Reissue

The items in bold italics have been corrected.					
Subject: Firmwar	e Release Note: Main		Prepared by: T. Takahashi		
From: VC Produc	ts Support Sect, Solution Sup	port Dept.			
Classification:	Troubleshooting	Part information	Action required		
	🗌 Mechanical	Electrical	Service manual revision		
	Paper path	Transmit/receive	Retrofit information		
	Product Safety	🛛 Other (Firmware)	🛛 Tier 2		

This RTB has been issued to announce the firmware release information for the Main.

Version	Program No.	Effective Date	Availability of RFU
B03	Y0445510A	May 2015 production	Not available
B02	Y0445510	1st Mass production	Not available

Note: Definition of Availability of RFU via @Remote

"Available": The firmware can be updated via RFU or SD card.

Version	Modified Points or Symptom Corrected
B03	1) Additional Model Information:
	N/A
	2) Specification Change
	In standard picture mode, the brightness has been increased.
	3) Error Corrections:
	N/A
B02	1st Mass production

Technical Bulletin

Reissued: 09-Mar-16

Model: Polaris-PJ1/Mizar-PJ1/Mimosa-PJ1/Hadar-PJ1

Date: 17-May-12

No.: RY020002e

RTB Reissue

	The items in bold italics have been corrected or added.	
--	--	--

Subject: Firmware Release Note: FW Update			Prepared by: T. Takahashi
From: VC Produc	ts Support Sect, Solution Sup		
Classification:	Troubleshooting	Part information	Action required
	🗌 Mechanical	Electrical	Service manual revision
	Paper path	Transmit/receive	Retrofit information
	Product Safety	Other (Firmware)	🖾 Tier 2

This RTB has been issued to announce the firmware release information for the **FW Update.**

Version	Program No.	Effective Date	Availability of RFU
12.6	Y0185511B	August 2014 production	Not available
10.3	Y0185511A	November 2012 production	Not available
9.2	Y0185511	May 2012 production	Not available

Note: Definition of Availability of RFU via @Remote

"Available": The firmware can be updated via RFU or SD card.

Version	Modified Points or Symptom Corrected						
12.6	Firmware modified to support the DDP 442X.						
	Additional Supported Model:						
	Polaris-PJ1/Mizar-PJ1/Mimosa-PJ1/ <i>Hadar-PJ1 CWU, Hadar-PJ1 CX</i>						
	Removed support for the following models:						
	Antares-PJ1 cs/Antares-PJ1 cw/Antares-PJ1 cx/Rigel-PJ1 cwH/ Rigel-PJ1 cwL/Rigel-PJ1 cxL						
10.3	NOTE:						
	 There is no functional difference between this version (v10.3) and the previous version, v9.2. This version was released in accordance with the modification made to the DLP Composer (which is not released). The FlashDeviceParameters.txt text file is provided as an attachment to this firmware release. 						
9.2	Initial release						

Technical Bulletin

PAGE: 1/1

Model: Polaris-PJ1 csi

Date: 18-Mar-15

No.: RY074001

Subject: Firmwar	e Release Note: Main	Prepared by: T. Takahashi	
From: VC Produc	ts Support Sect, Solution Sup		
Classification:	Troubleshooting	Part information	Action required
	Mechanical	Electrical	Service manual revision
	Paper path	Transmit/receive	Retrofit information
	Product Safety	🛛 Other (Firmware)	🖂 Tier 2

This RTB has been issued to announce the firmware release information for the Main.

Version	Program No.	Effective Date	Availability of RFU
B02	Y0745510	Initial release	Not available

Note: Definition of Availability of RFU via @Remote "Available": The firmware can be updated via RFU or SD card. "Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
B02	Initial release

Technical Bulletin

PAGE: 1/1

Model: Polaris-PJ1csi			Date: 22-Oct-15			No.: RY074002	
Subject: Added Parts Information for Polaris-PJ1csi				Prepared by: Toshiyuki Takahashi			
From: VC Products Support Section, Solution Supports Dept.							
Classification:	Mechanical Electronical Paper path Training		 Part information Electrical Transmit/receive Other (Action required Service manual revision Retrofit information Tier2 		

Change: The following parts were added.

Old Part Number	New Part Number	Description	Q'ty	Int	Page	Index	Note
-	Y0741250	COVER:IO:SVGA:51.8VH04H033	1	-	2	5	
-	Y0741255	SEAL:IO:3:INDIA:35.8YW01G021	1	-	2	6	
-	Y0743100	OPTICS:SECTIOM:70.8YW11GR01	1	-	4	6	
-	Y0745175	PCB:IO:PC-CONTROL:80.71506G001	1	-			
-	Y0746072	CD-ROM:INDIA:36.73002G012	1	-	2	18	
-	Y0746079	POWER SUPPLY CORD:INDIA:42.00181G011	1	-	2	17	

Reason: Service parts for the Polaris-PJ1csi (India market).