



Model: Capella-PJ1		Date: 18-Oct-16	No.: RY0AW001
Subject: The clamping bands		Prepared by: T. Sakakibara	
From: VC Tech Service Sect., MFP/Printer Tech Service Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Action required <input checked="" type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2

**There are four clamping bands inside the projector which cannot be used repeatedly.**



Model: Capella-PJ1

Date: 18-Oct-16

No.: RY0AW001

**① ② ③ : These bands fix the harnesses onto the top shielding. If you need to discard them, please remember the banding position, and fix the harnesses with new bands.**

**④ : Do not remove this band from the USB connector. Please keep it in the notch to prevent the connector from coming loose.**

Model: <b>Capella-PJ1 cw</b>	Date: 23-Feb-17	No.: RY0AW001
------------------------------	-----------------	---------------

Subject: Firmware Release Note: Main		Prepared by: T. Sakakibara	
From: VC Products Support Sec., Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **Main**.

Version	Program No.	Effective Date	Availability of RFU
B11.1C	Y0AW5510	1st release	Not Available

**Note: Definition of Availability of RFU via @Remote**

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
B11.1C	1st release

Model: **Capella-PJ1 cw / Capella-PJ1 cwu**

Date: 23-Feb-17

No.: RY0AW002

Subject: Firmware Release Note: LAN

Prepared by: T. Sakakibara

From: VC Products Support Sec., Solution Support Dept.

Classification:

☐ Troubleshooting

☐ Part information

☐ Action required

☐ Mechanical

☐ Electrical

☐ Service manual revision

☐ Paper path

☐ Transmit/receive

☐ Retrofit information

☐ Product Safety

☒ Other (Firmware)

☒ Tier 2

 This RTB has been issued to announce the firmware release information for the **LAN**.

Version	Program No.	Effective Date	Availability of RFU
A11	Y0AW5511	1st release	Not Available

**Note: Definition of Availability of RFU via @Remote**
**"Available":** The firmware can be updated via RFU or SD card.

**"Not available":** The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
A11	1st release

Model: <b>Capella-PJ1 cwu</b>	Date: 23-Feb-17	No.: RY0AW003
-------------------------------	-----------------	---------------

Subject: Firmware Release Note: Main		Prepared by: T. Sakakibara	
From: VC Products Support Sec., Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **Main**.

Version	Program No.	Effective Date	Availability of RFU
B11.1C	Y0AX5510	1st release	Not Available

**Note: Definition of Availability of RFU via @Remote**

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
B11.1C	1st release