



ange Information List

Date: March 1, 2018

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
CH-C1 Punch Unit PU3060	D706	201802		D7067500	D7067501	PUNCH UNIT.NA.CHANGE:ASS'Y	1	1	X/O	Y							V1500021	14120871
CH-C1 Punch Unit PU3060	D706	201802		D7067530	D7067531	PUNCH UNIT.NE.CHANGE:ASS'Y	1	1	X/O	Y							V1500021	14120871
CH-C1 Punch Unit PU3060	D706	201802		D7067011	D7067013	TONER HOPPER:ASS'Y	1	1	X/O	Y							V1500021	14120871



Part Change Information List

Date: April 2, 2018

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
CH-C1 Punch Unit PU3060	D706	201803			D6881000	STAY:PUNCH UNIT.SLIDE:ASS'Y	0	1		Y								

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
CH-C1 Punch Unit PU3060	D706	201811		AW020198	GW020024	PHOTOINTERRUPTOR:LG2A24BL1:GF	4	4	O/O	Y							V1801492	18070867