

Reissued: 16-Jun-15

Model: LCIT RT3030	Date: 26-Jun-13	No.: RD696001d
--------------------	-----------------	----------------

RTB Reissue

The items in ***bold italics*** have been corrected or added.

Subject: Firmware Release Note: LCIT RT3030		Prepared by: Y. Ino	
From: 1st Tech Service Sect., MFP/Printer Tech Service Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **LCIT RT3030**.

Version	Program No.	Effective Date	Availability of RFU
<i>01.810:11</i>	<i>D6965500G</i>	<i>July 2015 production</i>	<i>Not Available</i>
01.800:11	D6965500F	March 2015 production	Not Available
01.780:11	D6965500E	March 2014 production	Not Available
01.770:11	D6965500D	December 2013 production	Not Available
01.760:11	D6965500C	1st Mass production	Not Available

Note: Definition of Availability of RFU via @Remote
"Available": The firmware can be updated via RFU or SD card.

"Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
<i>01.810:11</i>	<i>Specification Change:</i> - <i>Supports a maximum paper stack height of 165mm.</i>
01.800:11	Symptom corrected: The paper feed tray might not be able to handle 1500 sheets of plain paper.
01.780:11	Symptom corrected: "No paper" is displayed even though there is still some paper remaining.
01.770:11	Symptom corrected: SC622 occurs and the machine reboots automatically if paper is fed from Tray 3.
01.760:11	1st Mass production