#### Modification Bulletin

Model: CARIB-B (	Duplex Unit1000) for S-P1	e: 9-Jul-08		No.: MG176002									
Modified Article:	Interface Harness for Paper Fe	1	Prepared by: Y.Yoshida										
From: 1st Technical Support Sec. Service Support Dept.													
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vend ☑ To im ☐ Other	prov	ange e reliability	□ To n	neet standards )							
Modification Schedule:													

Old Part	New Part	Description	Q'ty	Int	Page	Index	Note
Number	Number	·					
G3612800	G8932777	TIMING BELT:30S2M286	1→1	X/O	9	5	
G5527217	G8932775	PULLEY:HORIZONTAL	3→3	X/O	0	4	
	G0932113	TRANSPORT (outside)	ე→ე	7	9	4	
l-	G8932778	PULLEY:HORIZONTAL	3→3	X/O	0	1	
	G0932110	TRANSPORT:RIGHT (inside)	ე→ე	7	9	4	

#### Change:

1) The width of the timing belts was reduced from 4mm to 3mm.

Note: The attachment position of the belts was reversed (see the photo below).

2) Due to this change, the pulley was separated into two service parts.

**Reason:** To ensure that the timing belt does not touch the machine frame.

Important: If you install the new parts on machines produced before the cut-in serial


number, attach the belt in its **original position** (left illustration).


Do not reverse the positions of the belts. This is because the frame was

modified to accommodate the new parts.

Cut-in Serial number: S0989200734

**Before** the cut-in (original belt position):





**PAGE: 1/1** 



## **Part Change Information List**

Date: December 29, 2009

Model	Code	PCIL Nr.	PCIL	Old part	New part		Description	Old Q'ty	New Q'ty	Int	3DPC Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
	Code	I OIL IVI.	Correction	number	number		Description	Old Q ty	INCW Q Ly	1111	obi o i age	IIIdex .	OCI	Oct IIIt		Note		LON INI.
S-P2 Duplex Unit (AD1000)	G893	200912		G8935100	G8935110	PCB:DPX:ASS'Y		1	1	X/O	7	10					V0902910	9100652

**RICOH** 

# **Part Change Information List**

Date: February 26, 2010

Model	Code	PCIL Nr.	PCIL	Old part	New part	Description	Old O'ty	New O'tv	Int	3DPC Pa	ae Inde	ex Set	Set Int	RTB	Note	Ref Nr	ECN Nr.
		I OIL I II.	Correction	number	number	Description	Old Gily	non aty		0010 14	go ma	, OU	0011111	1115	11010	1101.111.	_011111.
S-P2 Duplex Unit (AD1000)	G893	201002		G3612810	G8932810 FEELER:SENSOR		1	1	X/O		9	6		Υ		V0902911	9101145



### **Part Change Information List**

Date: Aug 31, 2010

Model		Code	PCIL Nr.	PCIL	Old part	New part	Description	Old O't	New Q'tv	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Nr	ECN Nr.
Wiodei		0000	. 0.2	Correctio	number	number	20001.011	0.0 0.1	HOW QU		02. 0	. ago	cox		000	5			20111111
S-P2 Duplex Unit (AD100	0)	3893	201008		G3605700	AX040243	STEPPER MOTOR:MM42		2	2 X/O		5	12	2				V1000884	